INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u> Documentation format for Archaeological / Heritage Sites / Monuments

## Serial No.: OR/CTC- 64

	SECTION I : IDENTIFICATION		
1. Name			
Present Past Other Name (if any):		ole, Dhavalesvara Siva Temple Manchesvar, Dist Cuttack	
2. Location			
<b>LONGITUDE</b> 85 <sup>0</sup> 48 <sup>°</sup> 12 <sup>°</sup> E	<b>LATITUDE</b> 20 <sup>0</sup> 30 <sup>'</sup> 15 <sup>"</sup> N	ELEVATION 80 feet	
Address	: Village (village code) Post : Manchesvar Tehsil: Athgarh State : Orissa	Anantakuda, Manchesvar Via: Chasapada District: Cuttack PIN: 754002	
Approach	: The temple, within the compound of Dhavalesvara Siva temple is on a tiny island, locally known as Anantakuda in the river Mahanadi and situated on the left side of N.H - 42 leading from Cuttack to Dhenkanal branching at a distance of 4 kms from Nuapatana chowk. A flying bridge connects the village Manchesvar and the island.		
3. Property Type			
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public building         Residential building	Religious structures         Y       Temple         Mosque	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure		Note:	
Bridge Tunnel Other engineering structure	Park or garden	The temple has a <i>pidha vimana</i> of impoverished <i>Kalingan</i> order.	

4. Property Use						
	ABANDONED / IN USE : In use					
Present	: Living temple, the presiding deity is a brass Naga over a square <i>yonipitha</i> , made of black chlorite.					
Past	: Worshipped					
5. Age (Source)						
PERIOD	: In the princely rule of ex-state of Athgarh.					
YEARS	: 19 <sup>th</sup> century A.D.					
Precise date of Construction	: Last part of the 19 <sup>th</sup> century A.D.					
Completion	:					
Subsequent changes	:					
Destruction / Demolition	:					
6. Ownership / Level of Protection	n					
	SINGLE /MULTIPLE : Multiple					
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Endowment Department, Government of Orissa.					
Private	·					
Any other (Please specify)	Dhavalesvara Mandira Parichalana Committee					
Name	:					
Address						
Phone	:					
7. Association						
WITH EVENTS						
In History	:					
In Rituals	: Sivaratir, Kartika Purnima, etc are observed here.					
In Building Construction	:					
Any other (specify)	:					
WITH PERSONS						
Patron	: Endowment Department, Government of Orissa.					
Architect / Engineer	:					
Any other (specify)	: Dhavalesvara Mandira Parichalana Committee					
8. Statement of Significance						
Architectural	: 🗸 Architectural					
Archaeological	: 🗸 Archaeological					
Historical	:					
Religious	. ✓ Religious					
Any other (specify)	: On the basis of architectural feature and the sculptures					
	attached on the exterior walls, the temple can be dated to the last part of the 19 <sup>th</sup> century A.D.					

# **SECTION II: DESCRIPTION**

<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	* <b>Drawings (</b> Attach extra sheet if necessary) : N Located in an isla	
g-		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex
Quantification Area Dimension (L x B x H)	:	4.35 mtrs x 4.35 mtrs x 8.00 mtrs	
Number of Blocks Number of Storys	:	One. 	( <b>m</b> / cm/ feet / inch)
• <b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	Facing towards west. The <i>vimana</i> is square on plan. 10.00 mtrs (L) x 8.00 mtrs (W)	
ARCHITECTURAL STYLE			
Ornamentation Exteriors	:	Images such as- Yogapatta Narasimha, Narasimha Varaha, Visnu, Siva, two-armed female deity, Warrio	
Interiors	:	(02 nos) are fixed on the outer wal Plain	li of the temple.
Movable Collections *Any Other (specify)	:	<ul> <li>Nil</li> <li>The temple has plain <i>bada</i> in elevation and has five tiers <i>pidha</i> roof.</li> </ul>	
10. Construction Technology			
Structural System Building Techniques Material of Construction	:	<ul> <li><i>Pidha vimana</i> of impoverished <i>Kalingan</i> order.</li> <li>Ashlar masonry</li> <li>Sandstone is used for the construction of temple and the exterior surface is plastered and white washed.</li> </ul>	
11. Condition Assessment			
In General Good / Fair	:	Fair	
<ul> <li>Sign of Deterioration</li> <li>Serious Deterioration</li> <li>Danger of Disappearance</li> </ul>			

## In Brief (Attach extra sheet if necessary):

Visitors inscribe their names on the exterior surface of the temple.

### 12. Threats to the Property



## **SECTION III:** REFERENCES

### 13. Reference Sources (published and unpublished textual details)

- 1. ---
- 2.

### 14. Photographs: 11 nos

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	

#### 17. Listers

NAME :	Jaya Shankar Naik	NAME :	
18. Reviewers	6		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	