

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / CTC - 76

SECTION I : IDENTIFICATION		
1. Name	<u>ocononi</u> . Identii loanon	
Present Past Other Name (if any): 2. Location	: Suvarnesvara Mahadeva: Dist Cuttack::	Temple, Suvarnapur,
LONGITUDE 85° 36′ 33″ E	LATITUDE 20° 26′ 11″ N	ELEVATION 121 feet
Address	: Village (village code) Post : Suvarnapur Tehsil: Banki State : Orissa	Suvarnapur Via: Athgarh District: Cuttack PIN: 754029
Approach	Narasingpur road branch from Anshupa chowk. It is	n the left side of Athgarhing at a distance of 8 kms situated on the left bank of 0.5 kms from the sweet lake Athgarh.
3. Property Type		······································
Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Wall Gateway Pillar Others (specify)
Engineering structure	structures	te:
Bridge Tunnel Other engineering structure	Public square Th Park or garden vir Graveyard bh	e temple has a <i>pidha</i> nana, nandimandapa and a ogamandapa of poverished <i>Kalingan</i> order.

4. Property Use		
4. I Toperty Ose		ABANDONED / IN USE: In use
Present Past	:	It is a living temple and the presiding deity is a Sivalinga within a circular <i>yonipitha</i> . Worshipped
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : :	Suryavamsi Gajapati rule 16 th century A.D
o. Ownership / Level of Frotection	<u>/11</u>	SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private Any other (Please specify) Name	: : :	Local people
Address Phone	:	At/Po- Suvarnapur, Dist- Cuttack, Orissa

7. Association

•	WIT	HE\	/FN	PT
•	vvii	\Box		113

In History : --

In Rituals : Sivaratri, Kartika Purnima, etc are observed here.

In Building Construction : --

Any other (specify) : Thread ceremony is held here.

WITH PERSONS

Patron : Local people

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

J	
Architectural	: ✓ Architectural
Archaeological	:
Historical	:
Religious	: ✓ Religious
Any other (specify)	: On the basis of architectural feature the temple can be dated to the 16 th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context *Drawings (Attach extra sheet if necessary): No

Urban / Rural Setting : Rural setting

Surroundings

Stand in Isolation

Integral part of a Landscape Complex

/ Street / Complex :

Quantification

Area Dimension ($L \times B \times H$) : 13.30 mtrs \times 8.50 mtrs \times 10.20 mtrs (approximate

height)

(m / cm/ feet / inch)

Number of Blocks : Three Number of Storys : N.A.

• Spatial Organization

Orientation : Facing towards west

Plan : The *vimana* and *bhogamandapa* are square on plan

whereas the *nandimandapa* is rectangular on plan.

Allocation of Spaces : 19.60 mtrs (L) x 29.55 mtrs (W)

ARCHITECTURAL STYLE

Ornamentation

Exteriorsmn : It is devoid of sculptural embellishment. The

architectural motifs are khakharamundis and pidhamundis in the talajangha and uparajangha respectively. The pabhaga has five mouldings, bandhana has three mouldings and varanda has seven mouldings. A pair of udyotasimha is represented at each raha, dopichhasimhas and beki-bhairava over the beki. The parsvadevata includes four-armed

Parvati, Kartikeya and Ganesa.

Interiors : Plain

Movable Collections : Udyotasimha, votive khakhara temple, nandi and

architectural fragments.

* Any Other (specify) : Nisha shrines are added to the temple in latter period.

It is pancharatha on plan and panchangabada in elevation. The doorjambs of the vimana are relieved with four-fold mouldings such as lata, dalamankudi, puspa and beaded border along with Gajalaxmi at the

lalata bimba and dvarapalas at the base.

10. Construction Technology

Structural System : *Pidha* structure of impoverished *Kalingan* order.

Building Techniques : Ashlar masonry

Material of Construction : Sandstone and lime plaster.

11. Condition	n Assessment		
In General	Good / Fair	:	Fair
Serious I	Deterioration Deterioration of Disappearance		
In Brief (Atta	ch extra sheet if ne	ecess	sary):
	nen are found on the ater and flood water		face of the temple. During rainy season it is submerged
12. Threats to	the Property		
x x x x x x ;	x	X X X	Natural Negligence Vandalism Urban Pressures X X X X X X X X X X X X X X X X X X X
<i>XXXXXX</i>		,,,,	
	<u>S</u>	ECT	ION III: REFERENCES
13. Reference	e Sources (publishe	ed an	d unpublished textual details)
1. R. P. Mo	hapatra, 1986, <i>Arch</i>	aeolo	ogy in Orissa, Vol-II, Delhi
14. Photogra	phs: 33 nos		
			(attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	ence	:	
15. Audio / V	ideo		
			(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO	N	:	
16. Maps/Pla	ns/Drawings		
17. Listers			
NAME:	A. R. Sahoo		NAME:
18. Reviewer	s		
NAME: COMMENTS	Dr. S. Pradhan		NAME: COMMENTS: