

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/DKL-19

SECTION I: IDENTIFICATION			
1. Name			
Present  Past Other Name (if any):  2. Location	<ul> <li>: Kanakesvara Siva Temple (Astasmbhu Complex), Kualo, Dist Dhenkanal</li> <li>:</li> <li>:</li> </ul>		
<b>LONGITUDE</b> 85° 17′ 54″ E	LATITUDE 20° 56′ 57″ N ELEVATION 240 ft		
Address	: Village (village code) Post: Kualo Tehsil: Parajangh State: Orissa  Kualo (Ward.No-2) Via: Parajangh District: Dhenkanal PIN: 759120		
Approach	: It is located on the left bank of river Brahmani and about 10 kms east of Talcher town. It can be approached by a motorable road branching from Janata chowk on NH-23 and is about 2 kms north of it.		
3. Property Type			
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  ✓ Temple  Mosque  Minar  Church  Monastery  Stupa  Tomb, Mausoleum  Other Structures  Wall  Gateway  Pillar  Others (specify)		
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave  Note:  The temple is of the panchayatana class though the jagamohana and corner shrines have collapsed, the traces of pillars of the jagamohana and the subsidiary shrines do exist in a dilapidated condition. The temple is of an early rekha style of Kalingan order.		

## 4. Property Use

ABANDONED / IN USE: In use

Present : It is a living shrine, and the presiding deity is a

Sivalinga made of chlorite within a high circular sand

stone yonipitha.

Past : Worshipped.

5. Age (Source)

**PERIOD** : Sulkis (the feudatories of Bhaumakaras)

**YEARS** : 9<sup>th</sup> century A.D.

**Precise date of Construction**: First half of the 9<sup>th</sup> century A.D.

Completion : -

Subsequent changes : Conserved and Renovated by Archaeological Survey

of India.

Destruction / Demolition : ---

6. Ownership / Level of Protection

**SINGLE /MULTIPLE:** Multiple

**Public**: Archaeological Survey of : Protected monument of Archaeological Survey of India

India / State Archaeology Department / Any Other (Please

specify)

Private : --

Any other (Please specify) : Astasambhu Mandira Parichalana Committee

Name :

Address : Bhubaneswar Circle, 153, VIP Area, Nayapalli,

Bhubaneswar, Pin - 751015

Phone : 0674-2558170

7. Association

WITH EVENTS

In History : --

In Rituals : Sivaratri, Kartikapurnima, etc are observed.

In Building Construction :

Any other (specify) : Thread Ceremony, Engagement and Marriage

WITH PERSONS

Patron : Originally Sulkis, but presently under the care of

Archaeological Survey of India.

Architect / Engineer : ---

Any other (specify)

8. Statement of Significance

Architectural
Archaeological
Historical
Religious

Architectural
Archaeological

Religious

Architectural
Archaeological

Religious

Any other (specify)

It is the central shrine of the Panchayatana temple complex. On the basis of architectural style and sculptural embellishments, the temple can be dated to the 9<sup>th</sup> century AD.

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features

Context

**Urban / Rural Setting** 

Surroundings

\* **Drawings** (Attach extra sheet if necessary): No

Rural setting

Stand in Isolation Integral part of a Landscape

/ Street / Complex :

Quantification

9.60 mtrs X 9.60 mtrs x 12.00 mtrs Area Dimension (LxBxH)

(m / cm/ feet / inch)

Complex

Number of Blocks Two Number of Storys

Spatial Organization

Orientation The temple is facing towards east.

Plan The vimana is square on plan where as the jagamohana is

rectangular on plan

Allocation of Spaces 50.00 mtrs X 30.00mtrs in length and breadth respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors The exterior of the temple is decorated with images of God

> Goddess viz. Parvati, Ganesa, Bhairava. Ardhanariswara, Mahisasuramardini Durga etc. Other architectural motifs include chaitya medallions, vajramundi,

elephant friezes, lion, amorous couple and scroll work.

Interiors Plain

Movable Collections architectural members of a temple

\* Any Other (specify) The temple is triratha on plan and triangabada on

elevation. The gandi portion has lost its architectural

surface and the core stones are only visible.

10. Construction Technology

Structural System Rekha vimana and originally pillared has a

jagamohana which is now missing.

**Building Techniques** Ashlar dry masonry.

**Material of Construction** Sand stone.

11. Condition As	ssessment	
In General G	Good / Fair :	Good
Sign of Dete Serious Dete Danger of D		
In Brief (Attach	extra sheet if necess	ary):
The temple is we	ell conserved by Archae	eological Survey of India.
12. Threats to th	ne Property	
		Natural Negligence Vandalism Urban Pressures
x x x x x x x x x	<pre></pre>	× × × × × × × × × × × × × × × × × × ×
	SECT	ION III: REFERENCES
13. Reference S	ources (published and	d unpublished textual details)
		nple Art of Orissa, Vol. I, Leiden. Igy in Orissa, Vol. II, New Delhi.
14. Photographs	s: 12 nos	
		(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION 15. Audio / Vide	:	
	•	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION 16. Maps/Plans/	: : Drawings	
17. Listers		
NAME:	A. R. Sahoo	NAME:
18.Reviewers		
NAME: D COMMENTS	r. S. Pradhan	NAME: COMMENTS: