

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/DKL-11

SECTION I: IDENTIFICATION				
1. Name				
Present Past Other Name (if any): 2. Location	: Narayana Temple, CTemple Complex, Kapilas::	handrasekhara Mahadeva Hillock, Dist Dhenkanal		
LONGITUDE 85°45'48" E	LATITUDE 20 ⁰ 40 ['] 54 ["] N	ELEVATION 1550 feet		
Address	: Village (village code) Post : Deogaon Tehsil: Gondia State : Orissa	Kapilas Hillock, Deogaon Via: Gondia District: Dhenkanal PIN: 759016		
Approach 3. Property Type	main shrine Chandrasek complex and in the mid	e of 50.00 mtrs east of the chara Mahadeva within the ddle terrace of the Kapilas distance of 17 kms from the village Deogaon.		
Buildings	Delinieus etwietuwes	Othor Structures		
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure		ote:		
Bridge Tunnel Other engineering structure		nas a single <i>rekha vimana</i> of <i>llingan</i> order.		

4. Property Use				
		ABANDONED / IN USE: In use		
Present	:	It is a living temple and the presiding deity is a four-		
Past	:	armed Visnu made of chlorite. Worshipped		
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	During the princely rule of ex- state of Dhenkanal 18 th century A.D The temple is now covered with lime plaster		
6. Ownership / Level of Protection	<u>on</u>	OINOLE MALILITIDLE . Markingle		
		SINGLE /MULTIPLE : Multiple		
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Archaeological Survey of India and under Endowment Department, Government of Orissa.		
Private	:			
Any other (Please specify)	:			
Name	:	C: I C		
Address Phone	:	Archaeological Survey of India, Bhubaneswar Circle, 153 VIP Area, Nayapalli, Bhubaneswar, Orissa 0674-2558170		
7. Association				
WITH EVENTS				
In History	:	Narayan Singhdeo, the rular of ex- princely state of		
•		Dhenkanal built this temple		
In Rituals	:	Dola purnima, Janmastami etc. are observed here.		
In Building Construction Any other (specify)	:			
WITH PERSONS	•			
Patron	:	Archeological Survey of India.		
Architect / Engineer	:			
Any other (specify)	:	Endowment Department, Government of Orissa.		
8. Statement of Significance				
Architectural Archaeological Historical Religious Any other (specify)	: : : : :	Architectural Religious On the basis of architectural feature, iconographical details of the sculpture & local traditions, the temple can be dated to the 18 th century AD.		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	*Drawings (Attach extra sheet if necessary): No Kapilas Hillock		
Gurroundings		Stand in Isolation Integral part of a Landscape Complex / Street / Complex :		
 Quantification Area Dimension (L x B x H) 	:	4.30 mtrs x 4.70 mtrs x 7.40 mtrs (m / cm/ feet / inch)		
Number of Blocks Number of Storys	: :	One		
Spatial Organization Orientation Plan	:	It is facing towards west. The <i>vimana</i> is square on plan with a shallow porch measuring 0.40 mtrs in length which stands over a low <i>pista</i> measuring 0.55 mtrs in height.		
Allocation of Spaces	:	5.00 mtrs (L) x 5.00 mtrs (W)		
ARCHITECTURAL STYLEOrnamentation				
Exteriors	:	The temple is devoid of sculptural embellishment, except the <i>parsvadevata</i> images like- Varaha, Narasimha & Trivikram. Architectural motifs like <i>khakharamundis</i> and <i>pidhamundis</i> in the <i>talajangha</i> and <i>uparajangha</i> respectively, angasikharas surmounted by <i>udyotasimha</i> in each <i>raha, dopichhasimhas</i> & <i>beki</i> -bhairava over the beki are found.		
Interiors Movable Collections	:	Plain Nil		
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan & <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System Building Techniques Material of Construction	:	Rekha vimana of Kalingan order. Ashlary masonry with lime plaster. Khandolite.		
11. Condition Assessment				
In General Good / Fair	:	Fair		
Sign of Deterioration Serious Deterioration Danger of Disappearance				

In Brief (Attac	th extra sheet if neces	ssary):			
Moss and liche	en are noticed over the	temple.			
12. Threats to	the Property				
		Natural Negligence Vandalism Urban Pressures			
X X X X X X X X X X X X X X X X X X X					
	SEC	TION III: REFERENCES			
13. Reference Sources (published and unpublished textual details)					
1. R. P. Moh 2.	apatra, 1986, <i>Archaeo</i>	logy in Orissa, Vol. II, New Delhi.			
14. Photograp	ohs: 12 nos				
		(attach list as in page 6, in case of multiple photographs)			
Photo Reference CAPTION	nce :				
15. Audio / Vi	deo				
		(related to rituals / performance / festivals etc.)			
Reference DESCRIPTION	N :				
16. Maps/Plans/Drawings					
17. Listers					
NAME:	A. R. Sahoo	NAME:			
18. Reviewers)				
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:			