

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / DKL-12

SECTION I : IDENTIFICATION  1. Name				
Present  Past Other Name (if any):	: Parvati Temple, Chandra Complex, Kapilas Hillock, :	isekhara Mahadeva Temple Dist Dhenkanal		
LONGITUDE 85° 45′ 48″ E	<b>LATITUDE</b> 20° 40′ 54″ N	ELEVATION 1512 feet		
Address	: Village (village code) Post : Deogaon Tehsil: Gondia State : Orissa	Kapilas Hillock, Deogaon Via: Gondia District: Dhenkanal PIN: 759016		
Approach	main shrine Chandrasek complex and in the mid	e of 10.00 mtrs south of the thara Mahadeva within the ddle terrace of the Kapilas distance of 17 kms from the village Deogaon.		
3. Property Type				
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures    Wall   Gateway   Pillar   Others (specify)		
Engineering structure  Bridge Tunnel Other engineering structure	structures  Public square  Park or garden  Graveyard  Baolis, Well  The	e temple has a <i>pidha vimana</i> impoverished <i>Kalingan</i> der. To approach the temple 52 steps are provided from e foot hill.		

4. Property Use	
	ABANDONED / IN USE: In use
Present Past	<ul> <li>Living temple, the presiding deity is goddess Mahisasuramardini Durga, made of black chlorite.</li> <li>Worshipped</li> </ul>
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: Ganga rule : 13 <sup>th</sup> century A.D. : : :
6. Ownership / Level of Protection	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone 7. Association	<ul> <li>SINGLE /MULTIPLE: Multiple</li> <li>Protected monument of Archaeological Survey of India and under Endowment Department, Government of Orissa.</li> <li></li> <li></li> <li>Archaeological Survey of India, Bhubaneswar Circle, 153 VIP Area, Nayapalli, Bhubaneswar, Orissa</li> <li>0674-2558170</li> </ul>
<ul> <li>WITH EVENTS In History In Rituals</li> <li>In Building Construction Any other (specify)</li> <li>WITH PERSONS Patron Architect / Engineer Any other (specify)</li> <li>Statement of Significance</li> </ul>	<ul> <li>Ganga dynasty of Orissa</li> <li>Durga puja, Kartika Purnima, Dola Purnima etc. are observed here.</li> <li></li> <li>Marriage, thread ceremony engagements are held here.</li> <li>Archaeological Survey of India</li> <li></li> <li>Endowment Department, Government of Orissa.</li> </ul>
Architectural Archaeological Historical Religious Any other (specify)	: ✓ Architectural :
	deity, the original temple can be assigned to the 13 <sup>th</sup> century AD i.e. the Ganga rule in Orissa.

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features				
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	*Drawings (Attach extra sheet if necessary): No Hillock		
· ·		Stand in Isolation Integral part of a Landscape Complex / Street / Complex :		
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	:	4.25 mtrs x 4.25 mtrs x 6.00 mtrs (approximate height) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	One N.A.		
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul> ARCHITECTURAL STYLE	:	Facing towards south. The <i>vimana</i> is square on plan 25.75 mtrs (L) x 21.00 mtrs (W)		
Ornamentation     Exteriors  Interiors  Movable Collections	:	Decorated with architectural motifs like deulacharinis and dopichhasimhas over the beki to support the amlasila and projecting lions on the third tier of the gandi. Plain		
* Any Other (specify)	:	The temple is <i>triratha</i> on plan and <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System Building Techniques Material of Construction	: :	Pidha vimana of impoverished Kalingan order. Ashlar dry masonry Khandolite stone is used for the construction of the temple and lime plaster and white wash applied over the temple.		
11. Condition Assessment				
In General Good / Fair	:	Good		
Sign of Deterioration Serious Deterioration Danger of Disappearance				

In Brief (Attac	ch extra sheet if necessary	y):		
The temple is	in a good state of preservat	ion.		
12. Threats to	the Property			
	✓ N	latural legligence ⁄andalism Jrban Pressures		
XXXXXXX	(	x x x x x x x x x x x x x x x x x x x		
SECTION III: REFERENCES				
13. Reference	Sources (published and u	inpublished textual details)		
1. R. P. Mol 2.	napatra, 1986, <i>Archaeology</i>	in Orissa, Vol II, New Delhi.		
14. Photogra				
	(a	ttach list as in page 6, in case of multiple photographs)		
Photo Refere CAPTION	nce :			
15. Audio / Vi	deo			
Reference DESCRIPTION 16. Maps/Plan		(related to rituals / performance / festivals etc.)		
<u> </u>	<u> </u>			
17. Listers				
NAME :	Jaya Shankar Naik	NAME:		
18. Reviewers	5			
NAME: COMMENTS	Dr. Sadasiba Pradhan	NAME: COMMENTS:		