

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/DKL-06

SECTION I : IDENTIFICATION				
1. Name				
Present	: Siddhesvara Temple, Gangadhara Prasad, Dist Dhenkanal			
Past Other Name (if any):	: : Uttaresvara Temple			
2. Location				
LONGITUDE 85° 31′ 53″ E	LATITUDE 20° 31′ 53″ N ELEVATION 158 feet			
Address	: Village (village code) Post: Kamadhenukot Tehsil: Dhenkanal State: Orissa Gangadhara Prasada Via: Bhapur District: Dhenkanal PIN: 759015			
Approach	: The temple is located on the right side of the road leading from Athgarh to Hindol and situated on the left bank of the river Sapua. It is about 14 kms away from Athgarh.			
3. Property Type	. 3			
Buildings	Religious structures Other Structures			
Palace Fort	✓ Temple Wall Mosque Gateway			
Citadel	Mosque Gateway Minar Pillar			
Govt. building	Church Others (specify)			
Railway station	Monastery			
Defence building	Stupa			
Industrial building	Tomb, Mausoleum			
Other public buildings				
Residential building				
Engineering structure	Open space and related Note:			
Bridge	structures Public square The temple has a rekha			
Tunnel	Park or garden vimana of early Kalingan order.			
Other engineering structure				
	Baolis, Well			
	Tank Cave			

4. Property Use	
	ABANDONED / IN USE: In use
Present	: Living temple, the presiding deity is a <i>Patalaphuta</i> Sivalinga within a circular <i>yonipitha</i> .
Past	: Worshipped
E Ago (Source)	
5. Age (Source)	
PERIOD	: Bhaumakara rule
YEARS	: 8 th century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	: Renovated and conserved by Orissa State Archaeology.
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Protected monument of Orissa State Archaeology and under Endowment Department, Government of Orissa.
Private	·
Any other (Please specify)	:
Name	:
Address	: Orissa State Archaeology, Paryatan Bhawan, B.J.B.
Phone	Nagar, Bhubaneswar, Orissa : 0674-2432147
7. Association	
WITH EVENTS	
In History	:
In Rituals	: Sivaratri, Kartika Purnima, etc are observed here.
In Building Construction	:
Any other (specify)	:
 WITH PERSONS 	
Patron	: Orissa State Archaeology
Architect / Engineer	:
Any other (specify)	: Endowment Department, Government of Orissa.
8. Statement of Significance	
Architectural	: 🗸 Architectural
Archaeological	:
Historical	: <u> </u>
Religious	:
Any other (specify)	: On architectural ground and iconographical features the

On architectural ground and iconographical features the temple can be assigned to the 8^{th} century AD i.e. the Bhaumakara rule in Orissa.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
 Context Urban / Rural Setting Surroundings 	:	*Drawings (Attach extra sheet if r	necessary) : No Rural setting		
3		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex		
 Quantification Area Dimension (L x B x H) 	:	3.25 mtrs x 3.25 mtrs x 8.00 mtrs	(m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	One N.A.	(III / CIII/ leet / IIICII)		
 Spatial Organization Orientation Plan Allocation of Spaces 	: :	Facing towards east. The <i>vimana</i> is square on plan 35.00 mtrs (L) x 20.00 mtrs (W)			
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	Decorated with <i>vajramundi</i> nic miniature <i>chaitya</i> motifs enshrini center on the <i>gandi</i> , <i>astagraha</i> p the frontal <i>raha</i> has a double <i>chai</i> Uma-Mahesvara <i>murty</i> in the Nataraja on the top circle. Plain Architectural fragments The temple is <i>triratha</i> on plan elevation. Astagraha panel is ca and <i>Akasalinga</i> on the top of the temple to the stagrama of the stagrama in the stagrama of the top of the temple is the stagrama of	ng kirtimukha in the anel in the lintel and tya medallion houses lower and dancing and triangabada in rved out in the lintel		
10. Construction Technology					
Structural System Building Techniques Material of Construction	:	Rekha vimana of early Kalingan o Ashlary dry masonry Khandolite stone	rder.		
11. Condition Assessment					
In General Good / Fair	:	Fair			
Sign of Deterioration Serious Deterioration Danger of Disappearance					

In Brief (Attach extra sheet if necessary):

Growth of vegetation is found on the *gandi* of the frontal wall and around the temple complex. As the temple is 2.50 mtrs below the present ground level and the surrounding agricultural field the temple is submerged under water up to the lintel level during rainy season which may weaken the structure in long run.

12. Threats to	the Property	
	✓ Ne	atural egligence andalism ban Pressures
x x x x x x x	x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	SECTION	I III: REFERENCES
13. Reference	Sources (published and ur	published textual details)
1. R. P. Moh 2.	napatra, 1986, <i>Archaeology i</i>	in Orissa, Vol II, New Delhi.
14. Photograp		
	(at	tach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	nce :	
15. Audio / Vi	deo	
Reference DESCRIPTION	: N :	(related to rituals / performance / festivals etc.)
16. Maps/Plar	ns/Drawings	
17. Listers		
NAME:	Jaya Shankar Naik	NAME:
18. Reviewers	3	
NAME: COMMENTS	Dr. Sadasiba Pradhan	NAME: COMMENTS: