

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/DKL-07

1. Name	SECTION I: IDENTIFICATION
Present	: Somanatha Temple, Gangadhara Prasad, Dist Dhenkanal
Past Other Name (if any):	: :
2. Location	
LONGITUDE 85° 31′ 53″ E	LATITUDE 20 ⁰ 31 ¹ 53 ³ N ELEVATION 158 feet
Address	: Village (village code) Post: Kamadhenukot Tehsil: Dhenkanal State: Orissa Gangadhara Prasada Via: Bhapur District: Dhenkanal PIN: 759015
Approach 3. Property Type	: The temple is located on the right side of the road leading from Athgarh to Hindol and situated on the left bank of the river Sapua. It is about 14 kms away from Athgarh.
. , , ,	
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Open space and related Structures The temple is in dilapidated condition and only the base along with the western wall remain.

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deity is a <i>Patalaphuta</i> Sivalinga within a circular <i>yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD YEARS	:	Bhaumakara rule 8 th century A.D.
Precise date of Construction Completion Subsequent changes	:	
Destruction / Demolition	:	Except the base and the western wall the temple has completely collapsed
6. Ownership / Level of Protection	on	
·		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Orissa State Archaeology and under Endowment Department, Government of Orissa.
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	Orissa State Archaeology, Paryatan Bhawan, B.J.B.
Phone	:	Nagar, Bhubaneswar, Orissa 0674-2432147
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Kartika Purnima, etc are observed here.
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS Petrop		Origon Chata Arabagalagu
Patron	:	Orissa State Archaeology.
Architect / Engineer Any other (specify)	:	Endowment Department, Government of Orissa.
8. Statement of Significance	•	
		Arabitactural
Architectural Archaeological		✓ Architectural ✓ Archaeological
Historical	: 1	
Religious	:	

Any other (specify) SE	: <u>CT</u>	On architectural plan and the surviving decorative features, the temple can be assigned to the 8 th century AD i.e. the Bhaumakara rule in Orissa. ION II: DESCRIPTION			
9. Physical Description and Decorative Features					
 Context Urban / Rural Setting Surroundings 	:	*Drawings (Attach extra sheet if necessary): No Rural setting			
		Stand in Isolation Integral part of a Landscape / Street / Complex :			
• Quantification Area Dimension (L x B x H)	:	2.25 mtrs x 2.25 mtrs x 1.75 mtrs (existing height) (m / cm/ feet / inch)			
Number of Blocks Number of Storys	:	One N.A.			
 Spatial Organization Orientation Plan Allocation of Spaces 	: : :	Facing towards east. The <i>vimana</i> is square on plan 35.00 mtrs (L) x 20.00 mtrs (W)			
ARCHITECTURAL STYLEOrnamentation					
Exteriors Interiors Movable Collections * Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	The surviving portion of the temple is decorated with miniature <i>chaitya</i> motifs Plain Architectural fragments The base remains of the temple shows that it was <i>triratha</i> on plan			
10. Construction Technology					
Structural System Building Techniques Material of Construction	: : : : : : : : : : : : : : : : : : : :	The surviving remains shows that it was a <i>rekha vimana</i> of early <i>Kalingan</i> order. Ashlary dry masonry Khandolite stone			
11. Condition Assessment					
In General Good / Fair	:				
✓ Sign of Deterioration✓ Serious Deterioration✓ Danger of Disappearance					

In Brief (Attach extra sheet if necessary):

Growth of vegetation is found around the temple complex and water stagnates in the sanctum

during rainy season.

12. Threats to	the Property				
	✓ Na	atural			
		egligence			
		andalism			
	Ur	ban Pressures			
x x x x x x x	x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x			
SECTION III: REFERENCES					
13. Reference	Sources (published and ur	published textual details)			
1. R. P. Moh 2.	apatra, 1986, <i>Archaeology i</i>	in Orissa, Vol II, New Delhi.			
14. Photograp					
	(at	tach list as in page 6, in case of multiple photographs)			
Photo Referei	nce :				
CAPTION	:				
15. Audio / Vi	deo				
		(related to rituals / performance / festivals etc.)			
Reference	:				
DESCRIPTION	N :				
16. Maps/Plan	s/Drawings				
17. Listers					
NAME :	Jaya Shankar Naik	NAME:			
18. Reviewers	3				
NAME: COMMENTS	Dr. Sadasiba Pradhan	NAME: COMMENTS:			