

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/ DKL- 14

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Yanjesvara Temple, Kh : :	naragprasad, Dist Dhenkanal
LONGITUDE 85° 19 10 E	LATITUDE 20 ⁰ 49 ¹ 10 ⁷ N	ELEVATION 170 foot
LONGITUDE 85 19 10 E	LATITUDE 20 ⁰ 49 10 N	ELEVATION 172 feet
Address	: Village (village code) Post : Kharagprasad Tehsil: Dhenkanal State : Orissa	Kharagprasad Via: Meramandali District: Dhenkanal PIN: 759121
Approach	leading from Dhenkan kms branching at Mas	I on the right side of N.H- 42 al to Angul, at a distance of 3 ani chowk. It is situated on the Brahmani and it is about 42 kms
3. Property Type	nom 2 nomanar tomi.	
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The temple has a rekha vimana and a pidha jagamohana of impoverished Kalingan order.

4. Property Use			
		ABANDONED / IN USE: In use	
Present	:	Living temple, the presiding deity is a Sivalinga within a square <i>yonipitha</i> .	
Past 5. Age (Source)	:	Worshipped	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : :	During the princely rule of ex- state of Dhenkanal 19 th century A.D A RCC <i>mandapa</i> has been added in front of temple in later on	
		SINGLE /MULTIPLE : Multiple	
India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Orissa State Archaeology and under Endowment Department, Government of Orissa.	
Private Any other (Please specify) Name Address Phone	:	Yanjesvara Temple Committee Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa 0674-2432147	
7. Association			
WITH EVENTS In History In Rituals In Building Construction Any other (specify)	: : : : :	Sivaratri, Kartika Purnima, Rakhi Purnima, etc are observed here Marriage, thread ceremony, engagements, etc are	
WITH PERSONS Patron Architect / Engineer Any other (specify)	:	performed here. Orissa state Archaeology Endowment Department, Government of Orissa.	
8. Statement of Significance	•	, , , , , , , , , , , , , , , , , , , ,	
Architectural		✓ Architectural	

Architectural		✓ Architectural
Archaeological	:	
Historical	:	
Religious	:	
Any other (specify)	:	On the basis of the architectural features and local tradition, the temple can be dated to the last part of the 19 th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
 Context Urban / Rural Setting Surroundings 	:	*Drawings (Attach extra sheet if necessary): No Rural setting
Garroundings		Stand in Isolation Integral part of a Landscape Street / Street / Complex :
 Quantification 		
Area Dimension (LxBxH)	:	11.70 mtrs. x 5.60 mtrs x 11.00 mtrs (approximate height)
		(m / cm/ feet / inch)
Number of Blocks Number of Storys	:	Three (vimana, jagamohana, RCC mandapa) N.A.
Spatial Organization		
Orientation	:	Facing towards east.
Plan	:	The vimana and jagamohana are square on plan that
Allocation of Spaces	:	stands over a low platform. 15.00 mtrs (L) x 18.00 mtrs. (W)
ARCHITECTURAL STYLE		
 Ornamentation 		
Exteriors	:	Devoid of any decoration, except dopichhasimhas and deulacharinis over the beki and udyotasimha on each raha.
Interiors	:	Plain
Movable Collections	:	Nil
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation.
10. Construction Technology		
Structural System	:	Rekha vimana and pidha jagamohana of impoverished
Building Techniques		Kalingan order. Ashlar masonry with lime mortar.
Material of Construction	:	Stone is used for the construction of temple and the
		entire surface is cement plastered and colour washed.
11. Condition Assessment		
In General Good / Fair		Good
30110141 3004 / 1 411	•	
Sign of Deterioration		
Serious Deterioration		
Danger of Disappearance		

In Brief (Attac	ch extra sheet if necess	ary):
	in a good state of preserventers	vation.
		Natural Negligence Vandalism Urban Pressures
XXXXXXX	< x x x x x x x x x x x x	××××××××××××××××××××××××××××××××××××××
	SECTI	ON III: REFERENCES
13. Reference	e Sources (published and	l unpublished textual details)
1		
14. Photogra	phs: 33 nos	
		(attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	nce :	
15. Audio / Vi	deo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO	N :	
16. Maps/Pla	ns/Drawings	
17. Listers		
NAME:	Jaya Shankar Naik	NAME:
18. Reviewers	s	
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: