

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR/GJM-02 **SECTION I: IDENTIFICATION** 1. Name Present Balunkesvara Siva Temple, Nrusinghanatha Mahadeva Temple Complex, Baragaon, Dist. - Ganjam **Past** Other Name (if any): 2. Location **LONGITUDE** 84<sup>0</sup> 41' 00" E 19<sup>0</sup> 53' 52" N LATITUDE **ELEVATION** 262 ft **Address** Village (village code) Baragaon Post: Baragaon Via: Bellaguntha **Tehsil:** Bhanjanagar District: Ganjam State: Orissa PIN: 761119 Approach The temple, on the western side of Nrusinghanatha Mahadeva temple complex in the village Baragaon is located on the right side of the road leading from Nayagarh to Baliguda and 5 kms east of Bellaguntha. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify): Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Note. Residential building The temple has a rekha temple of early Kalingan order. Engineering structure Open space and related structures Bridge Public square Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deity is a Sivalinga with in a circular <i>yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Bhaumakara rule
YEARS	:	8 <sup>th</sup> century A.D.
Precise date of Construction Completion	:	
Subsequent changes	:	It was conserved by Orissa State Archaeology under
		X & XI Finance Commission Award.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology	:	Protected monument of Orissa State Archaeology and under Endowment Department, Government of Orissa.
Department / Any Other (Please specify)  Private		
Any other (Please specify)	:	Nrusinghanatha Mandira Parichalana Committee under the presidentship of Subash Rana.
Name	:	
Address	:	Orissa State Archaeology, Paryatan Bhawan, B.J.B.
Phone	:	Nagar, Bhubaneswar, Orissa 0674 2432147
7. Association		
<ul> <li>WITH EVENTS</li> </ul>		
In History	:	All ii I I I I I I I I I I I I I I I I I
In Rituals	:	All rituals related to the Saivite cult such as <i>Sivaratri, Kartika Purnima</i> , etc are observed here.
In Building Construction Any other (specify)	:	Marriage, thread ceremony, engagement, etc.
Patron	:	Orissa State Archaeology and now Endowment Department, Government of Orissa.
Architect / Engineer Any other (specify)	:	Nrusinghanatha Mandira Parichalana Committee
8. Statement of Significance		
Architectural Archaeological Historical Religious	: [	✓ Architectural ✓ Archaeological

Any other (specify)	:	on the basis of architectural features sculptures, the temple can be assign period i. e. the 8 <sup>th</sup> century A.D.	0 . ,	
9. Physical Description and D		TION II: DESCRIPTION		
Context     Urban / Rural Setting     Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Rural setting		
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex	
• Quantification Area Dimension ( L x B x H)	:	2.60 mtrs x 2.60 mtrs x 5.33 mtrs	(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	One N.A.	(III / GIII/ IGGE / IIIGII)	
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul>	: : :	Facing towards east. The temple is square on plan. 37.20 mtrs (L) x 25.40 mtrs (B)		
<ul><li>ARCHITECTURAL STYLE</li><li>Ornamentation</li><li>Exteriors</li></ul>	:	parsvadevata niches enshrined Kartikeya and an eight-armed	gha portion. The deity like Ganesa,	
Interiors	:	Durga. Plain		

10. Construction Technology

Movable Collections

\* Any Other (specify)

**Structural System** : Rekha vimana of early Kalingan order.

Nandi

elevation.

: The temple is triratha on plan and triangabada in

Building Techniques : Ashlar dry masonry

Material of Construction : Coarse grained sandstone.

11. Condition Assessment

In General	Good / Fair	:	Good			
Serious	Deterioration Deterioration of Disappearance					

In Brief (Attac	h extra sheet if nece	ssary):
The temple is i	n a good state of pres	ervation.
12. Threats to	the Property	
V V V V V V V		Natural Negligence Vandalism Urban Pressures
	SEC	TION III: REFERENCES
13. Reference	Sources (published a	and unpublished textual details)
1. R.P.Moha 2.	patra, 1986, <i>Archaeol</i>	ogy in Orissa, Vol. sss- I, New Delhi.
14. Photograp	hs: 09 nos	
<u> </u>		(attach list as in page 6, in case of multiple photographs)
Photo Referer CAPTION	ice	
15. Audio / Vid	deo	
Reference DESCRIPTION 16. Maps/Plan		(related to rituals / performance / festivals etc.)
17. Listers		
NAME :	B.B.Satpathy	NAME:
	Dr. S. Pradhan	NAME .
NAME:	DI. S. Plauliali	NAME:

**COMMENTS:** 

COMMENTS