

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/ GJM- 06

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	 Biranchi-Narayana Temple, Buguda Town, Dist Ganjam
2. Location	
LONGITUDE 84 ⁰ 47' 39" E	LATITUDE 19 ⁰ 48' 32" N ELEVATION 302 ft
Address	: Village (village code) Post : Buguda Town Tehsil: Buguda Town State : Orissa Buguda Town (Badadanda Sahi) Via: Buguda Town District: Ganjam PIN: 761118
Approach	: The temple is located in the Badadanda sahi of Buguda town which is ½ km south-west of Palasara chowk.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building	Religious structures Other Structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify): Monastery Stupa Tomb, Mausoleum
Other public buildings	Note.
Residential building	The temple is famous for it
Engineering structure	Open space and relatedwoodcarvingsandwastructurespaintingsbasedonKrisnalila
Bridge Tunnel Other engineering structure	Public square Ramayana, ten incarnation of Park or garden Visnu, Kanchiabhijana, etc. Graveyard Baolis, Well Tank Cave

		ABANDONED / IN USE : In use
Present	:	Living temple, the enshrining deity is a two-armed Surya standing on a chariort kept over a platform.
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	During the rule of the Bhanjas of ex- Ghumsar state.
YEARS	:	18 th century A.D.
Precise date of Construction	:	1790 A.D.
Completion Subsequent changes	÷	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Orissa State Archaeology an Endowment Department, Government of Orissa.
Private	:	
Any other (Please specify)	:	Under the care of Ravi Narayan Das, the Mahanta of the temple.
Name	:	
Address	:	Orissa State Archaeology, Paryatan Bhawan, B.J.E Nagar, Bhubaneswar, Orissa
Phone	:	0674 2432147
7. Association		
WITH EVENTS		
In History	:	The temple records says that Raja Srikara Bhanja c ex- Ghumsar state built this temple
In Rituals	:	Sambadasami, Makara Sankranti, Magha Saptam Ramnavami, Janmastam, etc are observed.
In Building Construction	:	
Any other (specify)	:	Thread ceremony is held here.
WITH PERSONS Patron	:	Orissa State Archaeology and Endowmer Department, Government of Orissa
Architect / Engineer	:	
Any other (specify)	:	Ravi Narayan Das, the Mahanta of the temple.
8. Statement of Significance		
Architectural	:	✓ Architectural
Archaeological	:	
Historical Religious	:	 ✓ Historical ✓ Religious
Any other (specify)	:	On the basis of temple records, the temple is ascribed to the
		last quarter of the 18 th century A.D.

SECTION II: DESCRIPTION

Context		* Drawings (Attach extra sheet if necessary)		
Urban / Rural Setting	:	Urban setting		
Surroundings		Stand in Isolation Integral part of a Landscape / C Street / Complex :	Complex	
Quantification				
Area Dimension (L x B x H)	:	22.40 mtrs x 22.00 mtrs x 12.80 mtrs (m / cm/	feet / incl	
Number of Blocks Number of Storys	:	Three		
Spatial Organization				
Orientation Plan	:	Facing towards west. Chariot like plan.		
Allocation of Spaces	:	43.00 mtrs (L) x 51.00mtrs (W)		
ARCHITECTURAL STYLE				
Ornamentation				
Exteriors	:	Decorated with paintings mostly based on Ramayana themes all over the <i>bada</i> portion. T subject matters are scenes of Sita-vivaha, Bali vad Setubandha-nirmana, Mayamirga-vadha, Ran Ravana yudha, etc; Krisnalila, and the incarnation Visnu and the most interesting is the plan of Jagannatha temple within the Sankhakhetra (Puri).		
Interiors	:	Decorated with paintings and wood carving Vaisnavite cult.		
Movable Collections	:			
* Any Other (specify)	:			
10. Construction Technology				
Structural System	:	Chariot like structure, looks like a plus	sign (Lat	
Building Techniques		cross) mark on plan. Ashlar masonry		
Material of Construction	:	Khandolite stone and lime plaster		
11. Condition Assessment				
In General Good / Fair	:	Fair		
 Sign of Deterioration Serious Deterioration Danger of Disappearance 				

In Brief (Attach extra sheet if necessary):

Seepage of rainwater during rainy season, which obliterated the paintings as well as the wood members used in the eave of the temple.

12. Threats to the Property

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. R.P.Mohapatra, 1986, Archaeology in Orissa, Vol. - I, New Delhi.

2.

14. Photographs: 73 nos

x :	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	

17. Listers

NAME :	D.B.Garnayak	NAME :	
18. Reviewer	S		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	