

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR/ GJM- 19

	SECTION I: IDENTIFICATION	
1. Name		
Present Past Other Name (if any): 2. Location	: Guptesvara Siva Temple : :	e, Raulapali, Dist Ganjam
Z. Location		
<b>LONGITUDE</b> 84 <sup>0</sup> 48' 48" E	<b>LATITUDE</b> 19 <sup>0</sup> 29' 48" N	<b>ELEVATION</b> 152 ft
Address  Approach		Raulapali Via: Pandia District: Ganjam PIN: 761043  n the top of a granite hillock in ituated at a distance of 3 kms
3. Property Type		ndia and 5 kms from Jaugada,
Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building Railway station Defence building Industrial building	Temple	Wall Gateway Pillar Others (specify):
Other public buildings	Tomb, Mausoleum	Note.
Residential building		The temple is designed under a
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave	big granite boulder. The main shrine or the presiding deity is kept inside the boulder with additional structure like jagamohana and a pillared mandapa.

4.	Pro	pe	rty	Use
----	-----	----	-----	-----

ABANDONED / IN USE: In use

Present : Living temple, enshrining a Sivalinga within a circular

yonipitha.

Past : Worshipped

#### 5. Age (Source)

PERIOD	:	During the Bhanja rule of ex-Ghumsar state.
YEARS	:	19 <sup>th</sup> century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

#### 6. Ownership / Level of Protection

**SINGLE /MULTIPLE :** Multiple

**Public**: Archaeological Survey of : Endowment Department, Government of Orissa.

India / State Archaeology Department / Any Other (Please

specify)

Private : --

Any other (Please specify) : Temple Managing Trust

Name : --Address : --Phone : ---

#### 7. Association

WITH EVENTS

In History :

In Rituals : Sivaratri, Kartika Purnima etc are observed here.

In Building Construction : --

**Any other (specify)** : Marriage, thread ceremony, etc are observed here.

WITH PERSONS

Patron : Presently the Endowment Department, Government

of Orissa and the Temple Managing Trust.

Architect / Engineer : --Any other (specify) : ---

#### 8. Statement of Significance

Architectural	: 🗸 Architectural
Archaeological	:
Historical	:
Religious	:
Any other (specify)	: On the basis of architectural design of the <i>jagamohana</i> and frontal <i>mandapa</i> , the temple can be dated to the 19 <sup>th</sup> centur

A.D.

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features		
• Context Urban / Rural Setting : Surroundings	* Drawings (Attach extra sheet if necessary) : No Rural setting	
Carroundings	Stand in Isolation Integral part of a Landscape / Complex Street / Complex:	
Quantification		
Area Dimension ( L x B x H) :	21.00 mtrs x 7.00 mtrs x 8.50 mtrs (approximate height)	
Number of Blocks :	(m / cm/ feet / inch) Three, consists of a natural cave used as <i>vimana</i> , a pidha jagamohana and a flat-roofed opened pillared mandapa.	
Number of Storys :		
• Spatial Organization Orientation : Plan :	Facing towards east.  The <i>vimana</i> is a natural cavern whereas the <i>jagamohana</i> and <i>mandapa</i> are square and rectangular	
Allocation of Spaces :	on plan respectively. 20.00 mtrs (L) x 35.00 mtrs (W)	
ARCHITECTURAL STYLE		
<ul> <li>Ornamentation</li> </ul>		
Exteriors :	Plain	
Interiors :	Plain	
Movable Collections :	Four-armed Visnu image, Kartikeya etc.	
* Any Other (specify)	<del></del>	
10. Construction Technology		
Structural System :	The <i>vimana</i> is a natural cavern whereas the <i>jagamohana</i> and <i>mandapa</i> are <i>pidha</i> and flat-roofed respectively.	
<b>Building Techniques</b> :	Ashlar masonry	
Material of Construction	Granite stone and cement plaster.	
11. Condition Assessment		
In General Good / Fair :	Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation.

12. Threats to	the Property	
x		Natural Negligence Vandalism Urban Pressures XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
	<u>3</u>	CHON III. REI ERENGES
13. Reference	Sources (publishe	and unpublished textual details)
1 2.		
14. Photograp	ohs: 12 nos	
		(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	nce	: :
15. Audio / Vi	deo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION		: :
16. Maps/Plan	ns/Drawings	
17. Listers		
NAME: 18. Reviewers	D.B.Garnayak	NAME:
NAME :	Dr. S. Pradhan	NAME :
COMMENTS	DI. S. Flauliali	COMMENTS: