

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/GJM-03

SECTION I : IDENTIFICATION			
1. Name			
Present	: Ladukesvara Siva Temple, Nrusinghanatha Mahadeva Temple Complex, Baragaon, Dist Ganjam		
Past Other Name (if any):	: :		
2. Location			
LONGITUDE 84 ⁰ 41' 00" E	LATITUDE 19 ⁰ 53' 52" N ELEVATION 262 ft		
Address	: Village (village code) Baragaon Post : Baragaon Via: Bellaguntha Tehsil: Bhanjanagar District: Ganjam State : Orissa PIN: 761119		
Approach	: The temple, on the south-western corner of Nrusinghanatha Mahadeva temple complex in the village Baragaon is located on the right side of the road leading from Nayagarh to Baliguda and 5 kms east of Bellaguntha.		

3. Property Type

Buildings	Religious structures	Other Structures					
Palace	✓ Temple	Wall					
Fort	Mosque	Gateway					
Citadel	Minar	Pillar					
Govt. building	Church	Others (specify):					
Railway station	Monastery						
Defence building	Stupa						
Industrial building	Tomb, Mausoleum						
Other public buildings		Note.					
Residential building							
		It is a <i>rekha</i> temple of early					
Engineering structure	Open space and related	<i>Kalingan</i> order.					
structures							
Bridge	Public square						
Tunnel	Park or garden						
Other engineering structure	Graveyard						

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Living temple, enshrining a Sivalinga within a circula yonipitha.
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Bhaumakara rule
YEARS	:	8 th century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	It was conserved by Orissa State Archaeology unde X & XI Finance Commission Award.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Orissa State Archaeology an under Endowment Department, Government of Orissa
Private	:	
Any other (Please specify)	:	Nrusinghanatha Mandira Parichalana Committe under the presidentship of Subash Rana.
Name	:	
Address	:	Orissa State Archaeology, Paryatan Bhawan, B.J.E Nagar, Bhubaneswar, Orissa
Phone	:	0674 2432147
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	All rituals related to the Saivite cult such as <i>Sivarati Kartika Purnima</i> , etc are observed here.
In Building Construction	:	
Any other (specify)WITH PERSONS	:	Marriage, thread ceremony, engagement, etc.
Patron	:	Originally the Bhaumakaras, but now under the care of Orissa State Archaeology.
Architect / Engineer	:	
Any other (specify)	:	Nrusinghanatha Mandira Parichalana Committee
8. Statement of Significance		
Architectural	:	✓ Architectural
Archaeological	:	✓ Archaeological
Historical	:	
Religious Any other (specify)	÷	On the basis of the plan and prohitectural style, the terms
	•	On the basis of the plan and architectural style, the templ can be dated to the Bhaumakara period i. e. the 8 th centur A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : : Rural sett		
Carrounanigo		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex	
• Quantification Area Dimension (L x B x H)	:	2.60 mtrs x 2.45 mtrs x 5.00 mtrs		
Number of Blocks Number of Storys	:	One N.A.	(m / cm/ feet / inch)	
• Spatial Organization Orientation Plan	:	 Facing towards north. The <i>vimana</i> is square on plan that stands over a <i>pist</i> of 0.29 mtrs high. 37.20 mtrs (L) x 25.40mtrs (B) 		
Allocation of Spaces	:			
ARCHITECTURAL STYLE • Ornamentation Exteriors	:	The temple is devoid of sculptural embellishment except the <i>parsvadevata</i> images. The <i>gandi</i> is carved with horizontal <i>bhumi</i> mouldings and <i>bhumi-amla</i> in the <i>kanika paga</i> . The architectural motifs like- vajramundis in the <i>rahapagas</i> are in incipient condition.		
Interiors Movable Collections * Any Other (specify)	:	Plain The temple is <i>triratha</i> on plan elevation with peculiarity of <i>p</i> housing Kartikeya, Lakulisa & Bha	arsvadevata niches	
10. Construction Technology				
Structural System Building Techniques	:	<i>Rekha vimana</i> of early <i>Kalingan</i> of Ashlar dry masonry	rder.	

Coarse grey sandstone.

:

11. Condition Assessment

Material of Construction

In General Good / Fair : Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Due to the renovation work done by Orissa State Archaeology, the temple is in a good state of preservation.

12. Threats to the Property

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. R.P.Mohapatra, 1986, Archaeology in Orissa, Vol.- I, New Delhi.

2.

14. Photographs: 07 nos

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	:
16. Maps/Plans/Drawings	

17. Listers

NAME :	D.B.Garnayak	NAME :	
18. Reviewer	S		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	