

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR/ GJM- 20

SECTION I : IDENTIFICATION			
1. Name			
Present Past Other Name (if any): 2. Location	: Tara-Tarini Temple, Rai : :	ipura, Dist Ganjam	
<b>LONGITUDE</b> 84 <sup>0</sup> 53' 59" E	<b>LATITUDE</b> 19 <sup>0</sup> 29' 19" N	ELEVATION 620 ft	
Address	: Village (village code) Post : Raipura Tehsil: Purushottampu State : Orissa	Raipura  Via: Purushottampur  Ir District: Ganjam  PIN: 761018	
Approach	Raipura is located on	mmit of a hillock in the village the right bank of the river 7 kms east of Purushottampur rhampur.	
3. Property Type			
Buildings  Palace Fort Citadel Govt. building Railway station Defence building	Religious structures  ✓ Temple  Mosque  Minar  Church  Monastery  Stupa  Tomb Mausoloum	Other Structures  Wall Gateway Pillar Others (specify):	
Industrial building Other public buildings	Tomb, Mausoleum	Note.	
Residential building			
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave	The place has now achieved tremendous popularity for worship of the twin goddesses Tara and Tarini. Both the deities are crudely fashioned in stone attached with silver eyes. Several traditional legends, current at this place, connect the deities with Sakta religion.	

## 4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the enshrining deities are twin images of goddess Durga locally worshiped as Tara & Tarini. **Past** Worshipped 5. Age (Source) Originally the enshrining deity was installed by the **PERIOD** Bhanja ruler of the ex-Ghumsar state. **YEARS** 19<sup>th</sup> century AD. **Precise date of Construction** Completion Subsequent changes The original structure was demolished in 2005 and a new temple is under construction. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of: Endowment Department, Government of Orissa State Archaeology / Department / Any Other (Please specify) **Private** Tara Tarini Development Board Any other (Please specify) Name Address Phone 7. Association WITH EVENTS In History Chaitra Purnima, Durga Puja, etc are held here. In Rituals In Building Construction Any other (specify) WITH PERSONS **Patron** Endowment Department, Government of Orissa **Architect / Engineer** Any other (specify) Tara Tarini Development Board 8. Statement of Significance Architectural Architectural

Archaeological

On the basis of the iconographical feature of the deities, the original temple can be dated to the early part of the 19<sup>th</sup>

✓ Religious

century A.D.

Archaeological

Any other (specify)

Historical Religious

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features				
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	* Drawings (Attach extra sheet if necessary): No Rural setting		
Carroundings		Stand in Isolation Integral part of a Landscape / Stand in isolation Street / Complex :		
Quantification  Area Dimension ( L x B x H)		30.00 mtrs x 12.60 mtrs x under construction		
Alea Dimension ( L X B X H)	•	(m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	Three		
Spatial Organization				
Orientation Plan	:	Facing towards east.  The <i>vimana</i> , <i>jagamohana</i> and frontal <i>mandapa</i> are square on plan that stands over a high platform.		
Allocation of Spaces	•	67.00 mtrs x 19.60 mtrs in length and breadth respectively.		
ARCHITECTURAL STYLE  • Ornamentation				
Exteriors	:	Decorated with pilaster design on the <i>pagas</i> of all the components and 275 images are under construction to insert in the recess of the temple.		
Interiors Movable Collections	:	Plain		
* Any Other (specify)	:	The temple is <i>saptaratha</i> on plan and <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System	:	Rekha vimana, pidha jagamohana and a frontal mandapa of impoverished Kalingan order.		
Building Techniques Material of Construction	:	Ashlar masonry Khandolite stone		
11. Condition Assessment				
In General Good / Fair	:	Good		
Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet if nec	ess	ary):		

The temple is in a good state of preservation.

12. Threats to	the Property			
		Natural		
		Negligence		
		Vandalism		
		Urban Pressures		
x x x x x x x	x x x x x x x x x x x x			
	<u>SECT</u>	ION III: REFERENCES		
13. Reference Sources (published and unpublished textual details)				
	patra, 1986, <i>Archaeolog</i>	y in Orissa, VolI, Delhi.		
2.				
3.				
4.				
14. Photograp	hs: 53 nos			
		(attach list as in page 6, in case of multiple photographs)		
Photo Referen	ice .			
CAPTION	:			
15. Audio / Vid	deo			
		(related to rituals / performance / festivals etc.)		
Reference	:			
DESCRIPTION	:			
40 M (D)	(D			
16. Maps/Plan	s/Drawings			
17. Listers				
NAME:	D. B. Garnayak	NAME:		
18. Reviewers	<u> </u>			
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:		