

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/ JSP- 23

SECTION I: IDENTIFICATION		
1. Name		
Present:KhandPast:Other Name (if any)::2. Location:	esvara Siva Temple, Nasik, Jagatsinghpur	
LONGITUDE 86°15'16"E LATITUDE	20 ⁰ 15'04" N ELEVATION 28 ft	
Post: Tehsil	e (village code) Nasik Kotian Via: Kodapada : Tirtol District: Jagatsinghpur : Orissa PIN: 754106	
north-e Machh	tuated in the outskirt of the Nasik village, 11 km east of Dihasahi chowk in the Jagatsinghpur – nagaon road and 5 kms north of Kantara. It can o approached from the right side of Tirtol-Dihasai	
3. Property Type		
Palace ✓ Temple Fort Mosque Citadel Minar Govt. building Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mau	Wall Gateway Pillar Others (specify)	
Other public buildings	Note:	
Residential building Engineering structure Open space al structures Bridge Public squa Tunnel Park or gar Other engineering structure Graveyard Baolis, Wel Cave	den impoverished <i>Kalingan</i> style. The temple is constructed over an ancient ruined temple.	

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Living temple, enshrining a Circular <i>yonipitha</i> , the ling is missing.
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	The Original temple was built during the Somavams rule
YEARS		10 th – 11 th century AD
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	The present temple has been constructed on the ruin of the original one in modern times.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please	:	Protected Monument of Orissa State Archaeology.
specify)		
Private	-	
Any other (Please specify) Name	:	
Address	:	Paryatan Bhaban, BJB Nagar, Bhubaneswar, Orissa.
Phone	:	0674 2432147
7. Association		
WITH EVENTS		
In History	÷	 Civeratri Cantranti Kartikanyumima ata
In Rituals In Building Construction	:	Sivaratri, Sankranti, Kartikapurnima etc.
Any other (specify)	:	
WITH PERSONS	•	
Patron		Orissa State Archaeology and the villagers.
Architect / Engineer	:	
Any other (specify)	:	Village people
8. Statement of Significance		
Architectural 🗸	/	Architectural
Archaeological :		
Historical :	/	Delinique
Religious ✓ Any other (specify) :		Religious On the basis of iconographical features of the <i>parsvadeval</i>
		images the temple can be dated to the $10^{\text{th}} - 11^{\text{th}}$ centurie AD, through the temple was built in modern times.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) : No Rural setting		
	Stand in IsolationStand in IsolationIntegral part of a Landscape /Street / Complex :		
Quantification			
Area Dimension (L x B x H)	: 16.30 mtrs x 4.00 mtrs x 10.00 mtrs (m / cm/ feet / inch)		
Number of Blocks Number of Storys	Two with recent addition of a R.C.C <i>mandapa</i>		
• Spatial Organization Orientation Plan Allocation of Spaces	 Facing towards east The <i>vimana</i> & <i>jagamohana</i> are square on plan. 14.40 mtrs (L) x 15.00 mtrs (W) 		
ARCHITECTURAL STYLE Ornamentation			
Exteriors	: Plain, but the <i>parsvadevata</i> niches are housed with the image of Ganesa, Parvati & Kartikeya.		
Interiors	: Plain, but later in the inner wall of the <i>jagamohana</i> images of Vajrapani, Parvati, Siva, are installed.		
Movable Collections	: Vajrapani, Santinatha, Parvati, Siva, temple architectural member and sculptural fragments.		
Any Other(specify)	: On plan it is <i>pancharatha</i> and in elevation it is <i>panchangabada</i> temple.		
10. Construction Technology			
Structural System	: Rekha vimana & jagamoha of impoverished Kalingan style.		
Building Techniques Material of Construction	English bondBricks and Sandstone.		
11. Condition Assessment			

Good / Fair In General : Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation.

12. Threats to the Property

	Natural Negligence Vandalism Urban Pressures			
* * * * * * * * * * * * * * * * * * * *	<pre>< x x x x x x x x x x x x x x x x x x x</pre>			
SECTION III: REFERENCES				

13. Reference Sources (published and unpublished textual details)

1.	
2.	
14. Photographs: 22 nos	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	

17. Listers			
NAME :	D. B. Garnayak	NAME :	
18. Review	ers		
NAME : COMMENT	Dr. S. Pradhan S	NAME : COMMENTS :	