

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/ JSP- 09

SECTION I: IDENTIFICATION					
1. Name					
Present Past Other Name (if any): 2. Location	: Kuttam Chandi Temple : :	, Debidol, DistJagatsinghpur			
LONGITUDE 86 ⁰ 10' 09"E	LATITUDE 20 ⁰ 09' 30" N	ELEVATION 32ft			
Address	: Village (village code) Post: Debidol Tehsil: Naugaon State: Orissa	Debidol – Ward No. 5 Via: Alanahata District: Jagatsinghpur PIN: 754109			
Approach		n the village Debidol, on the left and 5 kms from the Mundalo			
3. Property Type					
Palace Fort Citadel Govt. building Railway station Defence building Industrial building	Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Wall Gateway Pillar Others (specify)			
Other public buildings		Note:			
Residential building		It has a <i>pidha vimana</i> ,			
Engineering structure	Open space and related structures	jagamohana and frontal mandapa with addition of a			
Bridge Tunnel	Public square Park or garden	new RCC <i>mandapa</i> in front.			
Other engineering structure	Graveyard Baolis, Well Cave				

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, enshrining eight armed Mahisasuramardini Durga image. **Past** Worshipped 5. Age (Source) **PERIOD** Zamindari period 19th century AD YEARS **Precise date of Construction** Completion Subsequent changes A new RCC *mandapa* in front of the temple has been added. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Protected Monument of Orissa State Archeology & India / State Archaeology Endowment Department of Government of Orissa. Department / Any Other (Please specify) **Private** Any other (Please specify) Name Address Paryatan Bhavan, BJB Nagar, Bhubaneswar, Orissa Phone 0674-2432147 7. Association WITH EVENTS

In History : --

In Rituals : Jhamu yatra (occur in the month April)

In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Orissa State Archaeology & Endowment Department.

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

Architectural	✓	Architectural
Archaeological	✓	Archaeological
Historical	:	
Religious	✓	Religious
Any other (specify)	:	The architectural style assigns the temple to the early part of the 19 th century. But the enshrining deity iconographically can be dated to the late Gajapati period and the temple niches housed with the images of Ganga period.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if	necessary) : No Rural setting		
Junoundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Integral part of landscape		
• Quantification Area Dimension (L x B x H)	:	18.20 mtrs x 7.80 mtrs x 8.00 mtrs	(about) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	Three	(III / GIII/ leet / IIIGII)		
• Spatial Organization Orientation Plan	:	Facing towards east The <i>vimana</i> is square on place is place in the place is square on place in the place is a square of place.			
Allocation of Spaces	:	18.20 mtrs (L) x 7.80 mtrs (W)			
ARCHITECTURAL STYLE					
Ornamentation Exteriors	:	The temple is devoid of sculpt except the <i>parsvadevata</i> niches, images of Ganesa, Uma-Mahesvathe <i>vimana</i> & War procession Mahisasuramardini Durga image in	which are filled with ra and Gajalaxmi in scene panel and		
Interiors	:	The inner wall of the jagamohal niches which housed the image Narasimha, Indra, Uma-Mahesvar	na is provided with of Varahi, Manasa,		
Movable Collections Any Other(specify)	:	Nil (now attached in the niches) The sculptural edifice of the temp present temple is build over an a images are used on it are of the an	le suggest that, the ncient temple & the		
10. Construction Technology					
Structural System Building Techniques Material of Construction	:	Pidha vimana and jagamohana English Bond technique Bricks & stone.			
11. Condition Assessment In General Good / Fair	:	Fair			
Sign of Deterioration Serious Deterioration Danger of Disappearance	•				

In Brief (Attach extra sheet if nec	essary):
Water seepage during rainy seasor	າ in the sanctum and <i>jagamohana</i> .
12. Threats to the Property	
x x x x x x x x x x x x x x x x	Natural Negligence Vandalism Urban Pressures X X X X X X X X X X X X X X X X X X X
SE	CTION III: REFERENCES
13. Reference Sources (published	l and unpublished textual details)
1. 2.	
14. Photographs: 54 nos	(attack list as in page C in ages of moultiple what arrange)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	: :
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	: :
16. Maps/Plans/Drawings	
17. Listers	

NAME:

NAME: COMMENTS:

NAME:

NAME:

18. Reviewers

COMMENTS

D. B. Garnayak

Dr. S. Pradhan