

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / JPR - 63

1. Name	SECTION I: IDENTIFICATIO	N
Present Past Other Name (if any): 2. Location	: Mahastupa, Udayagiri : : Mahastupa, Madhava	Mahavihara-1, DistJajpur our Mahavihara
LONGITUDE 86 ⁰ 15' 59" E	LATITUDE 20 ⁰ 38'38"N	ELEVATION 115 ft
Address	: Village (village code) Post : Chandia Tehsil: Darpani State : Orissa	Udayagiri Via: Chaandikhol District: Jajpur PIN: 755044
Approach	Udayagiri monastic co hill range is located Birupa and about 12	he south-eastern side of the of omplex-1, in the foot hill of Assia on the right bank of the river kms from Haridaspur chowk on Chandikhol to Paradeep.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The stupa made of bricks and enclosed by a compound wall. On the four cardinal directions niches are provided to enshrine four unique figures of Dhynibuddha. The inscriptions found in the images are of Brahmi script and paleographically can be dated to the 10 th century AD.

4. Property Use ABANDONED / IN USE: Abandoned A point of tourist destination. Also the stupa houses **Present** four dhyini Buddha in the niches of four direction; Aksova in east, Ratnasambhava in the south, Amitava in the west and Amogasiddhi in the northern side. **Past** Worshipped. 5. Age (Source) **PERIOD** Somavamsi rule **YEARS** 9th century A.D. **Precise date of Construction** Completion Subsequent changes The stupa was renovated and conserved by Archaeological Survey of India. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Single **Public**: Archaeological Survey of : Protected monument of Archaeological Survey of Archaeology India / State India. Department / Any Other (Please specify) **Private** Any other (Please specify) ---Name **Address** Archaeological Survey of India, Bhuabaneswar Circle, 153, V.I.P. Area, Nayapalli, Bhubaneswar, Orissa 0674-2558170 **Phone** 7. Association **WITH EVENTS** In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Presently the stupa is looked after Archaeological Survey of India. **Architect / Engineer** Any other (specify) 8. Statement of Significance Architectural ✓ Architectural Archaeological Archaeological ✓ Historical Historical ✓ Religious Religious On the basis of architectural style and paleographical

evidence the stupa can be dated to the 9th centuries A.D.

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary): No Rural setting			
J	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :			
 Quantification 				
Area Dimension (LxBxH)	10.00 mtrs x 10 .00 mtrs x 04.80 mtrs			
Number of Blocks Number of Storys • Spatial Organization	(m / cm/ feet / inch) : One : NA			
Orientation :	The stung is acquere on plan			
Plan Allocation of Spaces	The stupa is square on plan. 20.90 mtrs. (L) x 21. 15 mtrs (W)			
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections * Any Other (specify) 10. Construction Technology Structural System Building Techniques Material of Construction	The stupa is devoid of ornamentation except the niches which are housed with the images of Dhyni-Buddha. NA The stupa is surmounted by a pradakshinapatha. Stupa provided with sculptural niches. English bond technique Bricks and Khandolite stone.			
Material of Construction 11. Condition Assessment	. Bricks and Khandonte stone.			
In General	Good / Fair : Good			
iii Selieiai	Sign of Deterioration Serious Deterioration Danger of Disappearance			
In Brief (Attach extra sheet if necessary):				
It is in a good state of preservation.				
12. Threats to the Property				
	✓ Natural Negligence Vandalism Urban Pressures			

SECTION III: REFERENCES

13. Reference	ce Sources (publish	ed ar	nd unpublished textual details)
1. G.C. Ch 2.	auley, 2004, <i>Monur</i>	nentai	l Heritage of Orissa, New Delhi.
14. Photogra	aphs: 36 nos		
			(attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	ence	:	
15. Audio / \	/ideo		
			(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	ON	:	
16. Maps/Pla	ans/Drawings		
17. Listers			
NAME :	A.R.Sahoo		NAME :
18.Reviewer	rs		
NAME :	Dr. S. Pradhan		NAME :

COMMENTS:

COMMENTS