

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDP - 03

SECTION I: IDENTIFICATION 1. Name Present Chandramauli Siva Temple, Chandannagar, Dist.- Kendrapara **Past** Other Name (if any): 2. Location **LONGITUDE** 86⁰39'17" E 20⁰33'01" N LATITUDE **ELEVATION** 20 ft **Address** Village (village code) Chandannagar Post: Chandannagar Via: Patamundai Tehsil: Patamundai **District**: Kendrapara State: Orissa **PIN:** 754215 The temple is located in the village Chandannagar at a **Approach** distance of ½ km right side of the Chandannagar chowk on Patamundai-Rajanagar Road. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Note: Residential building The temple has a pidha vimana, jagamohana and a flat-roofed Engineering structure Open space and related open mandapa. structures Bridge Public square Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, enshrining a Sivalinga within a circular yonipitha and bronze images of Siva & Parvati as the presiding deities. **Past** Worshipped. 5. Age (Source) During the days of the Zamindars of Kanika PERIOD YEARS 19th century A.D. **Precise date of Construction** Completion Subsequent changes Repaired and mentained by Kanika Raja Family **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Protected monument of Orissa State Archaeology & India State Archaeology Endowment Department Government of Orissa. / Department / Any Other (Please specify) **Private** Any other (Please specify) Name **Address** Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa **Phone** 0674-2432147 7. Association WITH EVENTS In History In Rituals Sivaratri, Kartika Purnima, etc. are observed here. In Building Construction Any other (specify) WITH PERSONS **Patron** Orissa State Archaeology Department. **Architect / Engineer** Any other (specify)

8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify) Architectural Religious Religious The basis of archaeological style, the temple can be dated to the last part of the 19th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings	•	* Drawings (Attach extra sheet if necessary): No Rural setting	
Currounumgs		Stand in Isolation Integral part of a Integral part of a Landscape / Street / Complex :	
 Quantification 			
Area Dimension (LxBxH)	:	26.00 mtrs x 8.00 mtrs x 9.50 mtrs (approximate height)	
N 1 (D) 1		(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	Three	
Spatial Organization			
Orientation	:	Facing towards east.	
Plan	:	The <i>vimana</i> & <i>jagamohana</i> are square on plan, whereas the frontal <i>mandapa</i> is rectangular plan that stands over a platform of 0.34 mtrs high.	
Allocation of Spaces		42.00 mtrs (L) x 40.00 mtrs. (W)	
ARCHITECTURAL STYLE Ornamentation			
Exteriors	•	The exterior walls of the temple are decorated with non-functional sculptural brackets of <i>nayikas</i> , divinities, mother with child, etc.	
Interiors	:	Plain	
Movable Collections	:	Images of ten-armed Chamunda measures 0.54 mtrs (L) x 32.00 mtrs (W) x 22.00 mtrs (D) and Bhairava	
* Any Other (specify)	:	The temple has seven projections with five-fold divisions of bada.	
10. Construction Technology			
Structural System	:	Pidha vimana, jagamohana with a flat-roofed pillared	
Building Techniques	:	mandapa. Ashlar masonry	
Material of Construction	:	Khandolite stone and cement plaster	
11. Condition Assessment			
In General Good / Fair	:	Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance			

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation

12. Threats to	the Property	
x		Natural Negligence Vandalism Urban Pressures X X X X X X X X X X X X X X X X X X X
	<u>SE</u>	CTION III: REFERENCES
13. Reference	Sources (published	and unpublished textual details)
1. 2.		
14. Photograp	hs: 60 nos	
-		(attach list as in page 6, in case of multiple photographs)
Photo Referen	nce	: :
15. Audio / Vic	deo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	I	: :
16. Maps/Plan	s/Drawings	
17. Listers		
NAME:	D. B. Garnayak	NAME:
18. Reviewers		
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: