

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDP - 08

SECTION I : IDENTIFICATION		
1. Name		
Present Past Other Name (if any):	: Harisankaresvara Siva DistKendrapara : : Harisankaresvara Maha	
2. Location		
LONGITUDE 86 ⁰ 18'40"E	LATITUDE 20 ⁰ 32'05" N	ELEVATION 30 ft
Address	: Village (village code) Post : Derabish Tehsil: Derabish State : Orissa	Kuanrpur Via: Derabish District: Kendrapara PIN: 754289
Approach		ideva Temple is located about erabish and 1/2 km south of k.
3. Property Type		
Buildings Palace Fort	<i>Religious structures</i> ✓ Temple Mosque	<i>Other Structures</i> Wall Gateway

	TOR	mooquo		Catomay
	Citadel	Minar		Pillar
	Govt. building	Church		Others (specify)
	Railway station	Monastery		
	Defence building	Stupa		
	Industrial building	Tomb, Mausoleum		
	Other public buildings	_	Ν	ote:
	Residential building		т	ha tamala haa a <i>nidha vin</i> aana
				he temple has a <i>pidha vimana</i>
	Engineering structure	 pen space and related ructures	-	nd a <i>jagamohan</i> of npoverished <i>Kalingan</i> order.
[Engineering structure Bridge	 •	-	, 0
		 ructures	-	, 0
	Bridge	 ructures Public square	-	, 0
	Bridge Tunnel	 ructures Public square Park or garden	-	, 0
	Bridge Tunnel	 ructures Public square Park or garden Graveyard	-	, 0
	Bridge Tunnel	 ructures Public square Park or garden Graveyard Baolis, Well	-	, 0

	ABANDONED / IN USE : In use	
Present	: Living temple, enshrining two Shaktipithas insta with lingam and Vishnu image.	
Past	: Worshipped.	
5. Age (Source)		
PERIOD	: Originally Ganga period, but later reconstructed by	
YEARS	Ex- Zamindar of Ali. 13 th century AD	
Precise date of Construction	· IS CENIURY AD	
Completion	: Reconstructed by the Zamindar of Ali in the 1	
Subsequent obseques	century. Banaviated by State Archaeology on 2002	
Subsequent changes Destruction / Demolition	Renovated by State Archaeology on 2002.	
6. Ownership / Level of Protection	on	
	SINGLE /MULTIPLE : Multiple	
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Endowment Department, Government of Orissa	
Private	:	
Any other (Please specify)	: Mahendra Kumar Dash, Chief Priest (Hereditary)	
Name Address	·	
Phone	·	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	: Sivaratri, Kartikapurnima, Bado Osha etc.	
In Building Construction Any other (specify)	·	
WITH PERSONS	-	
Patron	: Ex- Zamindar of Ali and Endowment Departme Government of Orissa	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural Archaeological	 Architectural Archaeological 	
Historical :		
Religious 🗸	Religious	
Any other (specify) :	On the basis of sculptural pieces kept in the <i>parsvadev</i> niches the temple can be dated to the 13 th century AD. ⁻ temple was renovated and reconstructed by Ex-Zamindar	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features * Drawings (Attach extra sheet if necessary) : No Context **Urban / Rural Setting** : Rural setting Surroundings Stand in Isolation Integral part of a Landscape / Stand in Isolation Street / Complex : Quantification 16.00 mtrs x 8.00 mtrs x 7.00 mtrs (present existing Area Dimension ($L \times B \times H$) height of *vimana*) (m / cm/ feet / inch) Number of Blocks Two Number of Storys ---**Spatial Organization** • Orientation Facing towards east Plan The vimana & jagamohana are square on plan. Allocation of Spaces 41.40 mtrs (L) x 29.40 mtrs. (W) ARCHITECTURAL STYLE Ornamentation Exteriors The temple is devoid of sculptural embellishment except the parsvadevata niches, which are housed with four armed Ganesa, four armed Kartikeya, Parvati. Except the doorjamb niches of the vimana, which Interiors housed Siva dvarapala the temple is plain. Movable Collections Ambika. Ganesa. Avalokatesvara, Parvati, Astikajaratkaru, Uma-Mahesvara etc. * Any Other (specify) : The temple is pancharatha on plan and panchangabada in elevation. **10.** Construction Technology Structural System : Pidha vimana and jagamohana **Building Techniques** Ashlar masonry and English bond with cement plaster **Material of Construction** Khandolite and brick. **11. Condition Assessment** In General Good / Fair Fair

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation.

12. Threats to the Property

~	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)				
1.				
14. Photographs: 57 nos				
	(attach list as in page 6, in case of multiple photographs)			
Photo Reference CAPTION				
15. Audio / Video				
	(related to rituals / performance / festivals etc.)			
Reference DESCRIPTION	:			
16. Maps/Plans/Drawings				
17. Listers				
NAME : D. B. Garnayak	NAME : A.R Sahoo			
18. Reviewers				

NAME :	Dr. S. Pradhan	NAME :
COMMENTS		COMMENTS :