

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDP - 01

SECTION I: IDENTIFICATION				
1. Name				
Present	: Malikesvara Siva Temple, Adhanga-Malikeswarpur, Dist Kendrapara			
Past Other Name (if any): 2. Location	: :			
LONGITUDE 86 ⁰ 17'37"E	LATITUDE 20°30′59″ N ELEVATION 70 ft			
Address	: Village (village code) Post : Palei Devakundi Tehsil: Kendrapara State : Orissa Adhanga–Malikeswarpur Via: Chandol District: Kendrapara PIN: 754208			
Approach	: The temple is located 4 kms north of Chandol, and on the right side of the Chandol - Derabish road.			
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)			
Other public buildings Residential building	Note: Rekha vimana and pidha			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures jagamohana of impoverished Kalingan order. Public square Park or garden Graveyard Baolis, Well Tank Cave			

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	It is a living temple, and enshrining a Sivalinga within a circular <i>yonipitha</i> .
Past	:	Worshipped.
5. Age (Source)		
PERIOD YEARS Precise date of Construction	:	Original temple which has no trace now was built in Somavamsi rule $9^{th} - 10^{th}$ centuries AD
Completion Subsequent changes Destruction / Demolition	: :	It must have been reconstructed in the 19 th century. Renovated by Orissa State Archaeology in 2006
6. Ownership / Level of Protection	<u>on</u>	
		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Endowment Department, Government of Orissa.
Private Any other (Please specify) Name	:	Purushotam Padhi (<i>Marfatdar</i>) Heredity Trustee & Ananta Ch. Panda
Address Phone	:	Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa 0674-2432147
7. Association		
WITH EVENTS In History In Rituals In Ruilding Construction	:	 Sivaratri, Rahasa Yatra, Pana Sankranti etc. observed here
In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer	:	Endowment Department and the Temple Trustee.
Any other (specify)	:	
8. Statement of Significance		
Architectural Archaeological	: ✓	Archaeological
Historical Religious	: ✓	Religious
Any other (specify)	: <u>=C1</u>	On the basis of architectural style, the temple can be dated to the 19 th century AD. And the sculpture attached in the temple can be dated to the 9 th – 10 th centuries AD. TION II: DESCRIPTION

9. Physical Description and Decorative Features					
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) : No Rural setting			
Carroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Street		
• Quantification Area Dimension (L x B x H)	:	9.75 mtrs x 4.90 mtrs x 10.00 mtrs	(m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	Two	(III / CIII/ leet / IIICII)		
 Spatial Organization Orientation Plan Allocation of Spaces 	: : :	Facing towards East The <i>vimana</i> and <i>jagamohana</i> are s 19.75 mtrs (L) x 17.80 mtrs. (W)	quare on plan.		
• Ornamentation Exteriors Interiors Movable Collections	: :	Devoid of sculptural and architectural ornamentation. Except the Gajalaxmi panel in the <i>lalatabimba</i> , th inner wall of the temple is plain. Avalokatesvara, Balarama, Astikajaratkaru, Varaha four armed Kartikeya, four armed Parvati, Eight arme Mahisasuramardini Durga. Batuka Bhairava, <i>nag</i>			
* Any Other (specify)	:	stambha etc. The temple is <i>triratha</i> on plan and elevation.	-		
10. Construction Technology					
Structural System Building Techniques Material of Construction	:	Rekha vimana & pidha jagamohan Ashlar masonry with cement plaste Khandolite stone.			
11. Condition Assessment In General Good / Fair		Good			
Sign of Deterioration Serious Deterioration Danger of Disappearance	•				
In Brief (Attach extra sheet if nec	ess	ary):			
It is in a good state of preservation.					

12. Threats to the Property

x	. x x x x x x x x x	✓ Natural Negligence Vandalism Urban Pressures X X X X X X X X X X X X X X X X X X X			
SECTION III: REFERENCES					
13. Reference	Sources (published	and unpublished textual details)			
 R. P. Moh Hotograp 	•	ology in Orissa, Vol. – I, Delhi			
14.1 Hotograp	7110. 27 1100	(attach list as in page 6, in case of multiple photographs)			
Photo Referei CAPTION		: :			
15. Audio / Vi	deo				
Reference DESCRIPTION		(related to rituals / performance / festivals etc.):			
16. Maps/Plan	ns/Drawings				
17. Listers					
NAME :	D. B. Garnayak	NAME :			
NAME : COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:			