

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 01

1. Name	SECTION I: IDENTIFICATION
Present	: Aisanesvara Siva Temple, Old Town, Bhubaneswar, DistKhurda
Past Other Name (if any):	: :
2. Location	
LONGITUDE 85 ⁰ 49'95" E	LATITUDE 20 ⁰ 14'31" N ELEVATION 88 ft
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Sriram Nagar, Old Town Via: Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, within the precinct of Municipal Corporation Hospital, is 10 mtrs distance from the western compound wall of Lingaraja temple across the road. It is surrounded by the approaching road in the east, Municipal hospital in north and residential buildings in west and south.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify) Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: The vimana is a rekha temple and the jagamohana is a pidha temple of Kalingan order.The temple is saptaratha on plan and panchangabada in elevation and resemblance

with the Meghesvara temple. On the basis of architectural style the temple can be dated to the 13th century A.D.

4. Property Use

ABANDONED / IN USE: In use

Present : It is a living temple, enshrining a Sivalinga within a

circular Yonipitha.

Past : Worshipped.

5. Age (Source)

PERIOD : Ganga rule
YEARS : 13th century A.D.

Precise date of Construction : Last quarter of 13th century A.D.

Completion : --

Subsequent changes : It is repaired and maintained by Bhubaneswar

Municipal Corporation.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Single

Public: Archaeological Survey of : India / State Archaeology

Department / Any Other (Please Bhubaneswar Municipal Corporation

specify)

Private : --Any other (Please specify) :

Name : --

Address : Bhubaneswar Municipal Corporation, Old Town,

Bhubaneswar, Khurda.

Phone : ---

7. Association

WITH EVENTS

In History : --

In Rituals : Sivaratri, Jalabhisheka, Rudrabhisheka, Sankranti etc.

are observed here.

In Building Construction : ---

Any other (specify) : As per tradition, lord Lingaraja visits this temple after

the 6th day of *Sivaratri*.

WITH PERSONS

Patron : Originally the Gangas, but now the Bhubaneswar

Municipal Corporation is looked after the monument.

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

Architectural Archaeological	✓	Architectural
Historical		
Religious	✓	Religious
Any other (specify)	:	Architectural features and decorative elements of the temple
_		assign the temple to the mature phase of temple building
		tradition of Orissa, i.e. the second half of the 13 th century.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

Urban / Rural Setting

Surroundings

* **Drawings** (Attach extra sheet if necessary):

Urban setting

No

Stand in Isolation Integral part of a Landscape /

Street / Complex:

Stand in Isolation

Quantification

Area Dimension (LxBxH) 10.05 mtrs. X 5.00 mtrs. X 9.19mtrs.

(m / cm/ feet / inch)

Number of Blocks Two Number of Storys

Spatial Organization

Orientation The temple is facing towards east

Both the *vimana and jagamohan are* square on plan Plan Allocation of Spaces

12.50 mtrs X 6.40 mtrs in length and breadth

respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors The temple is devoid of sculptural embellishments. The

tala jangha and upper jangha are decorated with khakara mundis and pidha mundis respectively. The pista has three mouldings and decorated with a series of khakara mundis. The anuratha pagas has series of khakara mundis in succession and lotus cup in anurahapagas and ten bhumi-amlas in the kanikapagas. The parsvadevata niches are provided with talagarbhika. Two udyata simhas are noticed in the gandi of rahapaga and a miniature rekha angasikhara at the base of the

gandi in the frontal raha.

Interiors The interior is devoid of any ornamentation.

Movable Collections

* Any Other (specify) The temple is saptaratha on plan and the panchanga

bada in elevation. The door jambs are decorated with vertical bands of puspa sakha, patra sakha and lata sakha from exterior to interior and dvarapala figures at

the bottom.

10. Construction	Technology	
Structural System	m :	The <i>vimana</i> is a <i>rekha</i> temple and the <i>jagamohana</i> is a <i>pidha</i> temple of <i>Kalingan</i> order.
Building Techniq Material of Const	truction :	Ashlar dry masonry. Grey Sandstone
11. Condition Ass	sessment	
In General Good Sign of Deterior Serious Deterior Danger of Disa	oration	Good
In Brief (Attach e	xtra sheet if necess	sary):
		reservation. In the north-eastern corner, the temple is south-eastern corner by the Hospital buildings.
12. Threats to th	ne Property	
	SECT	Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
14. Photographs:	: 16 nos	
		(attach list as in page 6, in case of multiple photographs
Photo Reference CAPTION	: :	
15. Audio / Video	ı	
		(related to rituals / performance / festivals etc.
Reference DESCRIPTION	: :	
16. Maps/Plans/D	rawings	
17. Listers		
	shis Ranjan Sahoo.	NAME:
18. Reviewers		
NAME · Dr	S Pradhan	NAME ·

COMMENTS:

COMMENTS