

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 05

1. Name	SECTION I: IDENTIFICATION	N
Present Past Other Name (if any): 2. Location	: Ananta – Vasudeva Te DistKhurda : Ananta – Vasudeva Te :	emple, Old Town, Bhubaneswar,
LONGITUDE 85 ⁰ 49'15" E	LATITUDE 20 ⁰ 13' 58" N	ELEVATION 52 ft
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa	Via: Bhubaneswar District: Khurda PIN: 751002
Approach	Lingaraja temple to	ght side of the road from Uttaresvara temple, and on ment of Bindusagara.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: It is a Kalingan style of temple having a rekha vimana, pidha jagamohana and also the natamandapa and bhogamondapa are of pidha temple.

4. Property Use

ABANDONED / IN USE: In use

Present : The name itself suggests that it is a Visnu temple

where Ananta, the primordial Snake serving as the couch and canopy of Visnu who is same as Lord Vasudeva or Krisna. The presiding deities are two brothers Krisna and Balaram with their sister

Subhadra.

Past : Worshipped

5. Age (Source)

PERIOD : Ganga rule. **YEARS** : 13th century A.D.

Precise date of Construction : 1278 A.D.

Completion : --

Subsequent changes: Addition of *natamandapa* and *bhogamanadapa* later

then the vimana & jagamohana.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of: Protected Monument of Archaeological Survey of

a / State Archaeology India.

Department / Any Other (Please

specify)

Private : ---Any other (Please specify) : ---

Name

Archaeological Survey of India.

Address : Bhubaneswar Circel, 153 VIP Area, Nayapalli,

Bhubaneswar, Orissa.

Phone : 0674-2558170

7. Association

WITH EVENTS

In History: The temple was built in AD.1278 by Chandrika,

daughter of Anangabhima-III during the reign of her nephew Bhanudeva – I (AD 1264-1279) for Ananta &

Vasudeva.

In Rituals : Anantabrata

In Building Construction : ---

Any other (specify) : Lord Lingara visits the temple on the day of

Prathamastami.

WITH PERSONS

Patron : Originally the Gangas, but now the Archaeological

Survey of India

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance				
Architectural Archaeological Historical Religious Any other (specify)	 ✓ Architectural ✓ Archaeological ✓ Historical ✓ Religious : On the basis of the architectural features, decorative features and paleography of the inscription, the temple is dated to the 13th century A.D. ECTION II: DESCRIPTION 			
9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) : No : Urban setting			
•	Stand in isolation Complex Integral part of a landscape / Street / Complex :			
 Quantification Area Dimension (L x B x H) 	: 16.00 mtrs x 6.00 mtrs x 12.00 mtrs(approximately) (m / cm/ feet / inch)			
Number of Blocks Number of Storys	: Four :			
 Spatial Organization Orientation Plan Allocation of Spaces 	 The temple is facing towards west. All the components are square on plan. 45.30 mtrs (L) x 30.50 mtrs(W) 			
ARCHITECTURAL STYLE • Ornamentation				
Interiors Interiors Movable Collections * Any Other (specify)	 Decorated with naga stambha, khakharamundi designs, alasakanya, mithuna, maithuna images, scrollwork and vidala motifs. Plain All the structures are panchangabada in elevation and pancharatha on plan. 			
10. Construction Technology				
Structural System	: The temple has a <i>rekha vimana</i> and rest components are of <i>pidha</i> order.			
Building Techniques Material of Construction 11. Condition Assessment	: Ashlar masonry.: Sandstone.			
In General Good / Fair	:			
✓ Sign of Deterioration✓ Serious DeteriorationDanger of Disappearance				

	h extra sheet if nece all of the temple has	ssary): urned blackish due to smoke of the temple kitchen.
12. Threats to	the Property	
		Natural Negligence Vandalism Urban Pressures
x x x x x x x	x x x x x x x x x x	
	SEC	TION III: REFERENCES
13. Reference	Sources (published a	and unpublished textual details)
 T. E. Dona Nilamani S R. P. Moh K. S. Behe 	Senapati, (Ed.), 1977, apatra, 1986, <i>Archae</i> era & Dolandson, 198	var, New Delhi. Temple Art of Orissa, Vol. II, Leiden. Orissa District Gazetters Puri, Cuttack. Tology in Orissa, Vol. I, New Delhi. The Sculptural master pieces from Orissa, New Delhi.
14. Photograp	hs: 50 nos	(Attach list as in page 6, in case of multiple photographs)
Photo Referen	ice	(/ madif not do in page 6, in case of maniple photographs)
15. Audio / Vid	leo	
Reference DESCRIPTION	I	(Related to rituals / performance / festivals etc.)
16. Maps/Plan	s/Drawings	
17. Listers		
NAME:	D. B. Garnayak	NAME:
18. Reviewers		
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: