

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 124 **SECTION I: IDENTIFICATION** 1. Name Banesvara Siva Temple, Muktesvara Temple Precinct, Present Old Town, Bhubaneswar, Dist.-Khurda **Past** Other Name (if any): 2. Location 20⁰14'33"N **LONGITUDE** 85⁰50'26"E LATITUDE **ELEVATION** 52 ft. Address Village (village code) Old Town Post: Old Town Via: Bhubaneswar **Tehsil:** Bhubaneswar District: Khurda State: Orissa **PIN**: 751002 Approach Located on the right side of the road leading to Puri from Bhubaneswar and on the South-Eastern corner of the Muktesvara Temple Complex just close to the (Muktesvara Tank) Ramakunda. 3. Property Type **Buildings** Religious structures Other Structures Palace Wall Temple Fort Mosque Gateway Pillar Citadel Minar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures Rekha vimana of Kalingan Bridge Public square order. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use

ABANDONED / IN USE: In use

Present : It is a living temple; the presiding deity is a Sivalinga

within a circular yonipitha.

Past : Worshipped

5. Age (Source)

PERIOD : Ganga rule
YEARS : 13th Century A.D.

Precise date of Construction : --Completion : --Subsequent changes : --Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE: Multiple

Public: Archaeological Survey of : Protected Monument of Archaeological Survey of India

India / State Archaeology Department / Any Other (Please

specify)

Private :

Any other (Please specify) : Lord Lingaraj Temple Management Trust

Name : Archaeological Survey of India

Address : Bhubaneswar Circle, 153- VIP Area, Nayapalli.

Phone : 0674-2558170

7. Association

WITH EVENTS

In History : ---

In Rituals : Sivaratri, Kartikapurnima etc. observed here

In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Archaeological Survey of India, Bhubaneswar Circle

Architect / Engineer : --

Any other (specify) : Lord Lingaraj Temple Management Trust.

8. Statement of Significance

Architectural

Archaeological

Historical

Religious

Any other (specify)

Architectural

✓ Architectural

✓ Religious

✓ Religious

∴ On architectural ground, the temple can be assigned to the 13th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) : No Urban setting	
Surroundings	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :	
• Quantification Area Dimension (L x B x H)	: 4.95 mtrs x 4.40 mtrs x 6.80 mtrs (approximate) (m / cm/ feet / inch)	
Number of Blocks Number of Storys	: one :	
 Spatial Organization Orientation Plan Allocation of Spaces 	 Facing towards west It is a square <i>Vimana</i> stand on a two moulded <i>pista</i> of 0.35mtrs in height. 68.50 mtrs x 61.00 mtrs 	
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	 Devoid of any decorations except the raha niches which are decorated with talagarbhika & urdhagarbhika surmounted by a Kirtimukha. In the frontal raha projections the doorjambs are crowned by three miniature pancharatha rekah vimana which again surmounted by a bho motif or vajramastaka. The vajramastaka of each side is crowned by udyotasimha. Plain It is saptaratha on plan and triangabada in elevation. An image of Lakulisa is found in the lalatabimba of the doorjamb. 	
10. Construction Technology		
Structural System Building Techniques Material of Construction	 Rekha vimana of Kalingan order. Ashlar dry masonry. Sandstone is used for the temple construction and laterite is used for foundation and the compound wall. Iron dowels are also used. 	
11. Condition Assessment		
In General	Good / Fair : Good	
	Sign of Deterioration Serious Deterioration	

	Danger of Disappearance	
In Brief (Attach extra sheet if nece	essary):	
Due to proper care & maintenance t	the temple is in good condition.	
12. Threats to the Property		
12. Threats to the Froperty	/ Notural	
	✓ Natural Negligence	
	Vandalism	
	Urban Pressures	
x x x x x x x x x x x x x x x x x x x	× × × × × × × × × × × × × × × × × × ×	
SECTION III: REFERENCES		
13. Reference Sources (published	and unpublished textual details)	
1. Debala Mitra, 1985, Bhubanes		
	Temple Art of Orissa, Vol. I, Leiden.	
3. R. P. Mohapatra, 1986, <i>Archae</i>	eology in Orissa, Vol I, New Delhi.	
14. Photographs: 13 nos		
	(attach list as in page 6, in case of multiple photographs)	
Photo Reference :		
CAPTION :		
15. Audio / Video		
	(related to rituals / performance / festivals etc.)	
Reference :		
DESCRIPTION :		
16. Maps/Plans/Drawings		
-		
17. Listers		
NAME: J. S. Naik	NAME :	
18. Reviewers		
NAME: Dr. S. Pradhan	NAME :	
COMMENTS	COMMENTS:	