

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 12

SECTION I : IDENTIFICATION 1. Name				
Present Past Other Name (if any): 2. Location	 Bhabani Sankar Temple, Old Town, Bhubaneswar, DistKhurda 			
LONGITUDE 85°50'09"E	LATITUDE 22 ⁰ 14'41"N ELEVATION 56 ft.			
Address	: Village (village code) Old Town Post : Old Town Tehsil: Bhubaneswar State : Orissa Old Town Via: Bhubaneswar District: Khurda PIN: 751002			
Approach	: Located on the southern reaches of the tank Bindusagar and in front of the Doodwawalla Dharmasala, on the left side of the road leading from Lingaraj to Bindusagar.			
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: The temple has a rekha vimana & pidha jagamohana of Kalingan order.			

4. Property Use

ABANDONED / IN USE: In use Present It is a living temple and enshrines a Sivalinga within a yonipitha. Worshipped **Past** 5. Age (Source) PERIOD Ganga rule YEARS 14th century A.D. **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple Public: Archaeological Survey of: Protected Monument of Orissa State Archaeology State Archaeology / Department / Any Other (Please specify) **Private** Bhabani Sankara Club Any other (Please specify) Name Ashok Kumar Garabadu (President of Bhabani Sankar Club). Old Town, Bhubaneswar Address Phone 7. Association WITH EVENTS In History In Rituals Sivaratri, Kartikapurnima, etc observed. In Building Construction Any other (specify) Thread ceremony, marriages, local mundana, meetings are performed. WITH PERSONS **Patron** Originally the Gangas but now it is looked after by Orissa State Archaeology Department. **Architect / Engineer** Any other (specify) 8. Statement of Significance ✓ Architectural Architectural Archaeological Historical ✓ Religious Religious Any other (specify) The architectural scheme and the overall decorative programme of temple suggest that the temple which is the impoverished Kalingan order belonged to the 14th century.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Rural setting		
		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :		
 Quantification 				
Area Dimension (LxBxH)	:	7.90 mtrs. X 5.45 mtrs X about 8.00 mtrs (m / cm/ feet / inch)		
Number of Blocks Number of Storys	:			
Spatial Organization				
Orientation	:	Facing towards north.		
Plan Allocation of Spaces	:	22.60 mtrs x 19.70 mtrs in length & breadth respectively.		
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	:	The temple is devoid of sculptural motifs, only a <i>Ganesa</i> image found on the outer wall crowned the <i>udyota simha</i> .		
Interiors Movable Collections	:	Udyotasimha, Surya and secular image of a hero with attendant.		
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation. In this temple the <i>vimana</i> & <i>jagamohana</i> are directly joined without a <i>sandhi-sthala</i> like <i>parsuramesvara</i> .		
10. Construction Technology				
Structural System Building Techniques	:	Rekha vimana and pidha jagamohana of Kalingan order. Ashlar dry masonry based on corbelling technique of construction.		
Material of Construction	:	Laterite is used for the construction of both superstructure & foundation and later on cement plaster is given on the surface of the temple.		
11. Condition Assessment				
In General	Go	ood / Fair : Fair		
	,	Sign of Deterioration Serious Deterioration Danger of Disappearance		

The temple is buri	ied upto the <i>jangl</i>	na in the eastern southern and northern sides.
12. Threats to the	e Property	
		✓ Natural Negligence Vandalism ✓ Urban Pressures
x x x x x x x x x	x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	SE	ECTION III: REFERENCES
13. Reference Sc	ources (published	and unpublished textual details)
•		eology in Orissa, Vol. I, New Delhi. Temple Art of Orissa, Vol. I, Leiden.
14. Photographs	: 10 nos	
		(attach list as in page 6, in case of multiple photographs
Photo Reference CAPTION	:	
15. Audio / Video)	
		(related to rituals / performance / festivals etc.
Reference DESCRIPTION		: :
16. Maps/Plans/D)rawings	
17. Listers		
NAME: D.	B. Garnayak	NAME :
18. Reviewers		
NAME · Dr	S Pradhan	NAME:

COMMENTS:

In Brief (Attach extra sheet if necessary):

COMMENTS