

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 21

SECTION I: IDENTIFICATION				
1. Name				
Present	: Bhrukutesvara Siva Te Dist Khurda	mple, Old Town, Bhubaneswar,		
Past	:			
Other Name (if any):	:			
2. Location				
LONGITUDE 85 ⁰ 49'93" E	LATITUDE 20 ⁰ 14'43" N	ELEVATION 86 ft		
Address	: Village (village code)	Yamesvara Patana, Old Town		
	Post : Old Town Tehsil: Bhubaneswar State : Orissa	Via: Bhubaneswar District: Khurda PIN: 751002		
Approach 3. Property Type	: The temple is located on the right side of the Badheibank chowk, on the road leading from Lingaraja temple to Yamesvara temple. The temple is at a distance of 40 mtrs west of Talesvara temple across the compound wall, 30 mtrs north-west of Yamesvara temple and 20 mtrs east of Bakresvara temple.			
Buildings	Religious structures	Other Structures		
Palace	✓ Temple	Wall		
Fort	Mosque	Gateway		
Citadel	Minar	Pillar		
Govt. building Railway station	Church Monastery	Others (specify)		
Defence building	Stupa			
Industrial building	Tomb, Mausoleum			
Other public buildings				
Residential building	• • • • • •			
Engineering structure	Open space and related structures	Note:		
Bridge	Public square	The temple is square on plan and		
Tunnel	Park or garden	<i>triangabada</i> in elevation. Locals ascribe it to the Somavamsis but		
Other engineering structure	Graveyard	on the basis of detached sculpture		
	Baolis, Well Tank	the temple can be dated to the		
	Cave	Ganga rule.		

4. Property Use				
ABANDONED / IN USE : In use				
Present	:	It is a living temple enshrining a Sivalinga within a circular yonipitha.		
Past	:	Worshipped.		
5. Age (Source)				
PERIOD	:	Ganga rule		
YEARS	:	13 th century A.D.		
Precise date of Construction	÷	Last quarter of the 13 th century A.D.		
Completion Subsequent changes	•			
Destruction / Demolition	:	Now the <i>mastaka</i> of the temple has collapsed.		
6. Ownership / Level of Protection				
		SINGLE /MULTIPLE : Multiple		
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:			
Private	:			
Any other (Please specify)	:	The temple is looked after by people of Yamesvara Patana locality.		
Name	:			
Address	:	Yamesvara Patana, Old Town, Bhubaneswara.		
Phone	:			
7. Association				
WITH EVENTS				
In History	:	According to the local people the temple is built by the (<i>Kesaris</i>) Somavamsis.		
In Rituals	:			
In Building Construction	÷			
Any other (specify) WITH PERSONS 	•			
• WITH PERSONS Patron		Now the people of Yamesvara Patana locality.		
Architect / Engineer	:			
Any other (specify)				
8. Statement of Significance	•			
Architectural Archaeological Historical	~	Architectural		
Religious	~	Religious		
Any other (specify)	:	Though locals ascribe it to the Somavamsis period, on the basis of architectural features, the temple can be dated to the last quarter of the 13 th century AD, the Ganga rule.		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features * **Drawings (**Attach extra sheet if necessary) : No Context **Urban / Rural Setting** Urban setting : Surroundings Stand in Isolation Complex Integral part of a Landscape / Street / Complex : Quantification Area Dimension (L x B x H) : 4.10 mtrs x 4.10 mtrs x 5.03 mtrs (m / cm/ feet / inch) Number of Blocks One : Number of Storys 5 **Spatial Organization** • Orientation The temple is facing towards north. Plan The vimana is square on plan. : Allocation of Spaces 5 ARCHITECTURAL STYLE Ornamentation • Exteriors : The temple is devoid of architectural motifs and sculptural embellishments. Interiors Plain : Movable Collections Image of Uma-Mahesvara (2 nos.) and an image of : Lakulisha. * Any Other (specify) : The temple is square on plan and triangabada in elevation. The gandi has three receding tiers that measures 3.00 mtrs in height and the mastaka has collapsed. **10.** Construction Technology : The vimana is pidha temple of Kalingan order. Structural System **Building Techniques** Ashlar dry masonry. : Material of Construction : Laterite

11. Condition Assessment

: Fair

✓ Sign of Deterioration

In General

✓ Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Good / Fair

Growth of vegetations like trees, wild grasses and lichen conceals the temple from all sides which needs to be cleared.

12. Threats to the Property

	 ✓ Natural ✓ Negligence 			
	Vandalism			
	Urban Pressures			
* * * * * * * * * * * * * * * * * * * *				
SECTION III: REFERENCES				
13. Reference Sources (published and unpublished textual details)				
1.				
2.				
14. Photograp				
	(attach list as in page 6, in case of multiple photographs)			
Photo Referei CAPTION	nce :			
15. Audio / Vi	deo			
	(related to rituals / performance / festivals etc.)			
Reference				
DESCRIPTION	N :			
16. Maps/Plans/Drawings				
17. Listers				
NAME :	Ashis Ranjan Sahoo NAME :			
18.Reviewers				

NAME :	Dr. S. Pradhan	NAME :
COMMENTS		COMMENTS :