

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 31

SECTION I: IDENTIFICATION 1. Name Present Siva Temple-III, Brahmesvara Temple Precinct, Bhubaneswar, Dist. - Khurda. **Past** Other Name (if any): 2. Location LONGITUDE 85°51'06"E 20<sup>0</sup>14'23"N LATITUDE **ELEVATION** 60 ft. **Address** Village (village code) Brahmesvara Patna Post: BJB Nagar Via: Bhubaneswar **Tehsil:** Bhubaneswar District: Khurda State: Orissa **PIN:** 751018 Approach It is on the north-eastern embankment of Brahmesvara tank and within the Brahmesavara temple precinct on the right side of Tankapani Road, leading from Ravi talkies square. 3. Property Type **Buildings** Religious structures Other Structures Palace Wall Temple Fort Mosque Gateway Citadel Minar Pillar Govt. building Others (specify) Church Railway station Monastery Defense building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The temple has a pidha vimana of structures Public square Kalingan order. Bridge Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

#### 4. Property Use ABANDONED / IN USE: In use It is a living temple; the presiding deity is a Sivalinga Present within a circular yonipitha. **Past** Worshipped 5. Age (Source) PERIOD Somavamsi rule 10<sup>th</sup> century A.D. YEARS **Precise date of Construction** Completion ---Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Single **Public**: Archaeological Survey of: Protected Monument of Archaeological Survey of India India / State Archaeology Department / Any Other (Please specify) Private ---Any other (Please specify) ---Name Address : Archaeological Survey of India, Bhubaneswar Circle, 153, VIP Area, Nayapalli, Bhubaneswar, Pin - 751015 Phone 0674-2558170 7. Association WITH EVENTS In History Connected with the history of Somavamsis In Rituals ---In Building Construction Any other (specify) WITH PERSONS Patron Originally the Somavamsis, now Archaeological Survey of India Architect / Engineer Any other (specify) 8. Statement of Significance

Architectural	✓	Architectural	
Archaeological	:		
Historical	/	Historical	
Religious	/	Religious	
Any other (specify)	:	On the basis of its architectural features, the can be dated to 10 <sup>th</sup> century A.D.	temple

# **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features						
<ul> <li>Context         Urban / Rural Setting         Surroundings     </li> </ul>	* <b>Drawings</b> (Attach extra sheet if necessary): No Urban setting					
<u>-</u>	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :					
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	: 3.35 mtrs x 3.00 mtrs x 5.00 mtrs (m / cm/ feet / inch)					
Number of Blocks Number of Storys • Spatial Organization Orientation Plan	<ul> <li>: One</li> <li>:</li> <li>: Facing towards east</li> <li>: The <i>vimana</i> is square on plan with a frontal porch of</li> </ul>					
Allocation of Spaces	<ul><li>0.35 mtrs. The cella of the <i>vimana</i> is 1.45 square mtrs.</li><li>3.35 mtrs (L) x 3.00 mtrs (B)</li></ul>					
• Ornamentation Exteriors	: The exterior wall of the temple is plain. The tiers pyramidal <i>gandi</i> are designed as the <i>khura</i> moulding.					
nteriors  Movable Collections  * Any Other (specify)	<ul> <li>Plain</li> <li></li> <li>The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.</li> </ul>					
10. Construction Technology						
Structural System	: It has a single <i>rekha vimana</i> with a shallow porch in front.					
Building Techniques Material of Construction 11. Condition Assessment	: Ashlar dry masonry : Sandstone					
In General	Good / Fair : Fair					
In Brief (Attach extra sheet if ı	Sign of Deterioration : Serious Deterioration Danger of Disappearance necessary):					
Rain water is percolating into the sanctum from the cracks in the roof.						
12. Threats to the Property						
	✓ Natural Negligence Vandalism Urban Pressures					

### **SECTION III: REFERENCES**

### 13. Reference Sources (published and unpublished textual details)

- 1. Debala Mitra, 1958, *Bhubaneswar*, New Delhi.
- 2. T. E. Donaldson, 1985, Hindu Temple Art of Orissa, Vol. I, Leiden.
- 3. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. I, New Delhi

14. Photographs: 03 n	os
-----------------------	----

(Attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference : DESCRIPTION :

16. Maps/Plans/Drawings

17. Listers

NAME: D.B. Garnayak NAME:

18. Reviewers

NAME: Dr. S. Pradhan NAME:

COMMENTS COMMENTS: