

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 09

SECTION I: IDENTIFICATION					
1. Name					
Present Past Other Name (if any):	 Buddhikesvar Siva Temple, Deulidharapur, DistKhurda 				
2. Location					
LONGITUDE 86 ⁰ 01'13" E	LATITUDE 20 ⁰ 08'34" N ELEVATION 42 ft.				
Address	: Village (village code) Post : Deulidharpur Tehsil: Bhuabaneswar State : Orissa Deulidharpur Via: Banamalipur District: Khurda PIN: 752103				
Approach	: The temple, on the left bank of the river Kushabhadra is situated on the left side of Balianta-Nimapada Road. It is about 22 kms from Balianta and 500 mtrs west of Madhukesvara temple.				
3. Property Type					
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)				
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: The temple has a rekha vimana and pidha jagamohana of Kalingan order.				

4. Property Use

ABANDONED / IN USE: In use

Present: It is a living temple and the presiding deity is a literite

Sivalinga made of laterite within a circular Yonipitha of

chlorite stone.

Past : --

5. Age (Source)

PERIOD : Gajapati Rule
YEARS : 15th century AD.

Precise date of Construction

Completion : --

Subsequent changes: The present temple was conserved and renovated by

INTACH in 2005.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

Public: Archaeological Survey of: Protected monument of Orissa State Archaeology

India / State Archaeology Department / Any Other (Please

specify)

Private : ---

Any other (Please specify) : Budhikeswar Yajna Committee under the

presidentship of Sudarsan Jena.

Name :

Address : Orissa State Archaeology, Paryatan Bhawan, B.J.B.

Nagar, Bhubaneswar, Orissa

Phone : 0674-2432147

7. Association

WITH EVENTS

In History : ---

In Rituals : Jagara, Sankranti, Visvasanti Mahayajna etc.

observed here.

In Building Construction : --

Any other (specify) : Engagement, Marriage ceremony are performed here

and meeting relating to the village problem are also

held in the temple.

WITH PERSONS

Patron : Originally by the Gajapatis, but presently under care

and mentainance of the Budhikeswar Yajna

Committee.

Architect / Engineer : ---

Any other (specify) : Orissa State Archaeology

8. Statement of Significance

Architectural ✓ Architectural

Archaeological Historical Religious Any other (specify)	: On be o	dated to the 15 th centual distribution	nitectural style, the temple can ury A.D.		
9. Physical Description and Do			shoot if necessary): No		
ContextUrban / Rural Setting	: Dra	wings (Attach extra s	sheet if necessary): No Rural setting		
Surroundings	Integ Land	d in Isolation ral part of a scape / Street / plex :	Stand in Isolation		
 Quantification Area Dimension (L x D x H) 	: 9.90	mtrs x 4.40 mtrs x 8.0	00 mtrs (approximate height) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	: Two :		(, 6, 1.66., 1)		
 Spatial Organization Orientation Plan Allocation of Spaces 		emple is facing towar vimana & jagamohan	ds west. <i>a</i> are square on plan.		
ARCHITECTURAL STYLE					
 Ornamentation Exteriors Interiors Movable Collections 	: Plain : A Ga	·	I and sculptural motifs. ing 0.88 mtrs (L) x 0.44 mtrs eto Ganga period.		
* Any Other (specify)	: The t	. ,	a on plan and <i>panchangabada</i>		
10. Construction Technology					
Structural System		s a <i>rekha vimana</i> gan order.	and a <i>pidha jagamohana</i> of		
Building Techniques Material of Construction	: Ashla	ar dry masonry. I stone.			
11. Condition Assessment					
In General	Good / F				
		Sign of Deterioration			
		us Deterioration er of Disappearance			
In Brief (Attach extra sheet if i					

The temple is in a good state of preservation as it was recently conserved & renovated .

12. Threats to	the Property		
x		✓ Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x	
	<u>S</u>	ECTION III : REFERENCES	
13. Reference	Sources (published)	ed and unpublished textual details)	_
14. Photogra	ohs: 07 nos		
		(attach list as in page 6, in case of multiple photograph	IS)
Photo Referer CAPTION	nce	: :	
15. Audio / Vi	deo		
		(related to rituals / performance / festivals et	С.)
Reference DESCRIPTION	N	: :	
16. Maps/Plar	ns/Drawings		
17. Listers			
NAME :	D.B. Garnayak	NAME :	
18.Reviewers	3		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	