

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

	5	Serial No.: OR / KDA/ BSR- 35
4 Name	SECTION I: IDENTIFICATION	N
1. Name		
Present	: Chintamanisvara Siva Bhubaneswar, Dist K	
Past	:	
Other Name (if any):	:	
2. Location		
LONGITUDE 85°49'80"E	<b>LATITUDE</b> 20 <sup>0</sup> 15'00"N	<b>ELEVATION</b> 100 ft.
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa	Via: Bhubaneswar
Approach	: It can be approace Chintamanisvara road road near the old static	, branching from Cuttack - Puri
3. Property Type		
Buildings	Religious structures	Other Structures
Palace	Temple	Wall
Fort Citadel	Mosque Minar	Gateway Pillar
Govt. building	Church	Others (specify)
Railway station	Monastery	carere (epocary)
Defence building	Stupa	
Industrial building	Tomb, Mausoleum	
Other public buildings		
Residential building		
Engineering structure	Open space and related structures	Note:
Bridge	Public square	It is a <i>rekha</i> temple of <i>Kalingan</i>
Tunnel	Park or garden	order.
Other engineering structure	Graveyard	
	Baolis, Well	
	Tank	
	Cave	

4. Property Use ABANDONED / IN USE: In use Present Living temple and the enshrining deity is a Sivalinga within a *yonipitha*. **Past** Worshipped 5. Age (Source) PERIOD Ganga rule 14<sup>th</sup> century A.D. YEARS **Precise date of Construction** Completion Subsequent changes Presently a R.C.C. mandapa has been added in front of the temple. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : State Archaeology Department / Any Other (Please specify) Private Chintamanisvara Temple Committee Any other (Please specify) Name Address Old Station Bazar, Bhubaneswar Phone 7. Association WITH EVENTS According to local legend the temple was built by the In History Kesharis (Somavamsis) In Rituals Various religious sacraments like Sivaratri, Siva Vivaha, Jalasaya, Rudrabhiseka are performed here. In Building Construction Any other (specify) Marriage and thread ceremonies are held here. WITH PERSONS **Patron** Chintamanisvara Temple Committee Architect / Engineer Any other (specify) 8. Statement of Significance

Architectural	1	Architectural
Archaeological		
Historical		
Religious	1	Religious
Any other (specify)	:	The architectural features and building materials of the temple assigns the temple to late Ganga period i.e. 14 <sup>th</sup> century AD.

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features				
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings (</b> Attach extra sheet if necessary): No Urban setting			
Curroundings	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :			
Quantification  Area Dimension ( L x B x H)	: 5.70 mtrs x 5.20 mtrs x 10.02 mtrs			
Number of Blocks Number of Storys	(m / cm/ feet / inch) : One :			
<ul> <li>Spatial Organization         Orientation         Plan     </li> </ul>	<ul><li>: Facing towards west.</li><li>: It has a square <i>vimana</i> with a frontal porch.</li></ul>			
Allocation of Spaces	: Compound wall measures 40 sq mtrs.			
ARCHITECTURAL STYLE  • Ornamentation				
Exteriors	: Decorated with <i>khakharamundis</i> & <i>pidhamundis</i> in <i>jangha</i> portion of <i>bada</i> , <i>deulacharini</i> on the recess of the <i>kanika paga</i> and the <i>gandi</i> portion is solely devoid of any decoration.			
Interiors Movable Collections	<ul> <li>Plain</li> <li>A four-armed Ganesa in the right side of the doorjambs who is holding a <i>parasu</i> and rosary in his lower left and right arms and <i>modakapatra</i> in upper left and broken</li> </ul>			
* Any Other (specify)	tooth (tusk) in lower left arm.  The temple is <i>pancharatha</i> on plan and <i>panchangabad</i> in elevation.			
10. Construction Technology				
Structural System Building Techniques Material of Construction	<ul> <li>The temple is a <i>rekha vimana</i> of <i>Kalingan</i> order.</li> <li>Ashlar dry masonry</li> <li>Sandstone used up to the <i>bada</i>. Laterite in the <i>gandi</i> &amp; compound wall, <i>mastaka</i> with cement plaster and lime wash.</li> </ul>			
11. Condition Assessment				
In General	Good / Fair : Fair			
	Sign of Deterioration ✓ Serious Deterioration Danger of Disappearance			

The western s	ide of the temple preci	nct is partly encroached by shops and buildings.		
12. Threats to	the Property			
		Natural Negligence Vandalism Urban Pressures		
x x x x x x x		x x x x x x x x x x x x x x x x x x x		
	SEC	TION III: REFERENCES		
13. Reference	Sources (published a	and unpublished textual details)		
1. K. C. Pan 2.	igrahi, 1961, <i>Archaeol</i>	ogical Remains at Bhubaneswar, Calcuatta.		
14. Photograp	ohs			
		(attach list as in page 6, in case of multiple photographs)		
Photo Referent CAPTION	ice :			
15. Audio / Vi	deo			
		(related to rituals / performance / festivals etc.)		
Reference DESCRIPTION	N :			
16. Maps/Plans/Drawings				
17. Listers				
NAME :	Jaya Shankar Naik	NAME :		
NAME :	Dr. S. Pradhan	NAME :		
COMMENTS	DI. S. PIAUIIAII	COMMENTS:		

In Brief (Attach extra sheet if necessary):