INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

## Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: OR / KDA/ BSR- 39

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	<ul> <li>Templeof north-east corner , Chitrakarini Temple</li> <li>Complex, Bhubaneswar, DistKhurda</li> <li></li> </ul>
Other Name (if any):	·
2. Location	
LONGITUDE 85 <sup>0</sup> 50'01"	<b>LATITUDE</b> 20 <sup>0</sup> 14'22" <b>ELEVATION</b> 86 feet
Address	: Village (village Badheibanka chowk code) Post : Old Town Via: Bhubaneswar Tehsil: District: Khurda Bhubaneswar State : Orissa PIN: 751002
Approach 3. Property Type	: The temple, on the north-eastern corner of the main temple, Chitrakarini near the Badheibanka Chowk, located at the right side of Kalpana – Lingaraja Temple Road. It is situated in the north- west corner of Lingarja temple complex.
Buildings	Religious structures Other Structures
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public buildings Residential building	✓     Temple     Wall       Mosque     Gateway       Minar     Pillar       Church     Others (specify)       Monastery     Stupa       Tomb, Mausoleum
Engineering structure         Bridge         Tunnel         Other engineering structure	Open space and related structuresNote:Public squareThe temple has a rekha vimana of Kalingan order and a projecting entrance.GraveyardBaolis, WellTankCave

4. Property Use		
		ABANDONED / IN USE : abandoned
Present	:	This is a non living temple, the enshrined deity is
Past	:	missing now. Worshipped
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition		Ganga Period 13 <sup>th</sup> century A.D.   
6. Ownership / Level of Prote	ctic	on
		SINGLE /MULTIPLE : Single
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Archaeological Survey of India
Private	:	
Any other (Please specify) Name Address	:	 Archaeological Survey of India Bhubaneswar Circle, 153, VIP Area, Nayapalli,
Phone	:	Bhubaneswar 0674-2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify) WITH PERSONS	•	
Patron	:	Originally the Gangas, but presently under the care of Archaeological Survey of India.
(Chief priest.) Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural Archaeological Historical	✓ : :	Architectural
Religious Any other (specify)	:	Religious It is one of the <i>panchayatana</i> class temples in Bhubaneswar

of mature phase of the temple building tradition. On architectural features and sculptural embellishments, the temple can be dated to the  $13^{th}$  century AD.

# SECTION II: DESCRIPTION

## 9. Physical Description and Decorative Features

Context		* Drawings (Attach extra sheet if necessary) : No
Urban / Rural Setting	:	Urban setting
Surroundings		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
		Sueer / Complex .
Quantification		
Area Dimension (L x B x H)	:	3.05 mtrs.x 3.05 mtrs.x 9.00mtrs.(Approximately) (m / cm/ feet / inch)
Number of Blocks	:	One
Number of Storys	:	
Spatial Organization		
Orientation	:	Facing towards west.
Plan	:	
Allocation of Spaces	:	32.60 mtrs (L)x 23.80 mtrs(B)
ARCHITECTURAL STYLE		
Ornamentation		
Exteriors	•	The exterior of the vimana and jagamohana are embellished with architectural motifs like pidha mundi and khakhara mundi in upper jangha and tala jangha respectively, sculptural motifs include bho-type vajramastaka, naga-nagi pillars, gajakranta, nayikas, kirtimukha and udyota simhas and various kinds of floral motifs and erotic sculpture etc.
Interiors	:	The interior of both <i>vimana</i> and <i>jagamohana</i> are devoid of any decoration.
Movable Collections	:	
* Any Other (specify)	:	The temple has <i>panchangabada</i> in elevation and <i>saptaratha</i> on plan.
10. Construction Technology		
Structural System	:	<i>Rekha vimana</i> and <i>pidha jagamohana</i> of <i>Kalingan</i> order.
Building Techniques	:	Ashlar dry masonry
Material of Construction	:	Sand stone.
11. Condition Assessment		
In General Good / Fair	:	Fair
Sign of Deterioration		
Serious Deterioration		
Danger of Disappearance		
In Brief (Attach oxtra sheet if r	~~	oeearu);

## In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation.

### 12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

### **SECTION III: REFERENCES**

#### 13. Reference Sources (published and unpublished textual details)

- 1. Debala Mitra, 1985, *Bhubaneswar*, New Delhi.
- 2. T. E. Donaldson, 1986, *Hindu Temple Art in Orissa*, Vol. II, Leiden.
- 3. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. I, New Delhi.

#### 14. Photographs: 04 nos

Photo Reference CAPTION	(attach list as in page 6, in case of multiple photographs) : :
15. Audio / Video	(related to rituals (performance (festively etc.))

	(related to fituals / performance / restivals etc.)
Reference DESCRIPTION	

#### 16. Maps/Plans/Drawings

17. Listers NAME :	Binod Bihari Satpathy	NAME :	
18. Reviewe	rs		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	