

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 38

1. Name	SECTION I: IDENTIFICATION	
Present	: Temple of north-west corner , Chitrakarini Temple Complex, Bhubaneswar, DistKhurda	
Past Other Name (if any):	: :	
2. Location		
LONGITUDE 85 ⁰ 50'01"	LATITUDE 20 ⁰ 14'22" ELEVATION 86 feet	
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Badheibanka chowk Via: Bhubaneswar District: Khurda PIN: 751002	
Approach	: The temple, on the north-west corner of the main temple, Chitrakarini near the Badheibanka Chowk, located at the right side of Kalpana – Lingaraja Temple Road. It is situated in the north-west corner of Lingarja temple complex.	
3.Property Type		
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public buildings	Religious structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum	
Residential building Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Note: The temple has a rekha vimana of Kalingan order and a projecting entrance.	

Cave

4. Property Use

ABANDONED / IN USE : abandoned Present It is a non living temple, the enshrined deity is missing now. Past Worshipped 5. Age (Source) Ganga Period **PERIOD** 13th century A.D. YEARS Precise date of Construction Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Single **Public**: Archaeological Survey: Protected monument of Archaeological Survey of of India / State Archaeology India Department / Any Other (Please specify) **Private** ---Any other (Please specify) Name Archaeological Survey of India **Address** Bhubaneswar Circle, 153, VIP Area, Nayapalli, Bhubaneswar **Phone** 0674-2558170 7. Association **WITH EVENTS** In History In Rituals In Building Construction Any other (specify) ---**WITH PERSONS Patron** Originally the Gangas, but presently under the care of Archaeological Survey of India. (Chief priest.) Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Architectural Archaeological Historical Religious Religious

Any other (specify)

It is one of the *panchayatana* class temples in Bhubaneswar of mature phase of the temple building tradition. On architectural features and sculptural embellishments, the temple can be dated to the 13th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

* Drawings (Attach extra sheet if necessary) : No

Urban / Rural Setting :

Surroundings

Stand in Isolation Complex

Integral part of a Landscape / Street /

Complex:

Quantification

Area Dimension (L x B x H) : 3.05 mtrs.x 3.05 mtrs.x 9.00mtrs.(Approximately)

(m / cm/ feet / inch)

Urban setting

Number of Blocks : One Number of Storys : ---

Spatial Organization

Orientation : Facing towards east.

Plan : ---

Allocation of Spaces : 32.60 mtrs (L)x 23.80 mtrs(B)

ARCHITECTURAL STYLE

Ornamentation

Exteriors : The exterior of the *vimana* and *jagamohana* are

embellished with architectural motifs like pidha mundi and *khakhara mundi* in *upper jangha* and *tala jangha* respectively, sculptural motifs include *bho-type vajramastaka*, *naga-nagi* pillars, *gajakranta*, *nayikas*, *kirtimukha* and *udyota simhas* and various kinds of floral motifs and

erotic sculpture etc.

Interiors : The interior of both *vimana* and *jagamohana* are

devoid of any decoration.

Movable Collections : --

* **Any Other** (specify) : The temple has *panchangabada* in elevation and

saptaratha on plan.

10. Construction Technology

Structural System : Rekha vimana and pidha jagamohana of Kalingan

order.

Building Techniques : Ashlar dry masonry

Material of Construction : Sand stone.

11. Condition Assessment	
In General Good / Fair : Fair	
Sign of Deterioration	
Serious Deterioration	
Danger of Disappearance	
In Brief (Attach extra sheet if necessary):	
12. Threats to the Property	
. Natural	
Negligeno	e
Vandalisr	
Urban Pro	essures
x x x x x x x x x x x x x x x x x x x	. x x x x x x x x x x x x x x x x x x x
<u>SECTION III:</u> RE	
13. Reference Sources (published and unpub	lished textual details)
1. Debala Mitra, 1985, <i>Bhubaneswar</i> , New D	elhi
2. T. E. Donaldson, 1986, <i>Hindu Temple Art</i>	
3. Nilamani Senapati, (Ed.), 1977, Orissa Di	
4. R. P. Mohapatra, 1986, Archaeology in O	
14. Photographs: 08 nos	
· ·	n page 6, in case of multiple photographs)
Photo Reference :	
CAPTION :	
15. Audio / Video	
	ted to rituals / performance / festivals etc.)
Reference	
DESCRIPTION :	
16. Maps/Plans/Drawings	
17. Listers	
NAME: Binod Bihari Satpathy NAM	IE:
18. Reviewers	
NAME: Dr. S. Pradhan NAM	E:
COMMENTS COM	IMENTS: