INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 70

4 N	SECTION I : IDENTIFICATION
1. Name	
Present	: Jalesvara Siva Temple, Kalarahanga, Bhubaneswar,DistKhurda
Past Other Name (if any): 2. Location	: :
LONGITUDE 85 ⁰ 50'40" E	LATITUDE 20 ⁰ 21'40" N ELEVATION 76 ft
Address	 Village (village code) Post : Patia Tehsil: Bhubaneswar State : Orissa Kalarahanga Via: Bhubaneswar District: Khurda PIN: 751031
Approach	: The temple is situated on the southern outskirt of the village Kalarahangaq at a distance of 2 kms from Patia and 6kms south of Chudangagada in the northern outskirt of Bhubaneswar.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Other Structures Image: Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: It has a rekha vimana and a unique pidha jagamohana of Kalingan order.Park or garden Baolis, Well Tank CaveNote: It has a rekha vimana and a unique pidha jagamohana of Kalingan order.



		ABANDONED / IN USE : In use
Present	:	It is a living temple and the presiding deity is a Sivalinga within a circular <i>yonipitha</i> .
Past	:	Worshipped.
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes	: : : : : : : : : : : : : : : : : : : :	Somavamsi rule 12 th century A.D.
Destruction / Demolition	•	
6. Ownership / Level of Protection	<u>)</u>	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey ofIndia / State ArchaeologyDepartment / Any Other (Pleasespecify)Private	:	Protected Monument of Orissa State Archaeology
Any other (Please specify)	:	The temple is looked after by the priests and sevayatas of Panda
Name Address Phone	:	Pryatana Bhawan, BJB Nagar, Bhubaneswar 0674-2432147
7. Association		
• WITH EVENTS In History In Rituals	:	 Rituals like <i>Sivaratri, Janmastami, Sitalasasthi,</i> <i>Chandana yatra</i> are observed.
In Building Construction	:	
Any other (specify) WITH PERSONS 	:	
Patron	:	Originally, the Somavamsis but now Orissa State Archaeology.
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural Archaeological Historical Religious	✓ : :	Architectural Religious
	•	On the basis of architectural style, the temple can be dated

SECTION II: DESCRIPTION

9. Physical Description and I	
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) : No : Urban setting
	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
Quantification	
Area Dimension (L x B x H)	: 15.70 mtrs x 9.00 mtrs x 12.35mtrs (m / cm/ feet / inch)
Number of Blocks	: Two
Number of Stories	:
Spatial Organization	
Orientation	: The temple is facing towards east.
Plan	: The vimana and jagamohana are square on plan.
Allocation of Spaces	:
ARCHITECTURAL STYLE	
Ornamentation	.
Exteriors	: The exterior of the temple is devoid of ornamentation except the <i>parsvadevata</i> niches and above the <i>antarala</i> is a <i>sukanasa</i> designed after a <i>khakhara mundi</i> , which is flanked by two miniature <i>rekha vimana</i> , above it there is a stylized <i>chaitya</i> motif flanked by two conches and crowned by a <i>kirtimukha</i> which is surmounted by a <i>gajakranta</i> . The base of the <i>gandi</i> is decorated with a series of miniature <i>rekha deul</i> as <i>angasikharas</i> .
Interiors	: plain
Movable Collections	: Images of gaja vidala, female figure with simha head gajakranta, amorous couple, nayikas etc.
* Any Other (specify)	: The temple is <i>pancharatha</i> on plan and <i>panchanga bada</i> in elevation.
10. Construction Technology	,
Structural System Building Techniques Material of Construction	 Rekha vimana and pidha jagamohana. Ashlar dry masonry. Sandstone
11. Condition Assessment	
In General Good / Fair ✓ Sign of Deterioration Serious Deterioration	: Fair

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Because of the low elevation of the temple, rain water stagnates during the rainy season.

12. Threats to the Property

\checkmark	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. T.E. Donaldson, 1985, *Hindu Temple Art of Orissa*, Vol-I, Leiden.
- 2. R.P. Mohapatra, 1986, Archaeology in Orissa, vol-I, Delhi.

14. Photographs

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	

17. Listers

NAME : D.B.Garnayak.

NAME :

18. Reviewers

NAME : Dr. S. Pradhan COMMENTS

NAME : COMMENTS :