

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR-78

SECTION I: IDENTIFICATION				
1. Name				
Present Past Other Name (if any): 2. Location	: Kapilesvara Siva Temp : :	ole, Kapilesvara, DistKhurda.		
LONGITUDE 85°49'65"E	LATITUDE 20 ⁰ 13'74"N	ELEVATION 45 ft		
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa	Via: Bhubaneswar		
Approach	the village Kapilesva	the south-western outskirt of ara is situated at the end of ading from Lingaraja temple		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The temple has a rekha vimana, pidha jagamohana, natamandapa and bhogamandapa of Kalingan order.		

4. Property Use ABANDONED / IN USE: ---Present Living temple and the presiding deity is a Sivalinga within a circular yonipitha. **Past** worshipped 5. Age (Source) **PERIOD** Suryavamsi rule. (Kapilendradeva) 14th century A.D. YEARS 14th century A.D. **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of : Endowment Department, Government of Orissa. India State Archaeology / Department / Any Other (Please specify) **Private** Kapilesvara Temple Trust Board Any other (Please specify) Name Address Kapilesvara, Bhubaneswar. Phone 7. Association WITH EVENTS Local people ascribe the temple to Kapilendra Deva In History Jagara, Sitalasasthi etc. are observed. In Rituals In Building Construction Marriages, engagements etc, held here Any other (specify) WITH PERSONS Patron Kapilesvara Temple Trust Board **Architect / Engineer** Any other (specify)

8. Statement of Significance

8. Statement of Significance		
Architectural	✓	Architectural
Archaeological	:	
Historical	:	
Religious	\checkmark	Religious
Any other (specify)	:	The inscription in the temple ascribes the temple to
		Kapilendradeva, the king of Suryavamsi Gajapati dynesty.
		Local belief also confirms.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Rural setting		
o an o an an ago		Stand in isolation Complex Integral part of a landscape / Street / Complex :		
Quantification				
Area Dimension (L x B x H)	:	29.90 mtrs x 9.50 mtrs x 11.40 mtrs		
Number of Blocks		(m / cm/ feet / inch)		
Number of Storys	:			
Spatial Organization				
Orientation	:	Facing towards east.		
Plan	:	On plan the temple has a <i>vimana</i> , <i>antarala</i> , <i>jagamohana</i> , <i>natamandira</i> and <i>bhogamandapa</i> , which stands on a rectangular <i>pista</i> . Except the rectangular <i>natamandira</i> all the components are square on plan.		
Allocation of Spaces	:	35.90 mtrs(L) x 16.25 mtrs(W).		
ARCHITECTURAL STYLE Ornamentation				
Exteriors	:	The temple is decorated with architectural motifs such as <i>khakharamundi</i> and <i>pidhamundi</i> in the lower and upper <i>jangha</i> respectively.		
Interiors	:	Plain		
Movable Collections	:	Nil		
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan & <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System	:	Kalingan style of architecture in which the vimana is of rekha order and jagamohana is of pidha order,		
Building Techniques		natamandira and bhogamandapa are of pidha order. Ashlar Masonry		
Material of Construction	:	Grey sandstone is used for the temple and laterite for the foundation and the compound walls.		
11. Condition Assessment				
In General Good / Fair	:	Fair		
Sign of Deterioration Serious Deterioration Danger of Disappearance				

Rain water is pe	rcolating into the natan	mandira due to the cracks in the roof.			
12. Threats to the	he Property				
	✓ ✓	Natural Negligence Vandalism Urban Pressures			
x x x x x x x x	< x x x x x x x x x x x x x x x x x x x				
SECTION III: REFERENCES					
13. Reference S	ources (published and	d unpublished textual details)			
		gy in Orissa, Vol- I, New Delhi. ole Art of Orissa, Vol II, Lieden.			
14. Photograph					
		(Attach list as in page 6, in case of multiple photographs)			
Photo Reference CAPTION	; e :				
15. Audio / Vide	90	(D.1.1.1)			
Reference DESCRIPTION	: :	(Related to rituals / performance / festivals etc.)			
16. Maps/Plans	/Drawings				
17. Listers					
NAME:	Jayasankar Naik	NAME:			
18. Reviewers					

NAME:

COMMENTS:

In Brief (Attach extra sheet if necessary):

NAME:

COMMENTS

Dr. S. Pradhan