

## **INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS**

Janpath, New Delhi -110 001, <a href="https://www.ignca.gov.in">www.ignca.gov.in</a>
Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 221

	SECTION I: IDENTIFICATION
1. Name	
Present  Past Other Name (if any):	<ul> <li>: Khandagiri Gumpha (Cave-No. 05 ASI),</li> <li>: Khandagiri Hillock, Bhubaneswar, Dist Khurda</li> <li>:</li> <li>:</li> </ul>
oution realities (in unity).	•
2. Location	
<b>LONGITUDE</b> 85 <sup>0</sup> 45'20" E	<b>LATITUDE</b> 20 <sup>0</sup> 15'74" N <b>ELEVATION</b> 247 ft.
Address	: <b>Village (village</b> Khandagiri Hillock code)
Khandagiri hill	Post: Khandagiri Via: Bhubaneswar Tehsil: District: Khurda Bhubaneswar
	State: Orissa PIN: 751030
Approach  3. Proporty Type	: It is situated on the middle terrace of the Khandagiri Hillock, on the left side of the road (MDR-78), branching from the National Highway No. 5 at Khandagiri Square.
3. Property Type  Buildings	Religious structures Other Structures
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank ✓ Cave  Note: It consists of two plain cells, one above the other, both badly damaged.

## 4. Property Use

ABANDONED / IN Abandoned

USE:

Present : Abandoned, but presently became the point of

tourist attraction.

Past : Used by the Jaina monks

5. Age (Source)

PERIOD : Mahameghavahana Chedi dynasty

**YEARS** : 1<sup>st</sup> century B.C.

Precise date of Construction : --- Completion : ---

**Subsequent changes**: Renovated by Archaeological Survey of India.

**Destruction / Demolition** : Badly damaged

6. Ownership / Level of Protection

SINGLE /MULTIPLE Single

Protected Monument of Archaeological Survey of

:

India

Public: Archaeological Survey:

of India / State Archaeology Department / Any Other

(Please specify)

Private : --Any other (Please specify) : --Name : ---

Address : Bhubaneswar Circle, 153, VIP Area, Nayapalli,

Bhubaneswar. Pin - 751015

**Phone** : 0674-2558170

7. Association

WITH EVENTS

In History : --In Rituals : --In Building Construction : --Any other (specify) : ---

**WITH PERSONS** 

Patron : Orginally Kharavela the king of Kalinga, now

Archaeological Survey of India.

Architect / Engineer : ---

Any other (specify) :

8. Statement of Significance

Architectural ✓ Architectural Archaeological ✓ Archaeological

Historical Religious Any other (specify)	<ul> <li>✓ Historical</li> <li>✓ Religious</li> <li>Epigraphic record in Hatigumpha ascribes it to Kharavela, who was ruling in 1<sup>st</sup> century BC.</li> </ul>
9. Physical Description and	SECTION II: DESCRIPTION Decorative Features
Context Urban / Rural Setting	* <b>Drawings (</b> Attach extra sheet if necessary): No : Urban setting
Surroundings	Stand in isolation Complex Integral part of a landscape / Street / Complex :
Quantification	
	: 05.10 mtrs X 2.70 mtrs X 1.87 mtrs
Number of Blocks	(m / cm/ feet / inch)
Number of Storys	·
Spatial Organization	Facility (a. a.ula Facil
Orientation Plan	<ul><li>: Facing towards East</li><li>: Rectangular plan without verandah</li></ul>
Allocation of Spaces	: 05.10 mtrs (L) X 2.70 mtrs (B)
ARCHITECTURAL STYLE Ornamentation	
Exteriors	: Plain
Interiors	: The cave is devoid of sculptural embellishment, only traces of ocher colour paintings are noticed on the celing and back wall of the cave.
Movable Collections	:
* Any Other (specify)	<ul> <li>Recently two pillars have been provided in the center of the cella by the Archaeological Survey of India.</li> </ul>
10. Construction Technolog	
Structural System	: Rock cut cave, consists of a single cella.
Building Techniques Material of Construction	<ul><li>: Hewed out of natural rock surface.</li><li>: Sandstone</li></ul>
	. Sanusione
11. Condition Assessment In General	Good / : Fair
iii <b>J</b> oiloidi	Fair

In Brief (Attach extra sheet i Water seepage from the roo Archaeological Survey of India 12. Threats to the Property	of during the rainy season, even it was conserve
X x x x	✓ Natural   Negligence   ✓ Vandalism   Urban Pressures   × x x x x x x x x   SECTION III: REFERENCES
<ol> <li>Debala Mitra, 1985, <i>Uday</i></li> <li>R. P. Mohapatra, 1986, <i>A</i></li> </ol>	ished and unpublished textual details)  vagiri & Khandagiri, New Delhi.  rchaeology in Orissa, Vol I, New Delhi.
<ul><li>3. Nilamani Senapati (ed.), 1</li><li>14. Photographs: 02 nos</li></ul>	1977, <i>Orissa District Gazetteers Puri</i> , Cuttack.
	1977, <i>Orissa District Gazetteers Puri</i> , Cuttack.  (attach list as in page 6, in case of multiple photogon): :
14. Photographs: 02 nos  Photo Reference	(attach list as in page 6, in case of multiple photogonic
14. Photographs: 02 nos  Photo Reference CAPTION	
14. Photographs: 02 nos  Photo Reference CAPTION  15. Audio / Video  Reference	(attach list as in page 6, in case of multiple photog :
14. Photographs: 02 nos  Photo Reference CAPTION  15. Audio / Video  Reference DESCRIPTION  16. Maps/Plans/Drawings	(attach list as in page 6, in case of multiple photog :
14. Photographs: 02 nos  Photo Reference CAPTION  15. Audio / Video  Reference DESCRIPTION	(attach list as in page 6, in case of multiple photog : :
14. Photographs: 02 nos  Photo Reference CAPTION  15. Audio / Video  Reference DESCRIPTION  16. Maps/Plans/Drawings	(attach list as in page 6, in case of multiple photog : : : (related to rituals / performance / festival): :