INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 28

4 NI	SECTION I : IDENTIFICATION		
1. Name			
Present	: Suvarnesvara Temple, Dist Khurda	Raiguru Basudeipura,	
Past	:		
Other Name (if any):	:		
2. Location			
LONGITUDE 85 ⁰ 53' 17" E	LATITUDE 20 ⁰ 13' 20" N	ELEVATION 22 ft	
Address	: Village (village code) Post : Balakati Tehsil: Bhubaneswar State : Orissa	Raiguru Basudeipura Via: Balakati District: Khurda PIN: 752100	
Approach 3. Property Type	situated on the right Balakati to Hansapal, kms from Umadei Bra	ft bank of the river Bhargavi is side of the road leading from branching at a distance of 3.2 hmapur canal bridge. It is about <i>i Yogini</i> temple, Hirapur.	
Puildingo	Policious structures	Other Structures	
Buildings Palace	<i>Religious structures</i> ✓ Temple	Wall	
Fort	Mosque	Gateway	
Citadel	Minar	Pillar	
Govt. building	Church	Others (specify)	
Railway station	Monastery		
Defence building	Stupa		
Industrial building	Tomb, Mausoleum		
Other public buildings			
Residential building			
Engineering structure	Open space and related structures	Note: The temple has a <i>pidha vimana</i>	
Bridge	Public square	of impoverish <i>Kalingan</i> order.	
Tunnel	Park or garden		

Graveyard Baolis, Well Tank Cave

Other engineering structure

4. Property Use **ABANDONED / IN USE :** In use Present It is a living temple and the presiding deity is a : patalaphuta Sivalinga within a circular yonipitha which is 1.70 mtrs below the entrance level. Past Worshipped 5 5. Age (Source) PERIOD Survavamsi Gajapati rule YEARS 16th century A.D. Early part of the 16th century A.D Precise date of Construction ÷ Completion 2 ____ Subsequent changes 2 The temple is thickly plastered and white washed. **Destruction / Demolition** 2 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public** : Archaeological Survey of : Endowment Department, Government of Orissa. India 1 State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) Temple Trustee under the presidentship of Nimai 2 Charana Baida. Name Address At - Raiguru Basudeipur, PO - Balakati, Dist. - Khurda, Pin-752100. Orissa Phone • 7. Association WITH EVENTS In History 2 In Rituals Sivaratri, Kartika Purnima, Sankranti, Astaprahari, 2 Yajna, etc are held here. In Building Construction Thread ceremony is held here. Any other (specify) : WITH PERSONS Patron Endowment Department, Government of Orissa under : taken this temple since 1954. Architect / Engineer Any other (specify) **Temple Trustee** : 8. Statement of Significance

Architec	tural	\checkmark	Architectural
Archaec	ological	:	
Historica	al	:	
Religiou	S	\checkmark	Religious
Any othe	er (specify)	:	On the basis of architecture and sculptural grounds, the temple can be dated early part of the 16 th century A.D. i.e. Gajapati rule in Orissa.

SECTION II: DESCRIPTION

Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) : No : Rural setting	
Surroundings	Stand in IsolationStand in isolationIntegral part of a Landscape /Street / Complex :	
Quantification		
Area Dimension (L x B x H)	: 9.36 mtrs x 5.85 mtrs x about 6.00 mtrs (m / cm/ feet / incl	
Number of Blocks	: Two	
Number of Storys	:	
Spatial Organization		
Orientation	: Facing towards east.	
Plan	: The temple has a square vimana and rectangular fl	
Allocation of Chasses	RCC mandapa.	
Allocation of Spaces	: 20.00 mtrs x 15.00 mtrs in length and breadth respectively.	
ARCHITECTURAL STYLE Ornamentation		
Exteriors	Decorated with <i>nayikas</i> , amorous couple, <i>gaja-vidalas</i> dancing male and female etc in the conjunction of the <i>pagas</i> .	
Interiors	: Plain	
Movable Collections	: Hero stone, <i>udyotasimha</i> , pillar members ar architectural fragments.	
* Any Other (specify)	: The temple is <i>pancharatha</i> on plan and <i>panchangabad</i> in elevation.	
10. Construction Technology		
Structural System	: Pidha vimana of impoverish of Kalingan order.	
Building Techniques	: Ashlar masonry.	
Material of Construction	: Sandstone is used for the lower part whereas lateri	
	used for the upper part of the temple. Now the temple thickly plastered and white washed.	
11. Condition Assessment		
In General	Good / Fair : Good	
	Sign of Deterioration	
	Serious Deterioration	
	Danger of Disappearance	

In Brief (Attach extra sheet if necessary)

The temple is in a good state of preservation, except vegetation around the temple premise.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. B. K. Ratha (ed.), 1996, *The Forgotten Monuments of Orissa*, Vol.-3, New Delhi.

14. Photographs: 05 nos

		(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	:	
15. Audio / Video		
		(related to rituals / performance / festivals etc.)
Reference	:	
DESCRIPTION	:	
16. Maps/Plans/Drawings		

17. Listers

NAME : Jaya Shankar Naik NAME :

18.Reviewers

NAME : Dr. S Pradhan COMMENTS NAME : COMMENTS :