

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u> Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: OR / KDA/ BSR- 88

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	<ul> <li>Sanisvara SivaTemple, Kapilaprasad, Bhubaneswar, DistKhurda</li> <li></li> <li></li> </ul>
2. Location	
<b>LONGITUDE</b> 85 <sup>0</sup> 49'65"E	<b>LATITUDE</b> $20^{\circ}13'74"N$ <b>ELEVATION</b> 45 ft.
Address	: Village (village code) Kapileswara Post : Old Town Via: Bhubaneswar Tehsil: Bhubaneswar State : Orissa PIN:751002
Approach	: Located inside the Kpilesvara temple precinct, which is situated at the end of Kapilesvara road leading from Lingaraj temple to Kapilesvara village in the old town of Bhubaneswar.
3. Property Type	
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defense building         Industrial building         Other public buildings         Residential building	Religious structures       Other Structures         Image: Church       Image: Church         Image: Church       Image: Church         Image: Church       Image: Church         Image: Stupa       Image: Church         Image: Tomb, Mausoleum       Image: Church
Engineering structure         Bridge         Tunnel         Other engineering structure	Open space and related structuresNote: The temple has a rekha vimana of Kalingan order.Public square Park or garden Graveyard Baolis, Well Tank CaveNote: The temple has a rekha vimana of Kalingan order.

4. Property Use	
	ABANDONED / IN USE : In use
Present	: Living temple, the presiding deity is a laterite Sivalinga within a circular <i>yonipitha</i> made of sand stone.
Past	: Worshipped
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	<ul> <li>Ganga rule.</li> <li>12<sup>th</sup> century AD</li> <li>12<sup>th</sup> century AD</li> <li></li> <li></li> <li></li> <li></li> </ul>
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE : Multiple
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Endowment Department, Government of Orissa
Private	: Kapilesvara Temple Trust Board
Any other (Please specify) Name	<ul> <li></li> <li>Harihara Mallia is the Chief of the Kapilesvara Temple Trust Board</li> </ul>
Address Phone	: :
7. Association	
<ul> <li>WITH EVENTS In History In Rituals In Building Construction Any other (specify)</li> <li>WITH PERSONS Patron</li> </ul>	<ul> <li></li> <li>Jagara, Sankranti etc are observed.</li> <li></li> <li></li> <li>Originally the Gangas, but now under Kapilesvara Temple Trust Board and Endowment Department, Out of Original</li> </ul>
Architect / Engineer Any other (specify)	Govt. of Orissa.  :
8. Statement of Significance	
ArchitecturalArchaeologicalHistoricalReligiousAny other (specify)	

# **SECTION II: DESCRIPTION**

9. Physical Description and De	corat	tive Features
Context Urban / Rural Setting Surroundings	:	* <b>Drawings</b> (Attach extra sheet if necessary) : No Urban setting
		Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :
Quantification		
Area Dimension (L x B x H)	:	2.50 mtrs. x 2.00 mtrs. x 5.30 mtrs. (m / cm/ feet / inch
Number of Blocks	:	One
Number of Storys	•	
Spatial Organization		
Orientation Plan	:	Facing towards west The temple has a square <i>vimana</i> and a shallow fronta
Allocation of Spaces	:	porch. 
ARCHITECTURAL STYLE		
Ornamentation		The temple is devoid of any departies event in th
Exteriors	:	The temple is devoid of any decoration except in the western wall above the door jamb there is a pilaster a the centre of which is an unidentified female figure with
Interiors	:	splayed out legs. Plain
Movable Collections	:	Nil
* Any Other (specify)	:	The temple has <i>triangabada</i> in elevation & <i>triratha</i> of plan.
10. Construction Technology		
Structural System	:	The temple has <i>rekha vimana</i> of Kalingan order.
Building Techniques Material of Construction	:	Ashlar Dry masonry. Sandstone is used for the temple construction and laterite for foundation.
11. Condition Assessment		
In General Good / Fair	:	Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary): The temple is in a fair condition due to the proper care & maintenance by the Kapilesvara Temple trust Board.

# 12. Threats to the Property

	Natural
	Negligence
	Vandalism
√	Urban Pressures

## **SECTION III:** REFERENCES

**13. Reference Sources** (published and unpublished textual details)

14. Photogra	phs		
		(Attach list as in page 6, in case of multiple photograph	าร)
Photo Refere CAPTION	nce	:	
15. Audio / Vi	ideo		
		(Related to rituals / performance / festivals et	<u>c.)</u>
Reference DESCRIPTIO	N	:	
16. Maps/Pla	ns/Drawings		
17. Listers			
NAME :	J. S. Naik	NAME :	
18. Reviewer	s		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	