

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

#### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR / KDA/ BSR- 135

**SECTION I: IDENTIFICATION** 1. Name Siva Temple No. VIII, Muktesvara Temple Complex, Present Bhubaneswar, Dist.-Khurda. **Past** Other Name (if any): 2. Location **LONGITUDE** 85°50'26"E 20<sup>0</sup>14'33"N LATITUDE **ELEVATION** 52 ft Address Village (village code) Temple Muktesvara Complex, Old Town Post: Old Town Via: Old Town **Tehsil:** Bhubaneswar District: Khurda State: Orissa **PIN**: 751002 Approach The temple is located within the precinct of Mukteswar temple, old town, and on the right side of the road leading from Bhubaneswar to Puri. 3. Property Type Buildings Religious structures Other Structures Wall Palace Temple Gateway Fort Mosaue Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures It is a rekha temple of Kalingan Public square Bridge order. The temple stands over Tunnel Park or garden a platform with a miniature Other engineering structure Graveyard rekha temple attached to it. Baolis, Well Tank Cave

4 Dranarty Has					
4. Property Use	ABANDONED / IN USE: Abandoned				
Present Past	: Abandoned, but a tourist point of attraction. : Worshipped				
5. Age (Source)					
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	<ul> <li>Somavansis rule</li> <li>10<sup>th</sup> century AD</li> <li></li> <li>Repaired and renovated by Archaeological Survey of India.</li> <li></li> </ul>				
6. Ownership / Level of Protectio	on				
	SINGLE /MULTIPLE : Single				
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Protected Monument of Archaeological Survey of India.				
Private Any other (Please specify) Name Address Phone	<ul> <li>:</li> <li>:</li> <li>: Archaeological Survey of India, Bhubaneswar circle</li> <li>: 153, VIP Area, Nayapali, Bhubaneswar, Orissa</li> <li>: 0674- 2558170</li> </ul>				
7. Association					
WITH EVENTS In History In Rituals In Building Construction Any other (specify)     WITH PERSONS Patron Architect / Engineer Any other (specify)      Statement of Significance	: : Sivaratri, Sitalasasthi etc. : : : Archaeological Survey of India. : :				
In History In Rituals In Building Construction Any other (specify)  • WITH PERSONS Patron Architect / Engineer	: :				

Architectural	$\checkmark$	Architectural
Archaeological	:	
Historical	:	
Religious	$\checkmark$	Religious
Any other (specify)	:	On the basis of building technique and plan, the temple can be dated to the 10 <sup>th</sup> century AD.

# **SECTION II: DESCRIPTION**

9. Physical Description and Dec	orat	ive Features
Context Urban / Rural Setting Surroundings	:	* <b>Drawings (</b> Attach extra sheet if necessary) : No Urban Setting
		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
• Quantification Area Dimension ( L x B x H)	:	<ul> <li>A. 1.75 mtrs x 1.50 mtrs x 3.15 mtrs</li> <li>B. 1.00 mtrs x 1.00 mtrs x 2.00 mtrs (miniature temple attached to the main temple)</li> <li>(m / cm/ feet / inch</li> </ul>
Number of Blocks	:	One (III 7 of the feet 7 inter-
Number of Storys	:	
Spatial Organization		
Orientation	:	Facing towards west
Plan	:	Square on plan
Allocation of Spaces	:	3.10 mtrs (L) x 1.90 mtrs (W)
ARCHITECTURAL STYLE		
Ornamentation		Dloin
Exteriors Interiors		Plain Plain
Movable Collections	:	
* Any Other (specify)	:	The temple <i>pancharatha</i> on plan and <i>triangabada</i> ir elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction	: : :	Rekha vimana Ashlar dry masonry Sand stone.
11. Condition Assessment		
In General Good / Fair  ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Good
In Brief (Attach extra sheet if ne	cess	sary):
It is in a good state of preservation		
12. Threats to the Property		
	<b>✓</b>	Natural
		Negligence
		Vandalism

	<b>Urban Pressures</b>
--	------------------------

## 

### **SECTION III: REFERENCES**

	<u>~</u>				
13. Reference Sources (published and unpublished textual details)					
1. 2.					
14. Photogra	phs: 04 nos				
			(attach list as in page 6, in case of multiple photographs)		
Photo Refere CAPTION	nce	:			
15. Audio / Vi	deo				
			(related to rituals / performance / festivals etc.)		
Reference DESCRIPTIO	N	:			
16. Maps/Plans/Drawings					
17. Listers					
NAME:	D. B. Garnayak		NAME:		
18. Reviewers	18. Reviewers				
NAME: COMMENTS	Dr. S. Pradhan		NAME: COMMENTS:		