

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 242

SECTION I: IDENTIFICATION			
1. Name			
Present	: Bhubanesvari Temple (Temple No 90), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda		
Past Other Name (if any): 2. Location	: : Gopalini Temple		
LONGITUDE 85°50′05″ E	LATITUDE 20 ⁰ 14 ² 26 N ELEVATION 70 ft.		
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002		
Approach	: The temple, on the north of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar.		
3. Property Type			
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a khakhara vimana and pidha jagamohana of Kalingan order.		

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is the goddess Bhubanesvari. **Past** Worshipped 5. Age (Source) PERIOD Ganga rule 12th century AD. YEARS **Precise date of Construction** Completion Subsequent changes Lime plaster was applied later on. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of: Protected monument of Archaeological Survey of India State Archaeology India 1 Department / Any Other (Please specify) Lingaraja Temple Trust Board maintains the rituals of **Private** the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name Archaeological Survey of India, Bhubaneswar Circle, **Address** 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674-2558170 **Phone** 7. Association WITH EVENTS In History In Rituals Solapuja is performed here. In Building Construction Any other (specify) WITH PERSONS Patron Archeological Survey of India and Endowment Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 8. Statement of Significance Architectural Architectural

Religious

Archaeological Historical

Any other (specify)

Religious

The Bhubanesvari temple is at a lower level than the Parvati temple, which belongs to the 13th century AD. And it is very close to the grand lingaraja which could not have existed in the 11th century when the main temple of the lingaraja was erected. Therefore, it seems that this Bhubanesvari temple was erected in the 12th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context * Drawings (Attach extra sheet if necessary) : No

Urban / Rural Setting

Surroundings

Stand in Isolation Complex

Integral part of a Landscape

/ Street / Complex :

Quantification

Area Dimension (LxBxH) : 13.00 mtrs x 6.50 mtrs x 8.00 mtrs (approximate

height)

(m / cm/ feet / inch)

Urban setting

Number of Blocks : Two Number of Storys : N.A.

Spatial Organization

Orientation : Facing towards East.

Plan : The *vimana* is oblong on plan whereas the

jagamohana is square and the later stands on a low

platform.

Allocation of Spaces : 158.49 mtrs x 141.73 mtrs in length and breadth

respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Devoid of any decorations except three miniature

rekha temple on the frontal raha of the vimana.

Interiors : Plain Movable Collections : Nil

* **Any Other** (specify) : The temple is *pancharatha* on plan and *triangabada* in

elevation.

10. Construction Technology

Structural System : Khakhara vimana and a pidha jagamohana of Kalingan

order.

Building Techniques : Ashlar dry masonry

Material of Construction : Sandstone is used for the construction of the temple

and the exterior surface is lime plastered.

11. Condition Assessment

Serious D	Good / Fair : eterioration eterioration Disappearance	Good
In Brief (Atta	ch extra sheet if neces	sary):
The temple is mutilated.	s in a good state of pre	servation but the <i>parsvadevata</i> images are eroded and
12. Threats to	the Property	
x x x x x x x :	××××××××××××××××××××××××××××××××××××××	Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
	SEC1	TION III: REFERENCES
13. Reference	e Sources (published ar	nd unpublished textual details)
Delhi.	nera, 2008, <i>The Lingaraj</i> Iitra, 1961, <i>Bhubaneswa</i>	a Temple of Bhubaneswar, Art and Cultural Legacy, New er, ASI, New Delhi.
14. Photogra	phs: 29 nos	
Photo Referer	nce :	(attach list as in page 6, in case of multiple photograph
15. Audio / V	ideo	
Reference DESCRIPTIO	: N :	(related to rituals / performance / festivals etc
16. Maps/Pla	ns/Drawings	
17. Listers		
NAME :	Jaya Shankar Naik	NAME :
18. Reviewer	s	
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :