

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 245

SECTION I: IDENTIFICATION					
1. Name					
Present Past Other Name (if any): 2. Location	 Dakshina Kali Temple (Temple No -122), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda 				
LONGITUDE 85°50'05" E	LATITUDE 20°14'26" N ELEVATION 70 ft.				
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002				
Approach	: The temple, on the north-east of the Grand Lingaraja temple within the complex is situated in Old Town, Bhubaneswar.				
3. Property Type					
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum				
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a pidha vimana of impoverished Kalingan style.				

4. Property Use ABANDONED / IN USE: In use Living temple, the presiding deity is a four-armed Present goddess holding lotus, trident, wheel and khadga and stands over a prostrate male figure. **Past** Worshipped 5. Age (Source) PERIOD Suryavamsi Gajapati rule 16th century AD YEARS Second half of the 16th century AD **Precise date of Construction** Completion Subsequent changes Lime plaster applied over the temple later on. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Protected monument of Archaeological Survey of State Archaeology India India. Department / Any Other (Please specify) Private Lingaraja Temple Trust Board maintains the rituals of the temple. Endowment Department, Government of Orissa Any other (Please specify) manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674-2558170 Phone 7. Association WITH EVENTS In History In Rituals : Dugapuja, Kalipuja, etc. In Building Construction Any other (specify) Thread ceremony, engagements, etc. WITH PERSONS Archeological Survey of India and Endowment Patron Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 9 Statement of Significance

0	. Statement of Significance		
	Architectural	✓	Architectural
	Archaeological		
	Historical		
	Religious	✓	Religious
	Any other (specify)	:	

On the basis of iconographical feature of the presiding deity, the temple can be dated to second half of the $16^{\rm th}$ century AD

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) : No Urban setting			
ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex		
• Quantification Area Dimension (L x B x H)	:	2.30 mtrs x 2.25 mtrs x 4.00 mtrs	(m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	One N.A.	(III / GIII/ IGGE / IIIGII)		
 Spatial Organization Orientation Plan Allocation of Spaces 	:	Facing towards east. A square <i>vimana</i> that stands over mtrs in height. 158.49 mtrs x 141.73 mtrs in length respectively.	•		
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	: : :	Devoid of any artistic decorations in Plain Nil The temple is <i>triangabada</i> in eleviplan.	·		
10. Construction Technology					
Structural System Building Techniques Material of Construction	:	Pidha vimana of Kalingan order. Ashlar dry masonry Laterite is used both for the temple of the pista whereas the upper based and the exterior surface.	ase of the <i>pista</i> is in		
11. Condition Assessment					
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Good			
In Brief (Attach extra sheet if ned	cess	sary):			

The temple is in a good state of preservation.

12. Threats to the Property					
	Natural Negligence Vandalism Urban Pressures				
SECT	ION III: REFERENCES				
13. Reference Sources (published and	d unpublished textual details)				
1. K. S. Behera, 2008, <i>The Lingaraja</i> Delhi.	a Temple of Bhubaneswar, Art and Cultural Legacy, New				
2. Debala Mitra, 1961, <i>Bhubaneswar</i>	, ASI, New Delhi.				
14. Photographs: 02 nos					
<u> </u>	(attach list as in page 6, in case of multiple photographs)				
Photo Reference : CAPTION :					
15. Audio / Video					
	(related to rituals / performance / festivals etc.)				
Reference : DESCRIPTION :					
16. Maps/Plans/Drawings					
17. Listers					
NAME: Jaya Shankar Naik	NAME :				
18. Reviewers					
NAME: Dr. S. Pradhan COMMENTS	NAME : COMMENTS :				