



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR – 246

SECTION I : IDENTIFICATION

1. Name

Present : Ekadasi Mahadeva Temple (Temple No.- 34), Lingaraja Temple Complex, Bhubaneswar, Dist. - Khurda

Past : ----

Other Name (if any): : ----

2. Location

LONGITUDE 85°50'05" E **LATITUDE** 20°14'26" N **ELEVATION** 70 ft.

Address : **Village (village code)** Lingaraja Temple Complex
Post : Old Town **Via**: Old Town, Bhubaneswar
Tehsil: Bhubaneswar **District**: Khurda
State : Orissa **PIN**: 751002

Approach : The temple is located at a distance of 5.00 mtrs south of the Grand Lingaraja temple and just behind the Baakhia *mandapa* within the complex in Old Town, Bhubaneswar.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note.

The temple has a *rekha vimana* of *Kalingan* order.

4. Property Use

ABANDONED / IN USE : In use

Present : Living temple, the presiding deity is a Sivalinga within a circular *yonipitha*.
Past : Worshipped

5. Age (Source)

PERIOD : Ganga rule
YEARS : 15th century AD
Precise date of Construction Completion : ---
Subsequent changes : The temple is renovated and conserved by Archaeological Survey of India.
Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE / MULTIPLE : Multiple

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) : Protected monument of Archaeological Survey of India
Private : Lingaraja Temple Trust Board maintains the rituals of the temple.
Any other (Please specify) : Endowment Department, Government of Orissa manages the property of the temple.
Name : ---
Address : Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone : 0674- 2558170

7. Association

• **WITH EVENTS**

In History : ---
In Rituals : *Sivaratri, Kartika Purnima, Ekadasi, etc.*
In Building Construction : ---
Any other (specify) : Thread ceremony, engagement, etc held here.

• **WITH PERSONS**

Patron : Archeological Survey of India and Endowment Department, Government of Orissa.
Architect / Engineer : ---
Any other (specify) : Lingaraja Temple Trust Board

8. Statement of Significance

<input type="checkbox"/>	Architectural	✓	Architectural
<input type="checkbox"/>	Archaeological		
<input type="checkbox"/>	Historical		
<input type="checkbox"/>	Religious	✓	Religious
<input type="checkbox"/>	Any other (specify)	:	On architectural ground, the temple can be dated to the late Ganga rule.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings (Attach extra sheet if necessary)** : No
- Urban / Rural Setting** : Urban setting
- Surroundings** : Stand in Isolation : Complex
Integral part of a Landscape
/ Street / Complex :

- **Quantification**
- Area Dimension (L x B x H) : 4.20 mtrs x 3.65 mtrs x 8.00 mtrs (approximate height)
(m / cm/ feet / inch)
- Number of Blocks : One
- Number of Storys : N.A.

- **Spatial Organization**
- Orientation : Facing towards east.
- Plan : Consists of a square *vimana* that stands on a low platform 0.40 mtrs in height.
- Allocation of Spaces : 158.49 mtrs x 141.73 mtrs in length and breadth respectively.

ARCHITECTURAL STYLE

- **Ornamentation**
- Exteriors : Devoid of any decorations except the *udyotasimha* in all *raha*, *dopichhasimha* and *beki-bhairava* over the *beki* and a miniature *rekhamundi* surmounted by a *gaja-kranta* motif on the frontal *raha*.
- Interiors : Plain
- Movable Collections : Nil
- * **Any Other** (specify) : The temple is *pancharatha* on plan and *panchangabada* in elevation.

10. Construction Technology

- Structural System** : *Rekha vimana* of *Kalingan* order.
- Building Techniques** : Ashlar dry masonry
- Material of Construction** : Sandstone is used for the construction of the temple.

11. Condition Assessment

In General **Good / Fair** :

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation due to recent renovation work.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

x x

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar, Art and Cultural Legacy*, New Delhi.
2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.

14. Photographs: 06 nos

(attach list as in page 6, in case of multiple photographs)

Photo Reference :
 CAPTION :

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference :
 DESCRIPTION :

16. Maps/Plans/Drawings

17. Listers

NAME : Jaya Shankar Naik NAME :

18. Reviewers

NAME : Dr. S. Pradhan NAME :
 COMMENTS COMMENTS :