

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 247 **SECTION I: IDENTIFICATION** 1. Name Present Ekambaresvara Temple (Temple No.- 101), Lingaraja Temple Complex, Bhubaneswar, Dist. - Khurda **Past** Other Name (if any): 2. Location LONGITUDE 85°50'05" E LATITUDE 20⁰14²6⁸ N **ELEVATION** 70 ft. **Address** Village (village code) Lingaraja Temple Complex Via: Old Town. Bhubaneswar Post: Old Town Tehsil: Bhubaneswar District: Khurda **PIN:** 751002 State: Orissa **Approach** The temple, on the north of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar 3. Property Type Buildings Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Minar Citadel Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note. structures The temple has a rekha Bridge Public square vimana of kalingan order. Park or garden Tunnel Gravevard Other engineering structure Baolis, Well Tank Cave

4. Property Use

ABANDONED / IN USE: In use

Present : Living temple, the presiding deity is a circular *yonipitha*

without *Lingam*, which is 1.70 mtrs below the entrance

level.

Past : Worshipped

5. Age (Source)

PERIOD : Somavamsi rule YEARS : 11th century AD.

Precise date of Construction : -- Completion : --

Subsequent changes : Renovated and conserved by Archaeological Survey of

India.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE / MULTIPLE : Multiple

Public: Archaeological Survey of : Protected monument of Archaeological Survey of India

India / State Archaeology Department / Any Other (Please

specify)

Private : Lingaraja Temple Trust Board maintains the rituals of

the temple.

Any other (Please specify) : Endowment Department, Government of Orissa

manages the property of the temple.

Name : ---

Address : Archaeological Survey of India, Bhubaneswar Circle,

153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.

Phone : 0674- 2558170

7. Association

WITH EVENTS

In History : --

In Rituals : Sivaratri, Sankranti, Kartika Purnima, etc.

In Building Construction :

Any other (specify) : Thread ceremony, engagements, etc are held here.

WITH PERSONS

Patron : Archeological Survey of India and Endowment

Department, Government of Orissa.

Architect / Engineer : ---

Any other (specify) : Lingaraja Temple Trust Board

8. Statement of Significance

Architectural ✓ Architectural
Archaeological
Historical

Religious ✓ Religious

Any other (specify) :

On the basis of its architectural features which have it affinity to the Rajarani and Dakra Bhimesvara, the temple can be dated to the 11th century and could be earlier than the Brahmesvara and Lingaraja temple.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

* Drawings (Attach extra sheet if necessary) : No Context Urban setting

Urban / Rural Setting

Surroundings

Stand in Isolation Complex

Integral part of a Landscape

/ Street / Complex :

Quantification

9.00 mtrs x 8.20 mtrs x 13.00 mtrs (approximate Area Dimension (LxBxH)

height)

(m / cm/ feet / inch)

Number of Blocks One Number of Storys N.A.

Spatial Organization

Orientation Facing towards west.

Plan The *vimana* is square on plan.

158.49 mtrs x 141.73 mtrs in length and breadth Allocation of Spaces

respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors Decorated with architectural motifs like miniature anga

sikharas on the base of the gandi in all pagas, decorative features like- udyotasimha in all raha, deulacharinis and dopichhasimhas on the beki to support the amal stone. The doorjambs have three sakhas and pidhamundi houses with dvarapala figures

at the base.

Interiors Plain Movable Collections Nil

* Any Other (specify) The pancharatha temple is on plan and

panchangabada in elevation.

10. Construction Technology

Structural System Rekha vimana of Kalingan order.

Building Techniques Ashlar dry masonry

Material of Construction Sandstone is used for the construction of the temple.

11. Condition Assessment

In General Good / Fair : Good

Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet if necessary):
The temple is in a good state of preservation due to the renovation work.
12. Threats to the Property
✓ Natural Negligence Vandalism ✓ Urban Pressures x x x x x x x x x x x x x x x x x x x
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
1. K. S. Behera, 2008, The Lingaraja Temple of Bhubaneswar, Art and Cultural Legacy, New
Delhi. 2. Debala Mitra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi.
14. Photographs: 23 nos
(attach list as in page 6, in case of multiple photographs)
Photo Reference : CAPTION :
15. Audio / Video
(related to rituals / performance / festivals etc.)
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME : Jaya Shankar Naik NAME :
18. Reviewers
NAME: Dr. S. Pradhan NAME: COMMENTS: