

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 249

	SECTION I: IDENTIFICATION
1. Name	
Present Past Other Name (if any): 2. Location	 Gouri-Sankara Temple (Temple No 83), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
LONGITUDE 85°50'05" E	LATITUDE 20°14'26" N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, on the north-west of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. **Ralingan** style. The temple is in dilapidated condition as the upper portions of the gandi, including the crowning elements are missing.

4. Property Use ABANDONED / IN USE: In use Living temple, the presiding deities are a Sivalinga **Present** within a circular vonipitha and a four-armed standing Parvati attached to the back wall of the temple. **Past** Worshipped 5. Age (Source) **PERIOD** Ganga rule 14th century AD YEARS Precise date of Construction Completion Renovated and conserved by Archaeological Survey of Subsequent changes India. **Destruction / Demolition** Now the upper portion of the gandi including the mastaka is missing. 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple Protected monument of Archaeological Survey of India **Public**: Archaeological Survey of: India 1 State Archaeology Department / Any Other (Please specify) **Private** Lingaraja Temple Trust Board maintains the rituals of the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674-2558170 **Phone** 7. Association WITH EVENTS In History Sivaratri, Sankranti, Ekadasi, Kartika Purnima, etc In Rituals performed here. In Building Construction Any other (specify) Thread ceremony performed here. WITH PERSONS Patron Archeological Survey of India and Endowment Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 8. Statement of Significance Architectural Architectural Archaeological Historical Religious

Any other (specify)	:	On architectural ground and iconographical feature of the presiding deity Parvati, the temple may be assigned to the 14 th century AD.		
SE	<u> C</u>	TION II: DESCRIPTION		
9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Urban setting		
Surroundings		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :		
 Quantification Area Dimension (L x B x H) 	:	5.00 mtrs x 4.35 mtrs x 7.00 mtrs (existing height)		
Number of Blocks Number of Storys	:	One N.A.		
 Spatial Organization Orientation Plan Allocation of Spaces 	: :	Facing towards east. The <i>vimana</i> is square on plan. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.		
ARCHITECTURAL STYLE Ornamentation				
Exteriors	:	Decorated with projecting lion on the <i>rahas</i> and the front face of the <i>raha</i> decorated with a central <i>khakharamundi</i> , flanked by miniature <i>rekha sikharas</i> on either side.		
Interiors Movable Collections * Any Other (specify)	: :	Plain Nil The temple is <i>pancharath</i> a on plan and <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System Building Techniques Material of Construction	:	Rekha vimana of Kalingan order. Ashlar dry masonry Sandstone is used for the construction of the temple.		
11. Condition Assessment				
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Good		
In Brief (Attach extra sheet if ned	cess	sary):		

The existing temple is in a good state of preservation due to the renovation work.
12. Threats to the Property
✓ Natural Negligence Vandalism ✓ Urban Pressures ××××××××××××××××××××××××××××××××××××
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
1. K. S. Behera, 2008, <i>The Lingaraja Temple of Bhubaneswar</i> , <i>Art and Cultural Legacy</i> , New Delhi.
2. Debala Mitra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi.
14. Photographs: 07 nos
(attach list as in page 6, in case of multiple photographs)
Photo Reference : CAPTION :
15. Audio / Video
(related to rituals / performance / festivals etc.)
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME : Jaya Shankar Naik NAME :
18. Reviewers

NAME : COMMENTS :

NAME:

COMMENTS

Dr. S. Pradhan