

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 250

SECTION I : IDENTIFICATION			
1. Name			
Present Past Other Name (if any): 2. Location		(Temple No 14), Lingaraja baneswar, Dist Khurda	
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 N	ELEVATION 70 ft.	
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa	Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002	
Approach		I on the south-east of the Grand ne complex in Old Town,	
3. Property Type			
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note. The temple, locally called as Guptesvara is of <i>rekha</i> order of <i>Kalingan</i> style.	

4. Property Use

ABANDONED / IN USE: In use Living temple, the presiding deity is a Sivalinga within Present a circular yonipitha. Worshipped **Past** 5. Age (Source) PERIOD Suryavamsi Gajapati rule 16th century AD **YEARS** Second half of the 16th century AD. Precise date of Construction Completion Subsequent changes The temple was renovated and conserved by Archaeological Survey of India. **Destruction / Demolition** The crowning element is missing now. 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of: Protected monument of Archaeological Survey of India India State Archaeology Department / Any Other (Please specify) Private Lingaraja Temple Trust Board maintains the rituals of the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674-2558170 **Phone** 7. Association • WITH EVENTS In History In Rituals Sivaratri, Kartika Purnima, Sankranti, etc. In Building Construction Thread ceremony, engagements Any other (specify) • WITH PERSONS Archeological Survey of India and Endowment Patron Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 8. Statement of Significance Architectural Architectural Archaeological Historical Religious Religious Any other (specify)

On architectural ground, the temple can be assigned to the late Suryavamsi Gajapati rule i.e. about the second half of the 16th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	/ Rural Setting : Urban s		f necessary) : No Urban setting	
		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex	
Quantification				
Area Dimension (LxBxH)	:	3.30 mtrs x 2.50 mtrs x 5.00 mtrs	(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	One N.A.	(III / Citi/ leet / ilicit)	
Spatial Organization				
Orientation	:	Facing towards west.		
Plan	:	The <i>vimana</i> is square on plan.		
Allocation of Spaces	:	158.49 mtrs x 141.73 mtrs in length and breadth respectively.		
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	:	Devoid of any decoration except the <i>dvarapala</i> image houses in the <i>pidhamundi</i> niches at the base of the doorjambs, Gaja-Laxmi in the lintel and the <i>navagraha</i> panel in the architrave.		
Interiors	:	Plain		
Movable Collections	:	Nil		
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.		
10. Construction Technology				
Structural System	:	Rekha vimana of Kalingan order.		
Building Techniques	:	Ashlar dry masonry		
Material of Construction	:	Sandstone is used for the construction	ction of the temple.	
11. Condition Assessment				
	ete Di	rioration sappearance		
In Brief (Attach extra sheet if nece	ess	sary):		

The temple is in a good state of preservation due to the renovation work.

12. Threats to the Property
✓ Natural Negligence Vandalism ✓ Urban Pressures xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
 K. S. Behera, 2008, The Lingaraja Temple of Bhubaneswar, Art and Cultural Legacy, New Delhi.
 Debala Mitra, 1961, Bhubaneswar, ASI, New Delhi. 3.
14. Photographs: 05 nos
(attach list as in page 6, in case of multiple photograph
Photo Reference : CAPTION :
15. Audio / Video
(related to rituals / performance / festivals etc
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME : Jaya Shankar Naik NAME :
18. Reviewers
NAME : Dr. S. Pradhan NAME : COMMENTS : COMMENTS :