

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 253

SECTION I : IDENTIFICATION 1. Name	
Present Past Other Name (if any): 2. Location	 : Kartikeya Temple (Temple No 95), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda : :
LONGITUDE 85°50'05" E	LATITUDE 20°14'26" N ELEVATION 70 ft. : Village (village code) Lingaraja Temple Complex
Approach	Post: Old Town Tehsil: Bhubaneswar State: Orissa The temple, on the north of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a rekha vimana of kalingan order and a vahana stamba in front of the entrance at a short distance, is surmounted by a peacock.

4. Property Use ABANDONED / IN USE: In use Living temple, the presiding deity is a standing figure of Present Kartikeva, whose upper part is only visible. He is distinguished by sikhandaka hair and peacock vehicle. Past Worshipped 5. Age (Source) PERIOD Somavamsi rule YEARS 12th century AD. **Precise date of Construction** Completion Subsequent changes Renovated and conserved by Archaeological Survey of India. **Destruction / Demolition** ---6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple Protected monument of Archaeological Survey of India **Public**: Archaeological Survey of : State Archaeology India / Department / Any Other (Please specify) Private Lingaraja Temple Trust Board maintains the rituals of the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. **Phone** 0674-2558170 7. Association WITH EVENTS In History In Rituals Kumarpurnima is celebrated here. In Building Construction Any other (specify) Thread ceremony, engagements, etc held here. **WITH PERSONS Patron** Archeological Survey of India and Endowment Department, Government of Orissa. Architect / Engineer Lingaraja Temple Trust Board Any other (specify) 8. Statement of Significance Architectural Architectural Archaeological Historical

Religious

Any other (specify)

On architectural ground and iconographical feature of the surviving *parsvadevata* images on the northern and eastern side, the temple can be dated to the late Somavamsi rule.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Fea
--

• Context * Drawings (Attach extra sheet if necessary) : No

Urban / Rural Setting

Surroundings

Urban setting

Stand in Isolation Complex

Integral part of a Landscape

/ Street / Complex :

Quantification

Area Dimension (L x B x H) : 5.50 mtrs x 4.75 mtrs x 9.50 mtrs (approximate height)

(m / cm/ feet / inch)

Number of Blocks : One Number of Storys : N.A.

Spatial Organization

Orientation : Facing towards south.

Plan : A square *vimana* fronted by a circular basa vahana

stamba.

Allocation of Spaces : 158.49 mtrs x 141.73 mtrs in length and breadth

respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Decorated with architectural motifs like

khakharamundis and pidhamundis in the lower and upper jangha respectively; three miniature temple, one khakharamundi in the center and two rekhamundis on the sides in the frontal raha; decorative figures like-udyotasimha is seen on each face on the raha and

deulacharini on the beki to support the amla.

Interiors : Plain Movable Collections : Nil

* Any Other (specify) : The temple is pancharatha on plan and

panchangabada in elevation.

10. Construction Technology

Structural System : Rekha vimana of Kalingan order.

Building Techniques : Ashlar dry masonry

Material of Construction : Sandstone is used for the construction of the temple.

11. Condition Assessment

In General Good / Fair : Good

Sign of Deterioration

Serious Deterioration Danger of Disappearance		
In Brief (Attach extra sheet if necessary):		
The temple is in a good state of preservation except the eroded and mutilated <i>parsvadevata</i> images on the northern and eastern <i>raha</i> niches.		
12. Threats to the Property		
Natural Negligence Vandalism ✓ Urban Pressures x x x x x x x x x x x x x x x x x x x		
SECTION III: REFERENCES		
13. Reference Sources (published and unpublished textual details)		
1. K. S. Behera, 2008, The Lingaraja Temple of Bhubaneswar, Art and Cultural Legacy, New		
Delhi. 2. Debala Mitra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi. 3. 4.		
14. Photographs: 21 nos		
(attach list as in page 6, in case of multiple photographs)		
Photo Reference : CAPTION :		
15. Audio / Video		
(related to rituals / performance / festivals etc.) Reference : DESCRIPTION :		
16. Maps/Plans/Drawings		
17. Listers		
NAME : Jaya Shankar Naik NAME :		
18. Reviewers		
NAME : Dr. S. Pradhan NAME : COMMENTS :		