

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR / KDA / BSR - 254

1. Name	SECTION I: IDENTIFICATION
Present  Past Other Name (if any):  2. Location	<ul> <li>Kasivisvanath Temple (Temple No -71), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda</li> <li></li> <li></li> </ul>
LONGITUDE 85°50'05" E	<b>LATITUDE</b> 20°14'26" N <b>ELEVATION</b> 70 ft
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa  Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, on the north- west of Grand Lingaraja and adjoining the Parvati temple within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures  Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum  Other Structures  Wall Gateway Pillar Others (specify)
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave  Note. The temple has a rekha vimana of Kalingan order.

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is a Siva-linga within a circular yonipitha. **Past** Worshipped 5. Age (Source) PERIOD Somavamsi rule 12<sup>th</sup> century A.D. YEARS First quarter of the 12<sup>th</sup> century A.D. **Precise date of Construction** Completion Subsequent changes Traces of lime plaster are found on the exterior surface and the temple is repaired and conserved by Archeological Survey of India. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple Public: Archaeological Survey of: Protected monument of Archaeological Survey of State Archaeology India. India / Department / Any Other (Please specify) Private Lingaraja Temple Trust Board maintains the rituals of the temple Endowment Department, Government of Orissa Any other (Please specify) manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153, VIP Area, Nayapalli, Bhubaneswar, Orissa. **Phone** 0674-2558170 7. Association WITH EVENTS In History In Rituals Sivaratir, Sankranti, Kartika Purnima, etc are observed here. In Building Construction Any other (specify) Thread ceremony is performed here. WITH PERSONS **Patron** Archaeological Survey of India and Endowment Department, Government of Orissa Architect / Engineer

8. Statement of Significance		
Architectural Archaeological	✓	Architectural
Historical		D. K. C
Religious	✓	Religious
Any other (specify)	:	On architectural ground and iconographical features of the

Lingaraja Temple Trust Board

Any other (specify)

parsvadevata images, the temple can be dated to the late Somavamsi rule i.e. the first quarter of the 12<sup>th</sup> century A.D.

## SECTION II: DESCRIPTION

9. Physical Description and Deco	orative Features
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings (</b> Attach extra sheet if necessary) No Urban setting
<b>3</b>	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
• Quantification Area Dimension ( L x B x H)	: 6.00 mtrs x 4.80 mtrs x 10.00 mtrs (approximate height)
Number of Blocks Number of Storys	(m / cm/ feet / inch) : One : N.A.
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul>	<ul> <li>Facing towards east.</li> <li>The <i>vimana</i> is square on plan.</li> <li>158.49 mtrs x 141.73 mtrs in length and breadth respectively.</li> </ul>
ARCHITECTURAL STYLE  Ornamentation	
Exteriors	: Decorated with five angasikharas, three on the central flank and two on the sides on the frontal raha and the projecting lion is seen on each raha. The doorjambs have remnants of three sakhas and dvarapala images along with river goddess Ganga and Yamuna houses in the khakharamundis at the base.
Interiors	: Plain
Movable Collections * Any Other (specify)	<ul><li>Nil</li><li>The temple is <i>pancharatha</i> on plan and <i>panchanga</i> bada in elevation.</li></ul>
10. Construction Technology	
Structural System Building Techniques Material of Construction	<ul><li> Rekha vimana of Kalingan order.</li><li> Ashlar dry masonry</li><li> Sandstone is used for the construction of the temple.</li></ul>
11. Condition Assessment	
In General	Good / Fair : Good Sign of Deterioration Serious Deterioration

	Danger of Disappearance	
In Brief (Attac	h extra sheet if necessary):	
Except the brok	ken projection lion on the <i>raha</i> , the temple is in a good state	of preservation.
12. Threats to	the Property	
	✓ Natural Negligence Vandalism ✓ Urban Pressures	
* * * * * * *	× × × × × × × × × × × × × × × × × × ×	
	SECTION III: REFERENCES	
13. Reference	Sources (published and unpublished textual details)	
Delhi.	era, 2008, <i>The Lingaraja Temple of Bhubaneswar</i> , Art and ( itra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi.	Cultural Legacy, New
14. Photograp	hs: 19 nos (attach list as in page 6, in case of	multiple photographs
Photo Reference CAPTION		autro priotograpii.
15. Audio / Vid	deo	
	(related to rituals / perfor	mance / festivals etc
	:	
Reference DESCRIPTION 16. Maps/Plans		
DESCRIPTION		
DESCRIPTION  16. Maps/Plan		
DESCRIPTION		
DESCRIPTION  16. Maps/Plans  17. Listers	s/Drawings	