INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR – 255

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	 Ladukesvara Temple (Temple No 62), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 [°] N ELEVATION 70 ft.
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach 3. Property Type	: The temple, on the west of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar
5. Flopenty Type	
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresOther StructuresImage: ChurchWallMinarPillarChurchOthers (specify)MonasteryStupaTomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public square Park or gardenThe temple has a rekha vimana of Kalingan order.Graveyard Baolis, Well Tank CaveCave

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a Sivalinga upon a circular <i>yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion	:	Ganga rule 12 th century AD First half of the 12 th century AD
Subsequent changes	:	Renovated and conserved by Archaeological Survey of India and lime wash applied in the interior surface of the temple.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Archaeological Survey of India
Private	:	Lingaraja Temple Trust Board maintains the rituals of the temple.
Any other (Please specify)	:	Endowment Department, Government of Orissa manages the property of the temple.
Name Address	:	 Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	:	0674- 2558170
7. Association		
WITH EVENTS		
In History	÷	 Siverstri Sankranti Kartika Duraima ata
In Rituals In Building Construction	•	Sivaratri, Sankranti, Kartika Purnima, etc.
 Any other (specify) WITH PERSONS 	:	Thread ceremony & engagements held here.
Patron	:	Archeological Survey of India and Endowment Department, Government of Orissa.
Architect / Engineer	:	
Any other (specify)	:	Lingaraja Temple Trust Board
8. Statement of Significance		
Architectural Archaeological Historical	~	Architectural
Religious Any other (specify)	✓ :	Religious

On the basis of architectural ground and iconographical feature of the *parsvadevata* images, the temple may be assigned to the early Ganga rule i.e. about the first half of the 12th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Urban setting
Sunounungs		Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :
Quantification Area Dimension (L x B x H) Number of Blocks	:	6.50 mtrs x 5.05 mtrs x 9.20 mtrs (approximate height) (m / cm/ feet / inch) One
Number of Storys	:	N.A.
• Spatial Organization Orientation Plan Allocation of Spaces		Facing towards east. It consists of a square <i>vimana</i> only. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE Ornamentation 		
Exteriors	:	Decorated with architectural motifs like- <i>khakharamundis</i> and <i>pidhamundis</i> in the lower and upper <i>jangha</i> respectively; cluster of three miniature temples, one <i>khakhramundi</i> in the centre flanked by <i>pidhamundis</i> on the frontal <i>raha</i> and decorative motifs like – <i>gajakranta</i> above a <i>kirtimukha</i> base on each <i>raha</i> .
Interiors Movable Collections	:	Plain Nil
* Any Other (specify)	-	The temple is <i>pancharatha</i> on plan and panchangabada in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction 11. Condition Assessment		<i>Rekha vimana</i> of <i>Kalingan</i> order. Ashlar dry masonry Sandstone is used for the construction of the temple.
In General Good / Fair Sign of Deterioration	:	Good

Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation due to the renovation work.

12. Threats to the Property

	✓	Natural
		Negligence
		Vandalism
	✓	Urban Pressures
x x x x x x x x x x x x x x x x x x x	ххх	* * * * * * * * * * * * * * * * * * * *

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.
- 3.
- 4.

14. Photographs: 13 nos

	(attach list as in page 6, in case of multiple photographs)
Photo Reference	:
CAPTION	:

15. Audio / Video

		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	:	

16. Maps/Plans/Drawings

17. Listers			
NAME :	Jaya Shankar Naik	NAME :	
18. Reviewer	S		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	