

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 259

| SECTION I: IDENTIFICATION | | |
|---|--|--|
| 1. Name | | |
| Present Past Other Name (if any): 2. Location | Mangaladevi Temple (Temple No 104), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda | |
| LONGITUDE 85°50'05" E | LATITUDE 20 ⁰ 14 ² 26 N ELEVATION 70 ft. | |
| Address | : Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002 | |
| Approach | : The temple is situated on the north of the Grand Lingaraja within the complex in Old Town, Bhubaneswar. | |
| 3. Property Type | | |
| Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building | Religious structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum | |
| Engineering structure Bridge Tunnel Other engineering structure | Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a pidha vimana of Kalingan order. | |

4. Property Use ABANDONED / IN USE: In use Living temple, the presiding deity is an eight-armed Present goddess seated in padmasana holding trisula, nagapasa, danda, mala (rosary), etc and mount lion is in the pedestal. The deity is locally known as Mangaladevi. Worshipped Past 5. Age (Source) PERIOD Ganga rule 15th century AD YEARS First half of the 15th century AD. **Precise date of Construction** Completion Subsequent changes The *gandi* and *mastaka* is lime plastered later on. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of : Protected monument of Archaeological Survey of India Archaeology India / State Department / Any Other (Please specify) Private Lingaraja Temple Trust Board maintains the rituals of the temple. Endowment Department, Government of Orissa Any other (Please specify) manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. **Phone** 0674-2558170 7. Association WITH EVENTS In History In Rituals Mangala Osa, Durgapurja, etc are performed here. In Building Construction Any other (specify) WITH PERSONS Patron Archeological Survey of India and Endowment Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 8. Statement of Significance Architectural Architectural Archaeological Historical Religious

| Any other (specify) : | On architectural ground and iconographical feature of the presiding deity, the temple can be assigned to the late Ganga rule i.e. about the first half of the 15 th century AD. |
|--|---|
| SEC | TION II: DESCRIPTION |
| 9. Physical Description and Decora | ative Features |
| • Context Urban / Rural Setting : Surroundings | * Drawings (Attach extra sheet if necessary): No Urban setting |
| | Stand in Isolation Complex Integral part of a Landscape / Street / Complex : |
| • Quantification Area Dimension (L x B x H) : | 6.00 mtrs x 5.15 mtrs x 7.30 mtrs (approximate height) (m / cm/ feet / inch) |
| Number of Blocks Number of Storys | One N.A. |
| • Spatial Organization Orientation : | Facing towards south. |
| Plan : Allocation of Spaces : | The <i>vimana</i> is square on plan. 158.49 mtrs x 141.73 mtrs in length and breadth respectively. |
| ARCHITECTURAL STYLE Ornamentation | |
| Exteriors : | Devoid of any decorations except a bell shaped member (<i>ghanta</i>) on each face of the temple. The doorjambs have the remains of <i>khakharamundi</i> at the base. |
| Interiors : | Plain |
| Movable Collections : * Any Other (specify) : | Nil The temple is <i>pancharatha</i> on plan and panchangabada in elevation. |
| 10. Construction Technology | |
| Structural System : Building Techniques : Material of Construction : | Pidha vimana of Kalingan order. Ashlar dry masonry Laterite is used for the temple and sandstone for the presiding deity. |
| 11. Condition Assessment | |
| In General Good / Fair Sign of Det Serious De | erioration |

| | Danger of Disappearance |
|--------------------------|--|
| In Brief (Attach | extra sheet if necessary): |
| The temple is in | a good state of preservation due to the renovation work. |
| 12. Threats to | he Property |
| x | Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x |
| | SECTION III: REFERENCES |
| 13. Reference | Sources (published and unpublished textual details) |
| Delhi. | ra, 2008, <i>The Lingaraja Temple of Bhubaneswar</i> , <i>Art and Cultural Legacy</i> , New ra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi. |
| 14. Photograpi | |
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference CAPTION | e : : |
| 15. Audio / Vid | |
| | (related to rituals / performance / festivals etc.) |
| Reference DESCRIPTION | : : |
| 16. Maps/Plans | :/Drawings |
| | |
| 17. Listers | |
| NAME : | Jaya Shankar Naik NAME : |
| 18. Reviewers | |
| NAME : COMMENTS | Dr. S. Pradhan NAME : COMMENTS : |