

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 263

	SECTION I: IDENTIFICATION
1. Name	
Present Past Other Name (if any): 2. Location	 Patalesvara Siva Temple (Temple No 21), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
LONGITUDE 85°50'05" E	LATITUDE 20°14'26" N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple is situated on the south of the Grand Lingaraja within the complex in Old Town, Bhubaneswar.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a rekha vimana of Kalingan order.

4. Property Use ABANDONED / IN USE: In use **Present** Living temple, the presiding deity is a Sivalinga within a circular yonipitha. **Past** Worshipped 5. Age (Source) **PERIOD** Ganga rule 14th century AD. **YEARS Precise date of Construction** Completion Subsequent changes The temple was renovated and conserved by Archaeological Survey of India. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple Protected monument of Archaeological Survey of India **Public**: Archaeological Survey of: State Archaeology India Department / Any Other (Please specify) **Private** Lingaraja Temple Trust Board maintains the rituals of the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name **Address** Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674-2558170 **Phone** 7. Association WITH EVENTS In History Sivaratri, Kartika Purnima, Sankranti, etc. In Rituals In Building Construction Any other (specify) Engagements, thread ceremony, etc. WITH PERSONS Patron Archeological Survey of India and Endowment Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 8. Statement of Significance Architectural Architectural

Arc	nitecturai	v	Architectural
Arc	haeological		
His	torical		
Rel	igious	\checkmark	Religious
Any	other (specify)	:	On architectural ground and iconographical feature of the <i>parsvadevata</i> images, the temple can be assigned to the late Ganga rule.

SECTION II: DESCRIPTION

9. Physical Description and Dec	orat	tive Features			
 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) : No Urban setting			
		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex		
 Quantification 					
Area Dimension (LxBxH)	:	6.80 mtrs x 5.10 mtrs x 11.50 height)			
Number of Blocks		One	(m / cm/ feet / inch)		
Number of Storys	:	N.A.			
Spatial Organization					
Orientation	:	Facing towards east.			
Plan	:	The <i>vimana</i> is square on plan.			
Allocation of Spaces		158.49 mtrs x 141.73 mtrs in length respectively.	and breadth		
ARCHITECTURAL STYLE					
 Ornamentation 					
Exteriors	:	Decorated with projecting lion on each raha and the frontal raha has an architectural design with five miniature temples; among these, the middle one is khakharamundis and the other four are rekha styled Deulacharinis are found in the middle of the beath above each raha to support the amalaka sila. The talagarbhika is in rekhamundi design.			
Interiors	:	Plain			
Movable Collections * Any Other (specify)	:	Nil The temple is <i>pancharatha</i> <i>panchangabada</i> in elevation.	on plan and		
10. Construction Technology					
Structural System Building Techniques Material of Construction 11. Condition Assessment	: :	Rekha vimana of Kalingan order. Ashlar dry masonry Sandstone is used for the construction of the temple.			
In General Good / Fair	: Deta	Good			
Sign of Deterioration Serious Deterioration					
		isappearance			

Except the <i>parsvadevata</i> image Ganesa, the temple is in a good state of preservation.
12. Threats to the Property
✓ Natural Negligence Vandalism ✓ Urban Pressures x x x x x x x x x x x x x x x x x x x
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
1. K. S. Behera, 2008, <i>The Lingaraja Temple of Bhubaneswar</i> , <i>Art and Cultural Legacy</i> , New
Delhi. 2. Debala Mitra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi.
14. Photographs: 12 nos
(attach list as in page 6, in case of multiple photographs) Photo Reference : CAPTION : 15. Audio / Video
(related to rituals / performance / festivals etc.)
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME : Jaya Shankar Naik NAME : 18. Reviewers
NAME : Dr. S. Pradhan NAME : COMMENTS :

In Brief (Attach extra sheet if necessary):