

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 266

SECTION I: IDENTIFICATION				
1. Name				
Present Past Other Name (if any): 2. Location	 Rama Sita Temple (Temple No - 65), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda 			
Z. Loodion				
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 N ELEVATION 70 ft			
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002			
Approach	: The temple, on the west of Grand Lingaraja and at a short distance to the north of Visvakarma temple within the complex is situated in Old Town, Bhubaneswar.			
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave			

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is a Sivalinga within a circular yonipitha; in addition, there are metal images of Rama and Sita. **Past** Worshipped. 5. Age (Source) **PERIOD** Somavamsi rule 12th century AD YEARS First half of the 12th century AD **Precise date of Construction** Completion Subsequent changes Renovated and conserved by Archaeological Survey of India. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of : Protected monument of Archaeological Survey of State Archaeology India. 1 Department / Any Other (Please specify) Private Lingaraja Temple Trust Board maintains the rituals of the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name **Address** Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674-2558170 **Phone** 7. Association • WITH EVENTS In History Sivaratri, Ramanavami, Dolapurnima, etc. In Rituals In Building Construction Thread ceremony is held here. Any other (specify) WITH PERSONS Patron Archeological Survey of India and Endowment Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 8. Statement of Significance

Architectural

Architectural

Archaeological Historical Religious

Any other (specify)

On the basis of architectural features and parsvadevata images the temple can be dated to the late Somavamsi rule.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) No Urban setting	
Surroundings		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :	
• Quantification Area Dimension (L x B x H)	:	(m / om/ foot / inch)	
Number of Blocks Number of Storys	:	One N.A. (m / cm/ feet / inch)	
 Spatial Organization Orientation Plan Allocation of Spaces 	: : :	Facing towards east. The <i>vimana</i> is square on plan. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.	
ARCHITECTURAL STYLEOrnamentationExteriors	:	Decorated with a miniature <i>pidhamundi</i> flanked by a pair of <i>rekhamundis</i> on the frontal <i>raha</i> and <i>udyotasimha</i> on each <i>raha</i> .	
Interiors Movable Collections * Any Other (specify)	:	Plain Nil The temple is <i>pancharatha</i> on plan and <i>triangabada</i> elevation.	
10. Construction Technology			
Structural System Building Techniques Material of Construction	:	Rekha vimana of Kalingan order. Ashlar dry masonry Sandstone is used for the construction of the temple.	
11. Condition Assessment			
In General Good / Fair ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Fair	

In Brief (Attach extra sheet if necessary):

The exterior su	rface is weathered and	minor cracks are noticed at places in the temple.	
12. Threats to	the Property		
	✓ ✓	Natural Negligence Vandalism Urban Pressures	
SECTION III: REFERENCES			
13. Reference	Sources (published and	d unpublished textual details)	
Delhi.	era, 2008, <i>The Lingaraja</i> tra, 1961, <i>Bhubaneswar</i>	Temple of Bhubaneswar, Art and Cultural Legacy, New	
Z. Debala ivii	ila, 1901, briubarieswar	, ASI, New Delili.	
14. Photograp	hs: 12 nos		
		(attach list as in page 6, in case of multiple photographs)	
Photo Reference CAPTION	ce :		
15. Audio / Vid	deo		
		(related to rituals / performance / festivals etc.)	
Reference DESCRIPTION	: I :		
16. Maps/Plans/Drawings			
17. Listers			
NAME :	Jaya Shankar Naik	NAME :	
18. Reviewers			
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :	