

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 267

	SECTION I : IDENTIFICATION
1. Name	<u></u>
Present Past Other Name (if any): 2. Location	 Ruined Siva Temple (Temple No 5), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple is situated in the north-east of the Grand Lingaraja within the complex in Old Town, Bhubaneswar.
3. Property Type	
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a rekha vimana of Kalingan order.

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is a Sivalinga upon a yonipitha. Past Worshipped 5. Age (Source) PERIOD Ganga rule 13th century AD YEARS Late 13th century AD **Precise date of Construction** Completion Subsequent changes Renovated and conserved by Archaeological Survey of India. **Destruction / Demolition** Now the crowning elements are missing. 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple Protected monument of Archaeological Survey of India **Public**: Archaeological Survey of : / State Archaeology Department / Any Other (Please specify) **Private** Lingaraja Temple Trust Board maintains the rituals of the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name **Address** Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. **Phone** 0674-2558170 7. Association WITH EVENTS

In History : --

In Rituals : Sivaratri, Kartika Purnima, Sankranti, etc.

In Building Construction : -

Any other (specify) : Thread ceremony, engagements, etc.

WITH PERSONS

Patron : Archeological Survey of India and Endowment

Department, Government of Orissa.

Architect / Engineer : ---

Any other (specify) : Lingaraja Temple Trust Board

8. Statement of Significance		
Architectural	✓	Architectural
Archaeological		
Historical		
Religious	✓	Religious
Any other (specify)	:	

On architectural ground, the temple can be assigned to the Gangavamsi rule i.e. about the late 13th century A.D.

SECTION II: DESCRIPTION				
9. Physical Description and Deco	<u>orat</u>	ive Features		
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Urban setting		
Surroundings		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :		
 Quantification Area Dimension (L x B x H) 	:	4.60 mtrs x 3.75 mtrs x 7.50 mtrs (existing height) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	One N.A.		
 Spatial Organization Orientation Plan Allocation of Spaces 	:	Facing towards east. It consists of a square <i>vimana</i> that stands over a platform of 0.35 mtrs in height. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.		
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	:	Decorated with architectural motifs like khakharamundis in the talajanga, pidhamundis in the uparajanga, miniature rekha deula in the frontal raha and udyotasimha in all rahas. The doorjambs have three sakha - lata, nara, puspa from interior to exterior and khakharamundi at the base.		
Interiors Movable Collections * Any Other (specify)	: :	Plain The temple is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation.		
10. Construction Technology		panchangabada in elevation.		
Structural System Building Techniques Material of Construction 11. Condition Assessment	: : :	Rekha vimana of Kalingan order. Ashlar dry masonry Sandstone is used both for the temple and the pista.		
In General Good / Fair ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Fair		

In Brief (Attach extra sheet if necessary):
Due to the ravages of nature and time most of the decorative elements are eroded and weathered.
12. Threats to the Property
✓ Natural Negligence Vandalism ✓ Urban Pressures SECTION III: REFERENCES
SECTION III. REI ERENGES
13. Reference Sources (published and unpublished textual details)
 K. S. Behera, 2008, The Lingaraja Temple of Bhubaneswar, Art and Cultural Legacy, New Delhi. Debala Mitra, 1961, Bhubaneswar, ASI, New Delhi. 3.
14. Photographs: 06 nos
(attach list as in page 6, in case of multiple photographs)
Photo Reference : CAPTION :
15. Audio / Video
(related to rituals / performance / festivals etc.)
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers

NAME:

NAME :

COMMENTS:

NAME:

NAME :

18. Reviewers

COMMENTS

Jaya Shankar Naik

Dr. S. Pradhan