INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR – 268

	SECTION I : IDENTIFICATION	
1. Name		
Present Past Other Name (if any):	 Ruined Siva Temple (Temple No - 6), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda 	
2. Location		
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 [°] N ELEVATION 70 ft.	
Address	 Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002 	
Approach	: The temple, on the north-eastern corner of Grand Lingaraja temple complex is situated in Old Town, Bhubaneswar.	
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Other Structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum Tomb, Mausoleum	
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public squareThe temple has a rekha vimana of Kalingan style.Park or gardenVimana of Kalingan style.GraveyardBaolis, WellTankCave	

		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a Sivalinga withi a circular <i>yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Ganga rule
YEARS	÷	13 th century AD
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	Renovated and conserved by Archaeological Survey of India.
Destruction / Demolition	:	Now the crowing element of the temple is missing.
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Archaeological Survey of India.
Private	:	Lingaraja Temple Trust Board maintains the rituals the temple.
Any other (Please specify)	:	Endowment Department, Government of Oriss manages the property of the temple.
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Circle
		153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	:	0674- 2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Sankranti, Kartika Purnima, etc.
In Building Construction	:	
Any other (specify) WITH PERSONS 	:	Thread ceremony, engagements, etc.
Patron	:	Archeological Survey of India and Endowme Department, Government of Orissa.
Architect / Engineer	:	
Any other (specify)	:	Lingaraja Temple Trust Board
8. Statement of Significance		
Architectural	\checkmark	Architectural
Archaeological		
Historical		
Religious		
Any other (specify)	:	

On architectural ground, the temple can be dated to the late 13^{th} century A.D. i.e. the Gangavamsi rule in Orissa.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) No Urban setting
Surroundings		Stand in Isolation Integral part of a Landscape Complex / Street / Complex :
• Quantification Area Dimension (L x B x H)	:	5.60 mtrs x 4.15 mtrs x 8.00 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks Number of Storys	:	One N.A.
Spatial Organization Orientation Plan Allocation of Spaces	: : :	Facing towards east. Consists of a square <i>vimana</i> that stands over a platform of 0.35 mtrs in height. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE • Ornamentation Exteriors	:	The temple is decorated with architectural motifs like
Interiors Movable Collections * Any Other (specify)	:	khakharamundis and pidhamundis in the lower and upper jangha respectively, miniature angasikharas surmounted by a gajakranta motif on the frontal raha and pidhamundi niches at the base of the doorjambs. Plain Plain The temple is pancharatha on plan and panchangabada in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	The temple has <i>rekha vimana</i> of <i>Kalingan</i> order. Ashlar dry masonry Sandstone is used both for the temple construction and the <i>pista</i> .
11. Condition Assessment		
In GeneralGood / Fair✓Sign of Deterioration✓Serious Deterioration	:	Good

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Due to renovation work the temple is in a good state of preservation.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.

14. Photographs: 04 nos

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	

15. Audio / Video

		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	:	

16. Maps/Plans/Drawings

17. Listers

NAME : Jaarya Shank Naik NAME : 18. Reviewers

NAME : Dr. S. Pradhan COMMENTS NAME : COMMENTS :