INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: OR / KDA / BSR - 271

	SECTION I : IDENTIFICATION
1. Name	
Present Past	<ul> <li>Saksi- Sankara Temple (Temple No 118), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda</li> <li></li> </ul>
Other Name (if any):	:
2. Location	
LONGITUDE 85°50'05" E	<b>LATITUDE</b> $20^{\circ}14^{\circ}26^{\circ}$ N <b>ELEVATION</b> 70 ft.
Address	<ul> <li>Village (village code)</li> <li>Post : Old Town</li> <li>Tehsil: Bhubaneswar</li> <li>State : Orissa</li> <li>Lingaraja Temple Complex</li> <li>Via: Old Town, Bhubaneswar</li> <li>District: Khurda</li> <li>PIN: 751002</li> </ul>
Approach	: The temple, on the east of the Grand Lingaraja temple within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public buildings         Residential building	Religious structures       Other Structures         Image: Temple       Image: Wall         Mosque       Gateway         Minar       Pillar         Church       Others (specify)         Monastery       Stupa         Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public square Park or gardenThe temple is of pidha order of Kalingan style.Graveyard Baolis, Well Tank CaveTank 

		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a Sivalinga within a circular <i>yonipitha</i> made of black chlorite.
Past	:	Worshipped
5. Age (Source)		
REDIOD		Survoyamai Cajanati rula
PERIOD YEARS	•	Suryavamsi Gajapati rule 16 <sup>th</sup> century AD
Precise date of Construction	:	Second half of the 16 <sup>th</sup> century AD
Completion	÷	
Subsequent changes	:	The pabhaga of the temple is half buried and the
		temple is renovated and conserved by Archaeological Survey of India.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
•		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of	:	Protected monument of Archaeological Survey of
India / State Archaeology		India.
Department / Any Other (Please		
specify)		
Private	:	Lingaraja Temple Trust Board maintains the rituals of
Any other (Please specify)		the temple. Endowment Department, Government of Orissa
Any other (Please specify)	•	manages the property of the temple.
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Circle,
		153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	:	0674- 2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Sankranti, Ekadasi, Kartika Purnima, etc held
In Building Construction		here.
Any other (specify)	:	 Thread ceremony held here.
WITH PERSONS	•	
Patron	:	Archeological Survey of India and Endowment
		Department, Government of Orissa.
Architect / Engineer	:	
Any other (specify)	:	Lingaraja Temple Trust Board
8. Statement of Significance		
Architectural	✓	Architectural
Archaeological		
Historical	,	Polizious
Religious	✓	Religious
Any other (specify)	-	

On architectural ground and the existing *parsvadevata* images on the south, the temple can be assigned to the Suryavamsi Gajapati rule. **SECTION II: DESCRIPTION** 

#### 9. Physical Description and Decorative Features

Context     Urban / Rural Setting     Surroundings		* Drawings (Attach extra sheet if necessary) : No Urban setting	
Surroundings		Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :	
• <b>Quantification</b> Area Dimension ( L x B x H)	:	6.50 mtrs x 4.75 mtrs x 5.12 mtrs (approximate height)	
Number of Blocks Number of Storys	:	( <b>m</b> / cm/ feet / inch) N.A.	
• <b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	Facing towards east. The <i>vimana</i> is square on plan. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.	
ARCHITECTURAL STYLE <ul> <li>Ornamentation</li> </ul>			
Exteriors	:	Devoid of any artistic decorations on the temple except the <i>pidhamundi</i> niches housing the <i>dvarapala</i> figures & river goddess at the base of the doorjambs and have three <i>sakhas- lata, lata</i> and <i>puspa</i> from interior to exterior, Gaja-Laxmi in the lintel & <i>navagraha</i> panel in the architrave.	
Interiors	:	Plain	
Movable Collections * Any Other (specify)	:	Nil The temple is <i>triangabada</i> in elevation and <i>pancharatha</i> on plan.	
10. Construction Technology			
Structural System Building Techniques Material of Construction	:	<i>Pidha vimana</i> of <i>Kalingan</i> order. Ashlar dry masonry Sandstone is used for the construction of the temple and traces of lime plaster is found both interior & exterior surface.	
11. Condition Assessment			
In GeneralGood / Fair✓Sign of Deterioration✓Serious Deterioration	:	Fair	

Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Minor cracks are noticed in the exterior surface of the temple.

# 12. Threats to the Property

12. Inreats to the Property				
<ul> <li>✓ Natural</li> <li>Negligence</li> <li>Vandalism</li> <li>✓ Urban Pressures</li> <li>x x x x x x x x x x x x x x x x x x x</li></ul>				
SECTION III: REFERENCES				
13. Reference Sources (published and unpublished textual details)				
1. K. S. Behera, 2008, <i>The Lingaraja Temple of Bhubaneswar</i> , <i>Art and Cultural Legacy</i> , New Delhi.				
<ol> <li>Debala Mitra, 1961, <i>Bhubaneswar</i>, ASI, New Delhi.</li> <li>4.</li> </ol>				
14. Photographs: 10 nos				
(attach list as in page 6, in case of multiple photographs)				
Photo Reference : CAPTION :				
15. Audio / Video				
(related to rituals / performance / festivals etc.)				
Reference : DESCRIPTION :				
16. Maps/Plans/Drawings				
17. Listers				
NAME : Jaya Shankar Naik NAME :				
18. Reviewers				

NAME : Dr. S. Pradhan COMMENTS

NAME : COMMENTS :